●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation

Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark

※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			room lamp Recommended《CSPplate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
IQ	2008.11-2016.4	KGJ.NGK10	※LED	－	－	※LED	－	－	－	－	－	－	※Not applicable due to LED lamp
Isis	2004.9-2007.4	ANM.ZNM1#	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	3 lights on the front
	2007.5-2009.9		T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	3 lights on the front
	2009.9-2012.6	ZGM1#	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	3 lights on the front
	2012.6-2015.5		T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	T10 2ケ (P404 ×2)	3 lights on the front
	2015.5-2017.10		T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P404 ×1)	－	－	T10 2ケ (P404 ×2)	3 lights on the front
aqua including crossover	2011.12-2014.11	NHP10.10H	T10 2ケ (P406/407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	※1 T10 side 1ケ (P145 ×1)	－	－	－	Early period ※1 The luggage lamp (P145) comes in 2 pieces, so please use one as a spare.
	2014.12-2021.6		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P404 ×1)	－	－	－	
			CSPcompleteキット P06TC										Applicable areas: front, center, luggage
	2021.7-	MXPK1#	※1 LED	T10 1ケ (P404 ×1)	－	※1 LED	※2 T10 1ケ (P145 ×1) (P141 ×1)	－	T10 1ケ (P404 ×1)	－	－	T10 2ケ (P404 ×2)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
Avalon	1995.5-1997.9	MCX10	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	－	G14 2ケ (No compatible products)	－	－	－	－	
	1997.10-1999.6		G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	G14 2ケ (No compatible products)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			room lamp Recommended《CSPplate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
avensis	2003.10-2006.6	AZT25# AZT25#W	T10×37 3ケ (No compatible products)	T10×37 2ケ (No compatible products)	T10×37 2ケ (No compatible products)	T10×37 3ケ (No compatible products)	T10×37 2ケ (No compatible products)	T10×37 2ケ (No compatible products)	－	－	－	－	
	2006.7-2008.8		T10×37 3ケ (No compatible products)	T10×37 2ケ (No compatible products)	T10×37 2ケ (No compatible products)	T10×37 3ケ (No compatible products)	T10×37 2ケ (No compatible products)	T10×37 2ケ (No compatible products)	－	－	－	－	
	2011.9-2015.9	ZRT272W	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	T10×37 1ケ (No compatible products)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 2ケ (P404 ×2)	
	2015.10-2018.4		T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	T10×37 1ケ (No compatible products)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 2ケ (P404 ×2)	
Arion	2001.12-2004.11	AZT24# NZT24# ZZT24#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No applicable products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2004.12-2007.5		G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No applicable products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2007.6-2010.3	ZRT26# NZT26#	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	
	2010.4-2016.5		T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	
	2012.12-2021.3		T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	T10 2ケ (P404 ×2)	
Aristo	1997.8-2000.6	JZS16#	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	－	T10×31 1ケ (P143 ×1) G14 2ケ (No applicable products)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	
	2000.7-2004.12		T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	－	T10×31 1ケ (P143 ×1) G14 2ケ (No applicable products)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA

Car model	model year	Model	room lamp Recommended《CSPplate type》 front	room lamp center	room lamp rear	room lamp《valve type》 front	room lamp center	room lamp rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
Altezza	1998.10-2005.7	GXE1# SXE1#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	※G14 2ケ (No applicable products)	T10×31 1ケ (P1431 ×1)	－	－	－	－	－	
Altezza Gita	2001.7-2003.7	JCE1#W GXE1#W	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	※G14 2ケ (No applicable products)	T10×31 1ケ (P1431 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
	2003.8-2005.7		G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	※G14 2ケ (No applicable products)	T10×31 1ケ (P1431 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
Alphard	2002.5-2005.3	ANH1# MNH1#	G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	T10 2ケ (P141 ×1)	－	－	
			G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	T10 2ケ (P141 ×1)	－	－	
	2005.4-2008.4		G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	T10 2ケ (P141 ×1)	－	－	
Alphard Vellfire	2008.5-2013.12	ANH2# GGH2#	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	T10 2ケ (P141 ×1)	－	T10 2ケ (P404 ×2)	
	2013.12-2015.1		T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	T10 2ケ (P404 ×2)	－	T10 2ケ (P404 ×2)	
Alphard Vellfire ※Continue to next page	2015.1-2017.12	AGH.GGH3#	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P404 ×2)	T10 2ケ (P404 ×2)	－	T10 2ケ (P404 ×2)	Not applicable to standard room LED cars
			CSPcompleteKIT P09TC										Car with door courtesy Applicable areas: front, 2nd row, 3rd row, luggage, door, vanity Not applicable to standard room LED cars
			CSPcompleteKIT P09TC-2										No door courtesy Applicable areas: front, 2nd row, 3rd row, luggage, vanity Not applicable to standard room LED cars

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			room lamp Recommended《CSPplate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
Alphard Vellfire	2018.1-R.5.6	AGH.GGH3#	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P404 ×2)	T10 2ケ (P404 ×2)	－	T10 2ケ (P404 ×2)	Not applicable to standard room LED cars
			CSPcompleteKIT P09TC										Car with door courtesy Applicable areas: front, 2nd row, 3rd row, luggage, door, vanity Not applicable to standard room LED cars
			CSPcompleteKIT P09TC-2										No door courtesy Applicable areas: front, 2nd row, 3rd row, luggage, vanity Not applicable to standard room LED cars
	2023.7-	AAHH4#W AGH40W	※LED	※LED	※LED	※LED	※LED	※LED	－	－	－	－	※The interior is all LED and cannot be replaced.
alphard hybrid	2003.7-2008.4	ATH1#	G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	T10 2ケ (P141 ×1)	－	－	
alphard hybrid Vellfire hybrid ※Continue to next page	2011.11-2013.12	ATH20W	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	T10 2ケ (P141 ×1)	－	T10 2ケ (P404 ×2)	
	2013.12-2015.1		T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	T10 2ケ (P404 ×2)	－	T10 2ケ (P404 ×2)	
	2015.1-2017.12	AYH30	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P402 ×2)	T10 2ケ (P402 ×2)	T10 2ケ (P402 ×2)	T10 2ケ (P404 ×2)	T10 2ケ (P404 ×2)	－	T10 2ケ (P404 ×2)	Not applicable to standard room LED cars
			CSPcompleteKIT P09TC										Car with door courtesy Applicable areas: front, 2nd row, 3rd row, luggage, door, vanity Not applicable to standard room LED cars
			CSPcompleteKIT P09TC-2										No door courtesy Applicable areas: front, 2nd row, 3rd row, luggage, vanity Not applicable to standard room LED cars

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
alphard hybrid Vellfire hybrid	2018.1-2023.6	AYH30	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P402 ×2)	T10 2ケ (P402 ×2)	T10 2ケ (P402 ×2)	T10 2ケ (P404 ×2)	T10 2ケ (P404 ×2)	－	T10 2ケ (P404 ×2)	Not applicable to standard room LED cars
			CSPcompleteKIT P09TC										Car with door courtesy Applicable areas: front, 2nd row, 3rd row, luggage, door, vanity Not applicable to standard room LED cars
			CSPcompleteKIT P09TC-2										No door courtesy Applicable areas: front, 2nd row, 3rd row, luggage, vanity Not applicable to standard room LED cars
alex	2001.1-2002.8	NZE12# ZZE12#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
	2002.9-2004.3		G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
			G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
	2004.4-2006.9		G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
			G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
ist ※Continue to next page	2002.5-2005.4	NCP6#	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P1431 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
			T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P1431 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
			T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P1431 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
ist	2005.5-2006.12	NCP6#	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P1431 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2006.12-2007.7	NCP6#	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2007.7-2016.5	NCP11# ZSP110	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	T10×37 1ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×37 1ケ (No compatible products)	－	－	－	－	
ipsum	2001.5-2009.12	ACM2#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
vanguard	2007.8-2010.1	ACA33W GSA33W ACA38W	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	※T10 2ケ (P404 ×2)	※Confirm the vanity is installed on the vehicle side.
	2010.1-2013.11	ACA3#W GSA33W	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	※T10 2ケ (P404 ×2)	※Confirm the vanity is installed on the vehicle side.
WILL Cipher	2002.10-2005.7	NCP7#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
WILL Vi	2000.1-2001.12	NCP1#	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
WILL VS	2001.4-2004.4	NZE12# ZZE12#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P401 ×1)	－	－	－	－	－	
WISH ※Continue to next page	2003.1-2009.3	ANE1# ZNE1#	G14 2ケ (No compatible products)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
	2009.4-2012.3	ZGE2#W ZGE2#G	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			room lamp Recommended《CSPplate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
WISH	2012.4-2017.10	ZGE2#W ZGE2#G	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
Vitz	1999.1-2005.1	NCP1# SCP1#	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2001.12-2002.11		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
			T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
	2002.12-2005.1		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
	2005.2-2006.1	KSP9# NCP9# SCP9#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2005.2-2006.1		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2006.1-2007.7		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2006.1-2007.7		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Vitz ※Continue to next page	2007.8-2010.12	KSP9# NCP9# SCP9#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×37 1ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×37 1ケ (No compatible products)	－	－	－	－	
	2007.8-2008.8		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×37 1ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×37 1ケ (No compatible products)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
Vitz	2008.9-2010.12	NSP13# KSP130 NCP131 NHP130	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×37 1ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×37 1ケ (No compatible products)	－	－	－	－	
	2010.12-2014.3		T10 2ケ (P406/407 ×2) ※1(P04TC-2 ×1)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T8×29 1ケ (P143 ×1)	－	－	※2 T10 side 2ケ (P404 ×2)	※1 P04TC-2 is the same as P406 2 pieces. ※2 Vanity is standard only on Jewela
	2014.4-2016.12		T10 2ケ (P406/407 ×2) ※1(P04TC-2 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P404 ×1)	－	－	※2 T10 side 2ケ (P404 ×2)	※1 P04TC-2 is the same as P406 2 pieces. ※2 Depending on the grade, it may or may not be set. P19TC can also be installed on 2014.4-2016.12 model cars. However, there are vehicles without vanity. However, there are vehicles without vanity.
	2017.1-2020.3		T10 2ケ (P406/407 ×2) ※1(P04TC-2 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P404 ×1)	－	－	T10 side 2ケ (P404 ×2)	※1 P04TC-2 is the same as P406 2 pieces.
			CSPcompleteキット P19TC										Applicable areas: front, center, luggage、vanity
Verossa	2001.7-2004.4	GX110# JZX11#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Voxy ※Continue to next page	2001.11-2007.5	AZR6#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	
	2007.6-2014.1	ZRR70W,G ZRR75W,G	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	※1 T10 side 2ケ (P404 ×2)	1 center light type, option (with large dome light) not available, rear compatible with all cars ※1 Confirm the vanity is installed on the vehicle side.
			T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1) ※1 T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	※2 T10 side 2ケ (P404 ×2)	Center 3 light type, option (with large dome light) not available, rear compatible with all cars *1 Reflector must be removed from center T10 part. ※2 Confirm the vanity is installed on the vehicle side.
	2014.1-2022.1	ZRR8# ZWR8#	T10 2ケ (P406/407 ×2) ※1(P04TC-2 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	T10 side 2ケ (P404 ×2)	standard car ※1 P04TC-2 is the same as P406 2 pieces.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
Voxy	2015.1-2022.1	ZRR8# ZWR8#	T10 2ケ (P406/407 ×2) ※1(P04TC-2 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	※2 T10 side 1ケ (P404 ×1)	－	－	T10 side 2ケ (P404 ×2)	welcab car ※1 P04TC-2 is the same as P406 2 pieces. ※2 Standard equipment only on Welcab (welfare vehicles)
	2014.1-2022.1		CSPcompleteKIT P05TC										Applicable areas: front, center, rear, vanity *Excluding welcab car.
	2022.1-	ZWR90.95W MZRA90.95W	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	－	－	－	※1 All room lamps are standard LED
Volz	2002.8-2004.4	ZZE13#	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
esquire	2014.1-2021.12	ZRR8# ZWR8#	T10 2ケ (P406/407 ×2) ※1(P04TC-2 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	T10 side 2ケ (P404 ×2)	standard car ※1 P04TC-2 is the same as P406 2 pieces.
	2015.1-2021.12		T10 2ケ (P406/407 ×2) ※1(P04TC-2 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	※2 T10 side 1ケ (P404 ×1)	－	－	T10 side 2ケ (P404 ×2)	welcab car ※1 P04TC-2 is the same as P406 2 pieces. ※2 Standard equipment only on Welcab (welfare vehicles)
	2014.1-2021.12		CSPcompleteKIT P05TC										Applicable areas: front, center, rear, vanity *Excluding welcab car.
Estima	1990.5-1997.12	TCR1# TCR2#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	T8×29 1ケ (No compatible products)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (No compatible products)	－	－	－	－	
	1998.1-1999.12		G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	T8×29 1ケ (No compatible products)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (No compatible products)	－	－	－	－	
	2000.1-2005.12	ACR.MCR3# ACR.MCR4#	G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	
	2006.1-2016.5	ACR5# GSR5#	※1 T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	※2 T10 side 2ケ (P145 ×1) (P141 ×1)	－	※2 T10 2ケ (P404 ×2)	※1 It is necessary to remove the reflector when installing the plate. ※2 front door/Confirm the vanity is installed on the vehicle side.
	2016.6-2020.3 2019.10生産終了		※1 T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 1ケ (P404 ×1)	※2 T10 side 2ケ (P145 ×1) (P141 ×1)	－	※2 T10 2ケ (P404 ×2)	※1 It is necessary to remove the reflector when installing the plate. ※2 front door/Confirm the vanity is installed on the vehicle side.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			room lamp Recommended《CSPplate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
Estima Hybrid	2001.6-2003.7	AHR10W	G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	
	2003.8-2006.5		G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	
	2006.6-2016.5	AHR20W	※1 T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	※2 T10 side 2ケ (P145 ×1) (P141 ×1)	－	※2 T10 2ケ (P404 ×2)	※1 It is necessary to remove the reflector when installing the plate. ※2 front door/Confirm the vanity is installed on the vehicle side.
	2016.6-2020.3 2019.10生産終了	AHR20W	※1 T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 1ケ (P404 ×1)	※2 T10 side 2ケ (P145 ×1) (P141 ×1)	－	※2 T10 2ケ (P404 ×2)	※1 It is necessary to remove the reflector when installing the plate. ※2 front door/Confirm the vanity is installed on the vehicle side.
FJ cruiser	2010.12-2018.1	GSJ15W	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
MR-S	1999.10-2002.7	ZZW3#	G14 2ケ (No compatible products)	－	－	G14 2ケ (No compatible products)	－	－	－	－	－	－	
	2002.8-2007.7		T10 1ケ (P406/407 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
Auris	2006.10-2009.10	ZRE15#H NZE15#H	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2009.10-2012.5	ZRE15#H NZE15#H	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2012.6-2015.3	NEZ18# ZRE18#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	T10×31 2ケ (P408/409 ×2) (P143 ×2)	
	2015.4-2018.3	NRE18# NEZ18# ZRE18# ZWE18#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	※T8×29 1ケ (P143 ×1) For T10 (P404 ×1)	－	－	※T10×31 2ケ (P408/409 ×2) (P143 ×2) For T10 (P404 ×2)	※Luggage/vanity may be T10 specification depending on model year and grade.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			room lamp Recommended《CSPplate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
camry	2001.9-2004.6	ACV3#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2004.7-2005.12		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2006.1-2011.9	ACV4#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2011.9-2014.7	AVV50	T10 2ケ (P406/407 ×2)	※1 T10 2ケ (No applicable products) Valve type recommended	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	T10 1ケ (P406/407 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 side 2ケ (P404 ×2)	※1The valve type is recommended for the center because the valve enters diagonally.
	2014.8-2017.6		T10 2ケ (P406/407 ×2)	※1 T10 2ケ (No applicable products) Valve type recommended	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	T10 1ケ (P406/407 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 side 2ケ (P404 ×2)	※1The valve type is recommended for the center because the valve enters diagonally.
	2017.7-	AXVH70.75	※LED	※LED	－	※LED	※LED	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	WS.Ggrade ※Not applicable due to LED lamp
			※LED	※LED	－	※LED	※LED	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	Xgrade ※Not applicable due to LED lamp
Caldina	2002.9-2007.5	AZT24# ST24# ZZT24#	G14 2ケ (No compatible products)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T8×29 1ケ (No compatible products)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (No compatible products)	－	－	－	－	
corolla corolla touring corolla sport	2019.9-2022.9 (sports 2018.6-)	NRE.ZWE. ZRE211(W/H)	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	T10 side 2ケ (P404 ×2)	
			CSPcompleteKIT P22TC										Applicable areas: front, center, luggage、vanity
	2022.10-		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	－	
corolla axio ※Continue to next page	2012.5-2017.9	NRE.NZE.NKE16 #	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
corolla axio	2017.10-	NRE.NZE.NKE16#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	-	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	-	T10 1ケ (P406/407 ×1)	-	-	-	
corolla cross	2021.9-	ZVG11.15 ZSG10	※LED	※LED	-	※LED	※LED	-	※LED	-	-	-	Zgrade ※Not applicable due to LED lamp
			※LED	※LED	-	※LED	※LED	-	※LED	-	-	-	S.Ggrade ※Not applicable due to LED lamp
corolla fielder	2012.5-2015.2	ZRE162G NZE161G.164G	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	-	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	-	T8×29 1ケ (P143 ×1)	-	-	-	
	2015.3-	ZRE162G NZE161G.164G NKE16#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	-	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	-	T10 side 1ケ (P404 ×1)	-	-	-	
Corolla Lumion	2007.10-2015.11	ZRE15# NZE15#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	-	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	-	-	-	-	-	standard room car
		ZRE15# NZE15#	T10 2ケ (P406/407 ×2)	T10 1ケ (P406/407 ×1)	-	T10 2ケ (P145 ×1) (P141 ×1)	※T10 1ケ (P145 ×1) (P141 ×1)	-	-	-	-	-	Car with round ceiling illumination ※Contains 2 valves, so there is 1 left.
Gran Ace	GDH303W	2019.12-	※LED	※LED	※LED	※LED	※LED	※LED	-	-	-	-	※Not applicable due to LED lamp
crown athlete (including hybrid) ※Continue to next page	1999.9-2003.11	JZS17#	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	-	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible	G14 2ケ (No compatible products)	-	-	-	-	-	
	2003.12-2008.1	GRS18#	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10 side 2ケ (P404 ×2)	-	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	-	-	-	-	-	
	2008.2-2012.12	GRS20# GWS20#	T10 1ケ (P406/407 ×1) T10 2ケ (P406/407 ×2)	T10 side 2ケ (P404 ×2)	-	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	-	-	T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation

Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark

※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
crown athlete (including hybrid)	2012.12-2015.9	GRS21# GWS214 AWS21# ARS210	T10 1ケ (P406/407 ×1) T10 2ケ (P406/407 ×2)	T10 side 2ケ (P404 ×2)	－	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	T10 side 2ケ (P404 ×2)	T10 side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.
	2015.10-2018.5		※LED	※LED	－	※LED	※LED	－	T10 side 1ケ (P404 ×1)	※LED	※LED	T10 side 2ケ (P404 ×2)	※Not applicable due to LED lamp
crown royal saloon	1999.9-2001.7	GS17# JKS17# JZS17#	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	－	－	－	－	
	2001.8-2003.11		T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	－	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	
	2003.12-2008.1	GRS18#	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10 side 2ケ (P404 ×2)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	
	2008.2-2012.12	GRS20# GWS20#	T10 1ケ (P406/407 ×1) T10 2ケ (P406/407 ×2)	T10 side 2ケ (P404 ×2)	－	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	－	T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.
	2012.12-2015.9	GRS21# GWS214 AWS21#	T10 1ケ (P406/407 ×1) ※1 T10 2ケ (P406/407 ×2)	T10 side 2ケ (P404 ×2)	－	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	T10 side 2ケ (P404 ×2)	T10 side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.
	2015.10-2018.5		※LED	※LED	－	※LED	※LED	－	T10 side 1ケ (P404 ×1)	※LED	※LED	T10 side 2ケ (P404 ×2)	※Not applicable due to LED lamp
crown	2018.6-	GWS.AWS22# AZSH2# ARS22#	※LED	※LED	－	※LED	※LED	－	T10 side 1ケ (P404 ×1)	※LED	※LED	※LED	
crown estate (athlete)	1999.12-2007.5	JZS17#W	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
crown estate (royal)	1999.12-2007.5	JZS17#W	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	
crown sedan	1995.12-2001.7	GS15# JZS15# LS15#	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	－	－	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	－	－	－	－	－	－	
	2001.8-2009.8	GBS1# GXS1# YXS1#	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	T10 2ケ (P408/409 ×2)	－	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	
crown majesta ※Continue to next page	1999.9-2001.7	JZS17# UZS17#	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	－	－	－	－	
	2001.8-2004.6		T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	－	－	－	－	
	2004.7-2009.2	UZS18#	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10 side 2ケ (P404 ×2)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	－	T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P404 ×2)	
	2009.3-2013.4	URS206 UZS207	T10 1ケ (P406/407 ×1) T10 2ケ (P406/407 ×2)	T10 side 2ケ (P404 ×2)	－	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	－	T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.
	2013.4-2013.8	URS206 UZS207	T10 1ケ (P406/407 ×1) T10 2ケ (P406/407 ×2)	T10 side 2ケ (P404 ×2)	－	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	－	T10 side 2ケ (P404 ×2)	T10 side 2ケ (P404 ×2)	T10 side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.
	2013.9-2018.4	GWS214 AWS215	T10 1ケ (P406/407 ×1) T10 2ケ (P406/407 ×2)	T10 side 2ケ (P404 ×2)	－	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	T10 side 2ケ (P404 ×2)	T10 side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.
	2015.6-2018.4		T10 1ケ (P406/407 ×1) T10 2ケ (P406/407 ×2)	T10 side 2ケ (P404 ×2)	－	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	T10 side 2ケ (P404 ×2)	T10 side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
crown majesta	2015.10-2018.4	GWS214 AWS215	※LED	※LED	－	※LED	※LED	－	T10 side 1ケ (P404 ×1)	※LED	※LED	T10 side 2ケ (P404 ×2)	※Not applicable due to LED lamp
crown comfort	1995.12-	GXS10 YXS10	G14 1ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 1ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
comfort	1995.12-	LXS11 SXS11 YXS11	G14 1ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 1ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
kruger	2000.11-2007.5	ACU2# MCU2#	※T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※It is necessary to remove the reflex inside the light fixture.
kruger hybrid	2005.3-2007.5	MHU28W	※T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※It is necessary to remove the reflex inside the light fixture.
Cresta chaser	1992.10-1996.8	GX9# JZX9# LX9# SX9#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1996.9-2001.6	GX10# JZX10# LX10#	G14 2ケ (No compatible products)	－	T10 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	
Mark II	1992.10-1996.8	GX9# JZX9# LX9# SX9#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1996.9-2001.6	GX10# JZX10# LX10#	G14 2ケ (No compatible products)	－	T10 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	
	2000.10-2004.10	GX11# JZX11#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Copen GR SPORTS	2019.10-	LA400A	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
Premio ※Continue to next page	2007.6-2016.5	ZRT26# NZT26#	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	※T10 side 2ケ (P404 ×2)	※Confirm that the visor is installed on the vehicle side

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》		room lamp	《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
Premio	2016.6-2021.3	ZRT26# NZT26#	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	※T10 side 2ケ (P404 ×2)	※Confirm that the visor is installed on the vehicle side
SAI	2009.12-2013.7	AZK10	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	※T10 side 2ケ (P404 ×2)	※Confirm that the visor is installed on the vehicle side
	2013.8-2017.11		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	T10 side 2ケ (P404 ×2)		※T10 side 2ケ (P404 ×2)	※Confirm that the visor is installed on the vehicle side
Succeed pro box	2002.7-2014.7	NCP58G NCP59G	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2014.8- (サクシード2020.5迄)	NHP.NSP160V	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
C-HR ※Continue to next page	2016.12-2019.9	NGX50 ZYX10	T10 2ケ (P14TC/TL ×1) (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	T10 side 2ケ (P404 ×2)	gradeG,G-T
			CSPcompleteKIT P15TC										gradeG,G-T ※Applicable areas: front, center, rear luggage, vanity
			T10 2ケ (P14TC/TL ×1) (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	－	gradeS,S-T
			CSPcompleteKIT P16TC										gradeS,S-T ※Applicable areas are front, center, and rear luggage.
	2019.10-	NGX10.50 ZYX10.11	T10 2ケ (P14TC/TL ×1) (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	T10 side 2ケ (P404 ×2)	gradeG,G-T
			CSPcompleteKIT P15TC										gradeG,G-T ※Applicable areas: front, center, rear luggage, vanity

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA

Car model	model year	Model	Recommended《CSPplate type》 room lamp front	center	rear	《valve type》 front	center	rear	luggage (trunk)	door front	slide(rear)	vanity	remarks
C-HR	2019.10-	NGX10.50 ZYX10.11	T10 2ケ (P14TC/TL ×1) (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	－	gradeS,S-T
			CSPcompleteKIT P16TC										gradeS,S-T ※Applicable areas are front, center, and rear luggage.
Sienta	2003.9-2015.6	NCP81G NCP85G	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	Common dice
	2015.6-2022.7	NCP175 NHP.NSP17#	T10 2ケ (P10TC/TL ×1) (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	－	Excludes vehicles with LED room lamps equipped with plasma cluster air purifiers.
			CSPcompleteKIT P11TC										Applicable areas: front, center, luggage ※Excludes vehicles with LED room lamps equipped with plasma cluster air purifiers.
	2022.8-	MXPL10.15 MXPC10	※LED	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	※LED	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	－	※Not applicable due to LED lamp
spade	2012.7-2015.7	NCP.NSP14#	T10 2ケ (P406/407 ×2) ※1 (P04TC-2 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 P04TC-2 is the same as P406 2 pieces.
	2015.7-2020.12		T10 2ケ (P406/407 ×2) ※1 (P04TC-2 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	※T10 side 2ケ (P404 ×2)	※1 P04TC-2 is the same as P406 2 pieces.
			CSPcompleteKIT P07TC										Applicable areas: front, center, luggage、vanity
supra	1993.5-1996.4	JZA80	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
	1996.5-2002.7		G14 2ケ (No compatible products)	－	－	G14 2ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	
	2019.5-	DB02.22.82	※LED	－	－	－	－	－	－	－	－	－	※Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
Celsior	2000.8-2003.7	UCF3#	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	－	－	－	－	
	2003.8-2006.5		T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	－	－	－	－	
century	2018.6-	UWG60	※LED	※LED	－	※LED	※LED	－	※LED	※LED	※LED	T10 side 2ケ (P404 ×2)	※Not applicable due to LED lamp
Soarer	1991.5-1993.12	JZZ3# UZZ3#	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1994.1-2001.3		T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	－	－	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	－	－	－	－	－	－	
	2001.4-2005.6	UZZ4#	G14 2ケ (No compatible products)	－	－	G14 2ケ (No compatible products)	－	－	－	－	－	－	
tank Roomy	2016.11-2020.9 Tank up to 2020.9	M9#0A	T10 2ケ (P406/407 ×2)	T10 1ケ (P404 ×1)	T10 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10 1ケ (P404 ×1)	－	T10 2ケ (P404 ×2)	－	※1 Since it comes in 2 pieces, please use one as a spare. ※2 The slide isDepending on the grade, it may or may not be set.
			CSPcompleteKIT P18TC										Applicable areas: front, center, rear, luggage
Roomy	2020.9-	M9#0A	T10 2ケ (P406/407 ×2)	T10 1ケ (P404 ×1)	T10 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10 1ケ (P404 ×1)	－	T10 2ケ (P404 ×2)	－	※1 Since it comes in 2 pieces, please use one as a spare. ※2 The slide isDepending on the grade, it may or may not be set.
			CSPcompleteKIT P18TC										Applicable areas: front, center, rear, luggage
town ace van ※Continue to next page	2008.2-2020.5	S402.412M	T10×31 1ケ (P408/409 ×1)	－	T10×37 1ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10×37 1ケ (No compatible products)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
town ace van	2020.6-	S403.413M	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 Since it comes in 2 pieces, please use one as a spare.
town ace truck	2008.2-2020.5	S402.412U	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
	2020.6-	S403.413U	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 Since it comes in 2 pieces, please use one as a spare.
Noah	2001.11-2007.5	AZR6#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	
	2007.6-2014.1	ZRR70W,G ZRR75W,G	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	※1 T10 side 2ケ (P404 ×2)	1 center light type, option (with large dome light) not available, rear compatible with all cars ※1 Confirm the vanity is installed on the vehicle side.
			T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1) ※1 T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	※2 T10 side 2ケ (P404 ×2)	Center 3 light type, option (with large dome light) not available, rear compatible with all cars *1 Reflector must be removed from center T10 part. ※2 Confirm the vanity is installed on the vehicle side.
	2014.1-2022.1	ZRR8# ZWR8#	T10 2ケ (P406/407 ×2) ※1(P04TC-2 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	T10 side 2ケ (P404 ×2)	standard car ※1 P04TC-2 is the same as P406 2 pieces.
	2015.1-2022.1		T10 2ケ (P406/407 ×2) ※1(P04TC-2 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	※2 T10 side 1ケ (P404 ×1)	－	－	T10 side 2ケ (P404 ×2)	welcab car ※1 P04TC-2 is the same as P406 2 pieces. ※2 Standard equipment only on Welcab (welfare vehicles)
	2014.1-2022.1		CSPcompleteKIT P05TC										Applicable areas: front, center, rear, vanity *Excluding welcab car.
	2022.1-	ZWR9#W MZRA9#W	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	－	－			※1 Room is standard LED
hiace(100 series) ※Continue to next page	1989.8-1993.7	KZH.LH.RZH10# ～18#	G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	T8×29 1ケ (No compatible products)	G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	T8×29 1ケ (P143 ×1)	－	－	－	－	
	1993.8-1996.7		G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	T8×29 1ケ (No compatible products)	G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	T8×29 1ケ (P143 ×1)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			room lamp Recommended《CSPplate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
hiace(100 series)	1996.8-1999.6	KZH.LH.RZH10#～18#	G14 2ケ (No compatible products)	※fluorescent lighting G14 2ケ (No compatible products)	T8×29 1ケ (No compatible products)	G14 2ケ (No compatible products)	※fluorescent lighting G14 2ケ (P402 ×2)	T8×29 1ケ (P143 ×1)	－	－	－	－	※Not applicable due to fluorescent lighting
	1999.7-2004.7		G14 2ケ (No compatible products)	※fluorescent lighting G14 2ケ (No compatible products)	T8×29 1ケ (No compatible products)	G14 2ケ (No compatible products)	※fluorescent lighting G14 2ケ (P402 ×2)	T8×29 1ケ (P143 ×1)	－	－	－	－	※Not applicable due to fluorescent lighting
hiace Regius Ace(200 series)	2004.8-	KDH.TRH.GDH 2##	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	DX
			※1 G14 2ケ (No compatible products)	T10×31 2ケ (P408/409×2)	T10×31 1ケ (P408/409 ×1)	※1 G14 2ケ (No compatible products)	T10×31 2ケ (P143×2)	T10×31 1ケ (P143 ×1)	－	－	※2 T8×28 1ケ (P408/409 ×1) (P143 ×1)	－	super GL Car with front map lamp and large room lamp ※1 G14 map is compatible with CSPcomplete set. ※2 T8×28 but P408/409 can be installed.
			※1 G14 2ケ (No compatible products)	T10×31 2ケ (P408/409×2)	T10×31 2ケ (P408/409 ×2)	※1 G14 2ケ (No compatible products)	T10×31 2ケ (P143×2)	T10×31 2ケ (P143 ×2)	－	－	※2 T8×28 1ケ (P408/409 ×1) (P143 ×1)	－	Grand Cabin/Commuter GL Car with front map lamp and large room lamp ※1 G14 map is compatible with CSPcomplete set. ※2 T8×28 but P408/409 can be installed.
hilux surf	1989.5-1995.11	KZN13# LN13# YN13# VZN13#	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×37 1ケ (No compatible products)	T10×31 1ケ (P135 ×1)	T10×31 1ケ (P143 ×1)	T10×37 1ケ (No compatible products)	－	－	－	－	Back lamp integrated car
			T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×37 1ケ (No compatible products)	T10×31 1ケ (P135 ×1)	T10×31 1ケ (P143 ×1)	T10×37 1ケ (No compatible products)	－	－	－	－	Lighting vehicle with separate back lamp
	1995.12-2000.6	KDN18# KZN18# RZN18# VZN18#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2000.7-2002.10		G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2002.11-2005.6	KDN.RZN.VZN. GRN.TRN21#	※T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※It is necessary to remove the reflex inside the light fixture.
	2005.7-2009.7		※T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※It is necessary to remove the reflex inside the light fixture.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
86	2012.4-2016.6	ZN6	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	T10 side 1ケ (P404 ×1)	※T10 side 2ケ (P145 ×1) (P141 ×1)	－	T6.3×30 (No compatible products)	Early period ※Confirm the front door is installed on the vehicle side.
	2016.7-2021.10		T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	T10 side 1ケ (P404 ×1)	※T10 side 2ケ (P145 ×1) (P141 ×1)	－	T6.3×30 (No compatible products)	Late period ※Confirm the front door is installed on the vehicle side.
GR86	2021.10-	ZN8	T10 2ケ (P406/407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10 1ケ (P406/407 ×1)	※T10 side 2ケ (P404 ×2)	－	T6.3×30 (No compatible products)	
passo	2004.6-2010.1	KGC1# QNC1#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	※T10 side 1ケ (P145 ×1) (P141 ×1)	－	－	－	※Contains 2 valves, so there is 1 left.
	2010.2-2016.3	NGC30 KGC30/35	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	
	2016.4-	M700.710A	T10 2ケ (P406/407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	
Passosette	2008.12-2012.3	M502E M512E	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	※T10 side 1ケ (P145 ×1) (P141 ×1)	－	－	－	※Contains 2 valves, so there is 1 left.
harrier ※Continue to next page	1997.12-2003.1	ACU1# MCU1# SXU1#	T10×41 1ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×41 1ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	standard car
			G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	Car with sunroof
	2003.2-2013.7	ACU.GSU3#W	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	※1 T10 side 2ケ (P145 ×1) (P141 ×1)	－	－	※1 Confirm the front door is installed on the vehicle side.
	2013.12-2015.3	ZSU6#W AVU65W	T10 ×2ケ (P12TC ×1) (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	T10 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	Before M/C ※Excludes standard LED specification vehicles.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
harrier	2015.4-2020.6	ASU.ZSU6#W AVU65W	T10 ×2ケ (P12TC ×1) (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	T10 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	After M/C ※Excludes standard LED specification vehicles.
			CSPcompleteKIT P13TC										Applicable areas: front, center, rear luggage, doors, vanity
	2020.6-	MXUA8#	※LED	※LED	－	※LED	※LED	－	※LED	※LED	－	－	※Not applicable due to LED lamp
harrier hybrid	2005.3-2013.7	MHU38W	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	※1 T10 side 2ケ (P145 ×1) (P141 ×1)	－	－	※1 Confirm the front door is installed on the vehicle side.
bB	2000.2-2003.3	NCP3#	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2003.4-2005.11		－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2005.12-2008.9	QNC20 QNC21 QNC25	※1 T10 2ケ (No compatible products)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	T10 1ケ (No compatible products)	※2 T10 side 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 No applicable products for plate type with narrow insertion opening. ※2 Contains 2 valves, so there is 1 left.
	2008.10-2014.7		※1 T10 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10 1ケ (No compatible products)	※2 T10 side 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 No applicable products for plate type with narrow insertion opening. ※2 Contains 2 valves, so there is 1 left.
	2014.8-2016.7		※1 T10 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10 1ケ (No compatible products)	※2 T10 side 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 No applicable products for plate type with narrow insertion opening. ※2 Contains 2 valves, so there is 1 left.
Pyxis Epoch	2012.5-2017.5	LA300A.310A	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2017.6-	LA350A.360A	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
pixis joy	2015.9-	LA250.260S	T10 2ケ (P406/407 ×2)	T10 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※T10 1ケ (P145 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	－	※Contains 2 valves, so there is 1 left. Front/center LED specification models available.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation

Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark

※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			room lamp Recommended《CSPplate type》			room lamp 《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
pixis space	2011.9-2017.1	L57#.58#	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
pixis track	2011.12-2014.8	S201U.211U	T10 1ケ (P406/407 ×1)	－	－	※T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※Contains 2 valves, so there is 1 left.
	2014.9-2018.4	S500U.510U	T10 1ケ (P406/407 ×1)	－	－	※T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※Contains 2 valves, so there is 1 left.
	2018.5-		T10 1ケ (P406/407 ×1)	－	－	※T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	halogen headlamp car ※Contains 2 valves, so there is 1 left.
			T10 1ケ (P406/407 ×1)	－	－	※T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	led headlamp car ※Contains 2 valves, so there is 1 left.
pixis van	2011.12-2017.11	S321M	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P408/409 ×1)	－	－	－	
	2017.12-2021.11	S3#1M	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P408/409 ×1)	－	－	－	halogen headlamp car ※Contains 2 valves, so there is 1 left.
			T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P408/409 ×1)	－	－	－	led headlamp car ※Contains 2 valves, so there is 1 left.
	2021.12-	S700.710M	※1 T10 1ケ (P406/407 ×1)	Unconfirmed	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	Unconfirmed	－	※1 T10 side 1ケ (P404 ×1)	－	－	－	※1 Standard LED settings are also available. ※2 It comes in 2 pieces, but only 1 piece is used.
pixis mega ※Continue to next page	2015.7-2016.4	LA700A.710A	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	T10 side 1ケ (P404 ×1)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	※T10 side 1ケ (P145 ×1) (P141 ×1)	T10 side 1ケ (P404 ×1) back door lamp	－	－	－	※Contains 2 valves, so there is 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation

Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark

※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
pixis mega	2016.5-	LA700A.710A	T10 2ケ (P406/407 ×2)	－	T10 side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	※T10 side 1ケ (P145 ×1) (P141 ×1)	T10 side 1ケ (P404 ×1) back door lamp	－	－	－	halogen headlamp car ※Contains 2 valves, so there is 1 left.
			T10 2ケ (P406/407 ×2)	－	T10 side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	※T10 side 1ケ (P145 ×1) (P141 ×1)	T10 side 1ケ (P404 ×1) back door lamp	－	－	－	led headlamp car ※Contains 2 valves, so there is 1 left.
fan cargo	1999.8-2005.9	NCP2#	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T8×29 1ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	－	
platz	1999.8-2003.7	NCP1# SCP1#	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2003.8-2005.11		T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
prius ※Continue to next page	1997.12-2000.4	NHW1#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2000.5-2003.8		G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2003.9-2009.4	NHW2#	T10 1ケ (P406/407 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※Contains 2 valves, so there is 1 left.
	2009.5-2011.11	ZVW30	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	－	
	2011.12-2013.6		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 side 2ケ (P404 ×2)	
	2013.6-2015.5		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
prius	2015.5-2015.12	ZVW30	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	
	2015.12-2018.11	ZVW5#	※T10 2ケ (P01TL ×1) (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	※Front map can only be installed on P406/407 except for moonroof vehicles.
			CSPcompleteKIT P03TC										Applicable areas: front, center, rear luggage, doors, vanity ※Excluding moonroof cars
	2018.12-		※T10 2ケ (P01TL ×1) (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	※Front map can only be installed on P406/407 except for moonroof vehicles.
			CSPcompleteKIT P03TC										Applicable areas: front, center, rear luggage, doors, vanity ※Excluding moonroof cars
prius α	2011.5-2013.6	ZVW40/41	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/ ×1) (P408/49 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 side 2ケ (P404 ×2)	
	2013.6-2015.5		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	
	2015.5-2021.3	ZVW40/41	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	
			CSPcompleteKIT P20TC										Applicable areas: front, center, rear luggage, doors, vanity
priusPHV ※Continue to next page	2012.1-2013.6	ZVW35	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 side 2ケ (P404 ×2)	
	2013.6-2015.5		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	
	2015.5-2016.5		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
priusPHV	2017.2-	ZVW52	※T10 2ケ (P01TL ×1) (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	※Front map can only be installed on P406/407 except for moonroof vehicles.
			CSPcompleteKIT P03TC										Applicable areas: front, center, rear luggage, doors, vanity ※Excluding moonroof cars
blade	2006.12-2012.4	GRE156H AZE154.156H	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※T10 side 2ケ (P404 ×2)	※Confirm the vanity is installed on the vehicle side.
brevis	2001.6-2007.5	JCG1#	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2005.12-2007.5		T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Premio	2012.12-2016.5	NZT.ZRT26#	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	T10 side 2ケ (P404 ×2)	
	2016.6-2021.3		T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	T10 side 2ケ (P404 ×2)	
Progre	1998.5-2007.5	JCG1#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Bertha	2005.11-2012.6	SCP92 KSP92 NCP96	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Porte	2004.7-2012.5	NNP10 NNP11 NNP15	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
※Continue to next page	2012.7-2015.7	NCP.NSP14#	T10 2ケ ※1 (P04TC-2 ×1) (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	T10 side 2ケ (P404 ×2)	※1 P04TC-2 is the same as P406 2 pieces.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA

Car model	model year	Model	room lamp Recommended《CSPplate type》 front	room lamp center	room lamp rear	《valve type》 front	《valve type》 center	《valve type》 rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
Porte	2015.7-2020.12	NCP.NSP14#	T10 2ケ ※1 (P04TC-2 ×1) (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	T10 side 2ケ (P404 ×2)	※1 P04TC-2 is the same as P406 2 pieces.
			CSPcompleteKIT P07TC										Applicable areas: front, center, rear luggage, vanity
Mark X	2004.11-2009.9	GRX12#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	※T10 side 2ケ (P145 ×1) (P141 ×1)	－	※T10 side 2ケ (P404 ×2)	※front door/Confirm the vanity is installed on the vehicle side.
	2009.10-2012.7	GRX13#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 side 2ケ (P404 ×2)	
	2012.8-2013.2		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 side 2ケ (P404 ×2)	
	2013.3-2019.12		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	
mark x geo	2007.9-2013.11	GGA1# ANA1#	T10 2ケ (P406/407 ×2)	※T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※T10×31 1ケ (P143 ×1)	－	－	T10 side 2ケ (P145 ×1) (P141 ×1)	－	T10 side 2ケ (P404 ×2)	※350G cannot be installed because it has large ceiling illumination (LED specification).
Mark Ⅱ brit	2002.1-2007.5	GX11# JZX11#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	
Mirai	2014.12-2020.11	JPD10	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	T10 side 2ケ (P404 ×2)	－	T10 side 2ケ (P404 ×2)	
	2020.12-	JPD20	Unconfirmed	Unconfirmed	Unconfirmed	Unconfirmed	Unconfirmed	Unconfirmed	Unconfirmed	Unconfirmed	Unconfirmed	Unconfirmed	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
yaris Yaris Cross	2020.2- 2020.8-	MXPH,MXPA1# KSP10 MXPB1,MXPJ1#	※LED	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	※LED	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	T10 side 2ケ (P404 ×2)	halogen headlamp car ※Cannot be installed due to LED ※Front standard LED is light bulb color G.Xgrade(Car without vanity)
			※LED	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	－	※LED	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)	－	－	T10 side 2ケ (P404 ×2)	led headlamp car ※Cannot be installed due to LED ※Front standard LED is light bulb color G.Xgrade(Car without vanity)
			CSPcompleteKIT P28TC										Applicable areas: center, rear luggage
			CSPcompleteKIT P28TC										Zgrade Applicable areas: center, rear luggage、vanity
raise	2019.10-	A200.210A	T10 2ケ (P406/407 ×2)	T10 side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 side 1ケ (P145 ×1)	－	T10 side 1ケ (P404 ×1) ※1 (P145 ×1)	－	－	－	※1 f you select P145 for the center lamp, it can be used in luggage as it comes in 2 pieces.
			CSPcompleteKIT P27TC										※Same as Daihatsu Rocky Applicable areas: front, center, luggage
light ace	1992.1-1996.9	CR.KR.TR.YR2# CR.KR.TR.YR3#	T10×31 1ケ (P408/409 ×1) G14 2ケ (No compatible products)	※fluorescent lighting	－	T10×31 1ケ (P143×1) G14 2ケ (No compatible products)	※fluorescent lighting	－	－	－	－	－	※Not applicable due to fluorescent lighting
light ace van	2008.2-2020.5	S402.412M	T10×31 1ケ (P408/409 ×1)	－	T10×37 1ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10×37 1ケ (No compatible products)	－	－	－	－	
	2020.6-	S403.413M	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 Since it comes in 2 pieces, please use one as a spare.
light ace truck	2008.2-2020.5	S402.412U	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
	2020.6-	S403.413U	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 Since it comes in 2 pieces, please use one as a spare.
light ace noah (Town Ace Noah) ※Continue to next page	1996.10-1998.11	CR.KR.SR4# CR.KR.SR5#	G14 2ケ (No compatible products)	※fluorescent lighting	T10×31 1ケ (P408/409 ×1)	G14 2ケ (No compatible products)	※fluorescent lighting	T10×31 1ケ (P143 ×1)	－	－	－	－	※Not applicable due to fluorescent lighting

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			Recommended《CSPplate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
light ace noah (Town Ace Noah)	1998.12-2001.10	CR.KR.SR4# CR.KR.SR5#	G14 2ケ (No compatible products)	※fluorescent lighting	T10×31 1ケ (P408/409 ×1)	G14 2ケ (No compatible products)	※fluorescent lighting	T10×31 1ケ (P143 ×1)	－	－	－	－	※Not applicable due to fluorescent lighting
raum	1997.5-2003.4	EXZ1#	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2003.5-2006.11	NCZ20 NCZ25	G14 2ケ (No compatible products)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2006.12-2011.10		G14 2ケ (No compatible products)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
RAV4 (hybrid/PHV)	2005.11-2015.5	ACA3#W	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※T10 side 2ケ (P404 ×2)	※Confirm that the visor is installed on the vehicle side
	2015.5-2016.7		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)			T10 side 2ケ (P404 ×2)	
	H31.3-	MXAA5# AXAH5# AXAP54	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 1ケ (P404 ×1)			T10 side 2ケ (P404 ×2)	
			CSPcompleteKIT P25TC										Applicable areas: front, center, rear luggage, vanity
Ractis	2005.10-2010.10	NCP10# SCP10#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2007.12-2010.10		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2010.11-2014.4	NCP12# NSP12#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2014.5-2016.9		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			room lamp Recommended《CSPplate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
Rush	2006.1-2016.3	J210E J200E	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	T10 1ケ (P406/407 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	※T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※The room (rear) has since it comes in 2 pieces, please use one as a spare.
land cruiser70	1987.8-2004.4	HZJ7#	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2014.8-2015.7	GRJ76K	T10×37 1ケ (No compatible products)	－	T10×37 1ケ (No compatible products)	T10×37 1ケ (No compatible products)	－	T10×37 1ケ (No compatible products)	－	－	－	－	van
		GRJ79K	T10×37 1ケ (No compatible products)	－	－	T10×37 1ケ (No compatible products)	－	－	－	－	－	－	pickup
	2023.11-2024.9 2024.10-	GDJ76W	T10 ×1ケ (P404 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10 ×1ケ (P404 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
land cruiser80	1989.10-1997.12	FJ.FZJ.HDJ. HZJ8#	G14 1ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	G14 1ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
land cruiser prado	1996.5-1999.5	KDJ.KZJ.RZJ. VZJ90#	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	T10×37 1ケ (No compatible products)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×37 1ケ (No compatible products)	－	－	－	－	
	1999.6-2002.9		G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	T10×37 1ケ (No compatible products)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×37 1ケ (No compatible products)	－	－	－	－	
	2002.10-2009.8	GRJ.KDJ.RZJ. TRJ.VZJ12#	G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	
land cruiser prado	2009.9-2013.8	GRJ.TRJ15# GDJ15#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	※T10 side 2ケ (P145 ×1) (P141 ×1)	※T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P404 ×2)	gradeTX only 2009.8-2013.8 is available with or without vanity.
	2013.8-	GRJ.TRJ15# GDJ15#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	※T10 side 2ケ (P145 ×1) (P141 ×1)	※T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P404 ×2)	gradeTX only
			CSPcompleteKIT P24TC										gradeTX only Applicable areas: front, center, rear, vanity

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			room lamp Recommended《CSPplate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
land cruiser prado	2009.9-2013.8	GRJ.TRJ15# GDJ15#	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	※T10 side 2ケ (P145 ×1) (P141 ×1)	※T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P404 ×2)	gradeTZ-G,TX (L package) only 2009.8-2013.8 is available with or without vanity.
	2013.8-		T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P406/407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	※T10 side 2ケ (P145 ×1) (P141 ×1)	※T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P404 ×2)	gradeTZ-G,TX (L package) only
			CSPcompleteKIT P26TC										gradeTZ-G,TX (L package) only Applicable areas: front, center, rear, vanity
land cruiser100	1998.1-2005.3	HDJ10# UZJ10#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1) T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1) T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2005.4-2007.8		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1) T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1) T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	
land cruiser200	2007.9-2011.10	URJ20# UZJ20#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	※T10 side 2ケ (P145 ×1) (P141 ×1)	※T10 side 2ケ (P145 ×1) (P141 ×1)		Early period ※Check that the door is installed on the vehicle side
	2011.11-2013.7		T10 2ケ (P406/407 ×2)	※1 T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 2ケ (P404 ×2)	※2 T10 side 2ケ (P145 ×1) (P141 ×1)	T6.3×30 (No compatible products)	middle period ※1 Three centers may be used depending on the grade. ※2 Check that the door is installed on the vehicle side
	2013.8-2015.7		T10 2ケ (P406/407 ×2)	※1 T10 3ケ (P406/407 ×3)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 3ケ (P145 ×2) (P141 ×2)	T10×31 1ケ (P143 ×1)	－	T10 side 2ケ (P404 ×2)	※2 T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P404 ×2)	Late period ※1 Please check the center. The valve type comes in 2 pieces, so there is one extra. ※2 Check that the door is installed on the vehicle side
	2015.8-2021.8		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	T10×31 1ケ (P02TC ×1) (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	T10 side 2ケ (P404 ×2)	※2 T10 side 2ケ (P145 ×1) (P141 ×1)	T10 side 2ケ (P404 ×2)	Late period ※1 Please check the center. ※2 Check that the door is installed on the vehicle side
land cruiser300	2021.8-	FJA300W VJA300W	※LED	※LED	※LED	※LED	※LED	※LED	－	－	－	－	※All room lamps are LED and cannot be replaced.
land cruiser cygnus ※Continue to next page	1999.1-2002.7	UZJ10#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P406/407 ×1) T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1) T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation

Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark

※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			room lamp Recommended《CSPplate type》			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	Model	front	center	rear	front	center	rear		front	slide(rear)		
land cruiser cygnus	2002.8-2007.8	UZJ10#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

LEXUS			room lamp Recommended《CSP plate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
ES	2018.10-	AXZH10	※ LED	※ LED	－	※ LED	※ LED	－	－	－	－	－	※Not applicable due to LED lamp
HS	2009.7-2018.3	ANF10	T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/P409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	T10side 2ケ (P145 ×1) (P141 ×1)	－	T10side 2ケ (P404 ×2)	
IS	2005.9-2013.4	GSE2#	T10 1ケ (P406/P407 ×1) T10 2ケ (P406/P407 ×2)	－	T8×29 2ケ (No compatible products)	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	T8×29 2ケ (P143 ×2)	－	－	－	T10side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.
	2013.5-2016.9	GSE.AVE3#	T10 1ケ (P406P407 ×1) T10 2ケ (P406/P407 ×2)	－	T10 1ケ (P406/P407 ×1) T10 2ケ (P406/P407 ×2)	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10side 1ケ (P404 ×1)	－	－	T10side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.
	2016.10-2020.10	GSE.AVE ASE3#	T10 1ケ (P406P407 ×1) T10 2ケ (P406/P407 ×2)	－	T10 1ケ (P406/P407 ×1) T10 2ケ (P406/P407 ×2)	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10side 1ケ (P404 ×1)	－	－	T10side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.
	2020.11-	GSE.AVEASE3#	※ LED	－	※ LED	※ LED	－	※ LED	T10side 1ケ (P404 ×1)	－	－	T10side 2ケ (P404 ×2)	※Not applicable due to LED lamp
IS F	2007.12-2014.5	USE20	T10 1ケ (P406P407 ×1) T10 2ケ (P406/P407 ×2)	－	T8×29 2ケ (No compatible products)	※T10 1ケ (P145 ×1) (P141 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	T8×29 2ケ (P143 ×2)	T10side 1ケ (P404 ×1)	－	－	T10side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.
IS convertible	2009.5-	GSE2#	T10 2ケ (P406/P407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	
RX ※Continue to next page	2009.1-2012.3	GGL1#W	T10 2ケ (P406/P407 ×2)	－	T10 1ケ (P406/P407 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	※ T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	T10side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.
	2009.4-2012.3	GYL1#W	T10 2ケ (P406/P407 ×2)	－	T10 1ケ (P406/P407 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	※ T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	T10side 2ケ (P404 ×2)	hybrid ※Contains 2 valves, so there is 1 left.
	2012.4-2015.9	AGL.GGL GYL1#	T10 2ケ (P406/P407 ×2)	－	T10 1ケ (P406/P407 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	※ T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	T10side 2ケ (P404 ×2)	※Contains 2 valves, so there is 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

LEXUS			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
RX	2015.10-	GYL2#	※ LED	-	※ LED	※ LED	-	※ LED	-	-	-	T10side 2ケ (P404 ×2)	※Not applicable due to LED lamp
RC	2014.10-2018.9	CGC.AVC1#	※ LED	※ LED	-	※ LED	※ LED	-	-	-	-	T10side 2ケ (P404 ×2)	※Not applicable due to LED lamp
	2018.11-	GSC.AVC,ASC1#	※ LED	※ LED	-	※ LED	※ LED	-	-	※ LED	-	T10side 2ケ (P404 ×2)	※Not applicable due to LED lamp
LS	2006.9-2009.9	USF4#	T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	-	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	-	-	-	-	T10side 2ケ (P404 ×2)	
			T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1) T9 2ケ (No compatible products)	-	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1) T9 2ケ (No compatible products)	-	-	-	-	T10side 2ケ (P404 ×2)	Car with sunroof, car with rear seat ceiling monitor
	2009.10-2017.9		T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	-	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	-	-	-	-	T10side 2ケ (P404 ×2)	
			T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1) T9 2ケ (No compatible products)	-	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1) T9 2ケ (No compatible products)	-	-	-	-	T10side 2ケ (P404 ×2)	Car with sunroof, car with rear seat ceiling monitor
	2017.10-	VXFA5#	※ LED	※ LED	-	※ LED	※ LED	-	-	-	-	-	※Not applicable due to LED lamp
LC	2017.3-	GWZ100	※ LED	※ LED	-	※ LED	※ LED	-	-	-	-	-	※Not applicable due to LED lamp
LFA	2010.10-2012.12	LFA10	※ LED	-	-	※ LED	-	-	-	-	-	-	※Not applicable due to LED lamp
LS hybrid	2007.5-2012.9	UVF4#	T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/409 ×1)	-	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	-	-	-	-	T10side 2ケ (P404 ×2)	
			T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/409 ×1) T9 2ケ (No compatible products)	-	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1) T9 2ケ (No compatible products)	-	-	-	-	T10side 2ケ (P404 ×2)	Car with sunroof, car with rear seat ceiling monitor

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

LEXUS			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
SC	2005.8-2010.7	UZZ4#	G14 2ケ (No compatible products)	－	－	G14 2ケ (No compatible products)	－	－	－	－	－	－	
CT	2011.1-2017.7	ZWA10	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	T10side 2ケ (P145 ×1) (P141 ×1)	－	T10side 2ケ (P404 ×2)	
	2017.8-		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P02TC/TL ×1) (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10side 2ケ (P404 ×2)	－	－	T10side 2ケ (P404 ×2)	
GS	2005.8-2011.12	GRS.UZS.URS 19#	T10 2ケ (P406/P407 ×2)	※ LED	－	T10 2ケ (P145 ×1) (P141 ×1)	※ LED	－	－	T10side 2ケ (P145 ×1) (P141 ×1)	T10side 2ケ (P145 ×1) (P141 ×1)	T10side 2ケ (P404 ×2)	※Not applicable due to LED lamp
	2012.1-27.10	GRL1#	※ LED	※ LED	－	※ LED	※ LED	－	－	－	－	－	※Not applicable due to LED lamp
GS F	2015.11-2020.9	URL10	※ LED	※ LED	－	※ LED	※ LED	－	－	T10side 2ケ (P145 ×1) (P141 ×1)	T10side 2ケ (P145 ×1) (P141 ×1)	T10side 2ケ (P404 ×2)	※Not applicable due to LED lamp
GS hybrid	2006.3-2011.12	GWS19#	T10 2ケ (P406/P407 ×2)	※ LED	－	T10 2ケ (P145 ×1) (P141 ×1)	※ LED	－	－	T10side 2ケ (P145 ×1) (P141 ×1)	T10side 2ケ (P145 ×1) (P141 ×1)	T10side 2ケ (P404 ×2)	※Not applicable due to LED lamp
	2012.3-	GWL10	※ LED	※ LED	－	※ LED	※ LED	－	－	－	－	－	※Not applicable due to LED lamp
UX	2018.11-	MZAH1# MZAA1#	※ LED	※ LED	－	※ LED	※ LED	－	－	－	－	－	※Not applicable due to LED lamp
NX	2014.7-2017.8	AYZ/AGZ1#	※ LED	※ LED	－	※ LED	※ LED	－	T8×29 1ケ (P143 ×1)	－	－	－	※Not applicable due to LED lamp
	2017.9-		※ LED	※ LED	－	※ LED	※ LED	－	T10side 2ケ (P404 ×2)	－	－	－	※Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
avenir	1990.5-1998.7	W10	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10 1ケ (P406/P407 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	1998.8-2005.10	W11	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
infiniti q45	1989.11-1997.7	G50	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
wing road	1996.5-1999.4	Y10	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10 1ケ (P406/P407 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	1999.5-1997.9	Y11	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10 1ケ (P406/P407 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2001.10-2005.10		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10 1ケ (P406/P407 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2005.11-2018.3	Y12	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10 1ケ (P406/P407 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》		room lamp	《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
expert	1999.6-2005.10	W11	－	T10×31 1ケ (P408/P409 ×1)	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P143 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
AD Wagon	1990.10-1999.5	Y10	－	T10×31 1ケ (P408/P409 ×1)	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P143 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Advan	1990.10-1999.5	Y10	－	T10×31 1ケ (P408/P409 ×1)	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P143 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	1999.6-2001.9	Y11	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2001.10-2005.10		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
AD/AD Expert	2007.1-	Y12	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10 1ケ (P406/P407 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
NT100 clipper	2013.12-	DR16T	T10 1ケ (P406/P407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
NV100 clipper	2013.12-2015.2	DR64V	T10 1ケ (P406/P407 ×1)	－	T10 1ケ (P406/P407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
NV100 clipper	2015.3-	DR17V	T10 1ケ (P406/P407 ×1)	-	T10 1ケ (P406/P407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
NV100 Clipper Rio	2013.12-2015.2	DR64W	T10 1ケ (P406/P407 ×1)	T10×31 1ケ (P408/P409 ×1)	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
	2015.3-	DR17W	T10 1ケ (P406/P407 ×1)	T10×31 1ケ (P408/P409 ×1)	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
x-trail ※Continue to next page	2000.11-2007.7	T30	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	※G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	-	-	-	-	※It is necessary to remove the metal plate inside the light fixture.
	2007.8-2010.6	T31	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	-	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	-	T10×31 1ケ (P408/409 ×1) (P143 ×1)	-	-	-	
			T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	-	T10×31 1ケ (P143 ×1)	T10×31 2ケ (P143 ×2)	-	T10×31 1ケ (P408/409 ×1) (P143 ×1)	-	-	-	Car with sunroof
	2010.7-2015.2		T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	-	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	-	T10×31 1ケ (P408/409 ×1) (P143 ×1)	-	-	-	
	2013.12-2017.6	T32 NT32	※1 LED	T10×31 1ケ (P408/P409 ×1)	T8×29 1ケ (No compatible products)	※1 LED	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	-	-	-	-	※1 Not applicable due to LED lamp
	2015.4-2017.6	HT32.NHT32 hybrid	※1 LED	T10×31 1ケ (P408/P409 ×1)	T8×29 1ケ (No compatible products)	※1 LED	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	-	-	-	-	※1 Not applicable due to LED lamp
			※1 LED	T10 2ケ (P406/P407 ×2)	T8×29 1ケ (No compatible products)	※1 LED	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	-	-	-	-	※1 Not applicable due to LED lamp Car with sunroof

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
x-trail	2017.6-2022.6	T32.NT32 HT32.NHT32	※1 LED	T10×31 1ケ (P408/P409 ×1)	T8×29 1ケ (No compatible products)	※1 LED	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	－	※1 Not applicable due to LED lamp
			※1 LED	T10 2ケ (P406/P407 ×2)	T8×29 1ケ (No compatible products)	※1 LED	T10 2ケ (P145 ×1) (P141 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	－	※1 Not applicable due to LED lamp Car with sunroof
	2022.7-	T33.SNT33	T10 2ケ (CSPはサイズNot applicable)	T10 2ケ (CSPはサイズNot applicable)	T10×31 1ケ (P408/P409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	T10 ×2ケ (P404 ×2)	
NV200 Vanette	2009.5-	M20	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	
e-NVvan	2014.6-	VME0	T10 3ケ (P406/P407 ×3)	－	－	※1 T10 3ケ (P145 ×2) (P141 ×2)	－	－	T10 1ケ (P406/407 ×1)	－	－	－	※1 It comes in 2 pieces, but only 3 pieces are used.
e-NV wagon	2014.6-	ME0	T10 3ケ (P406/P407 ×3)	T10×31 1ケ (P408/P409 ×1)	－	※1 T10 3ケ (P145 ×2) (P141 ×2)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	※1 It comes in 2 pieces, but only 3 pieces are used.
NV350 character van ※Continue to next page	2012.6-2017.6	E26	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	DX
			G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T10 1ケ (P406/407 ×1)	－	－	－	premiumGX、GX
NV350 character van	2017.7-	E26	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	DX
			G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T10 1ケ (P406/407 ×1)	－	－	－	premiumGX、GX

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
elgrand	1997.5-2000.7	E50	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	standard car
			G14 2ケ (No compatible products)	T10×31 2ケ (P408/P409 ×2)	G14 4ケ (No compatible products)	G14 2ケ (No compatible products)	T10×31 2ケ (P143 ×2)	G14 4ケ (No compatible products)	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	Car with large room lamp
	2000.8-2002.4	E50	G14 2ケ (No compatible products)	T10×31 2ケ (P408/P409 ×2)	G14 4ケ (No compatible products)	G14 2ケ (No compatible products)	T10×31 2ケ (P143 ×2)	G14 4ケ (No compatible products)	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2002.5-2010.7	E51	G14 2ケ (No compatible products)	T10×31 2ケ (P408/P409 ×2)	G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	T10×31 2ケ (P143 ×2)	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2010.8-2013.12	E52	T10 2ケ (P406/P407 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2014.1-		T10 2ケ (P406/P407 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
aura	FE13.FSNE13	2021.6-	T13 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T13 2ケ (P145 ×2) (P141 ×2)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/P407 ×1)	－	－	－	
Otti	2005.6-2006.9	H91W	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2006.10-	H92W	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			room lamp Recommended《CSP plate type》			room lamp 《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
kicks	2008.10-2012.6	H59A	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2020.7-	P15	T13 2ケ (P406/P407 ×2)	T10 1ケ (P406/P407 ×1)	－	※1 T13 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	
caravan Homie	1986.9-1997.4	E24	G14 2ケ (No compatible products)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	1997.5-2001.4		G14 2ケ (No compatible products)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 2ケ (P143 ×1)	T10×31 1ケ (134 ×1)	－	－	－	－	
caravan	2001.5-2005.11	E25	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	－	※1 T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	Room front 1 month type car
			G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	Room front 2 months type car
			※1 G14 2ケ (No compatible products)	G14 4ケ (No compatible products)	－	※1 G14 2ケ (No compatible products)	G14 4ケ (No compatible products)	－	T10 1ケ (P406/407 ×1)	－	－	－	2 rooms front type/Car with large room lamp ※1 Some specifications are T10×31. In that case, P408/P409 and P143 are recommended.
	2005.12-2012.5	E25	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	－	※1 T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	Room front 1 month type car
			※G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	Room front 2 months type car
			※G14 2ケ (No compatible products)	※G14 4ケ (No compatible products)	－	G14 2ケ (No compatible products)	※2 G14 4ケ (No compatible products)	－	T10 1ケ (P406/407 ×1)	－	－	－	2 rooms front type/Car with large room lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
cube	1998.2-2002.9	Z10	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	Room front 2 months type car
	2002.10-2005.4	Z11	※1 G14 2ケ (No compatible products)	G14 4ケ (No compatible products)	－	※1 G14 2ケ (No compatible products)	G14 4ケ (No compatible products)	－	T10 1ケ (P406/407 ×1)	－	－	－	2 rooms front type/Car with large room lamp ※1 Some specifications are T10×31. In that case, P408/P409 and P143 are recommended.
	2005.5-2006.12	Z11	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P408/409 ×1) (P143 ×1)				
	2007.1-2008.10		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P408/409 ×1) (P143 ×1)				
	2008.11-2020.3	Z12	T10 3ケ (P406/P407 ×3)	T10×31 1ケ (P408/P409 ×1)	－	※1 T10 3ケ (P145 ×2) (P141 ×2)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	※1 It comes in 2 pieces, but only 3 pieces are used.
cube cubic	2002.10-2005.4	Z11	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2005.5-2006.12		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2007.1-2008.10		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			room lamp Recommended《CSP plate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
clipper van	2003.10-	U71V U72V	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
clipper rio	2007.6-2011.11	U71W U72W	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
crew	1993.7-2002.6	K30	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (適応品なし)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Gloria	1991.6-1993.5	Y32	G14 2ケ (No compatible products)	※ T10×31 2ケ (P408/P409 ×2)	－	G14 2ケ (No compatible products)	※1 T10×31 2ケ (P143 ×2)	－	－	－	－	－	※1 It is necessary to remove the metal plate inside the light fixture.
	1993.6-1995.5		G14 2ケ (No compatible products)	※ T10×31 2ケ (P408/P409 ×2)	－	G14 2ケ (No compatible products)	※1 T10×31 2ケ (P143 ×2)	－	－	－	－	－	※1 It is necessary to remove the metal plate inside the light fixture.
	1995.6-1999.5	Y33	G14 2ケ (No compatible products)	※ T10×31 2ケ (P408/P409 ×2)	－	G14 2ケ (No compatible products)	※1 T10×31 2ケ (P143 ×2)	－	－	－	－	－	※1 It is necessary to remove the metal plate inside the light fixture.
	1999.6-2004.10	Y34	G14 2ケ (No compatible products)	－	※1 T10×31 2ケ (P408/P409 ×2)	G14 2ケ (No compatible products)	－	※1 T10×31 2ケ (P143 ×2)	－	－	－	－	※1 It is necessary to remove the metal plate inside the light fixture.
sunny	1994.1-1998.9	B14	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
sunny	1998.10-2004.10	B15	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Luchino (coupe)	1994.5-1999.4	B14	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Luchino (hatch back)	1995.1-1999.9	N15	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Luchino S-RV	1996.5-2000.8	N15	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
safari	1997.10-H114.10	Y61	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
※Continue to next page	2002.11-2004.7		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
safari	2004.8-2007.6		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
Sakura	2022.5-	B6AW	T10 3ケ (P406/P407 ×3)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 3ケ (P145 ×2) (P141 ×2)		T10×31 1ケ (P143 ×1)	－	－	－	－	
CIMA	1991.8-1996.5	Y32	G14 2ケ (No compatible products)	※1 T10×31 2ケ (P406/407 ×2)	－	G14 2ケ (No compatible products)	※1 T10×31 2ケ (P143 ×2)	－	－	－	－	－	※1 It is necessary to remove the metal plate inside the light fixture.
	1996.6-2000.12	Y33	G14 2ケ (No compatible products)	※1 T10×31 2ケ (P406/407 ×2)	※2 T10×31 2ケ (P134 ×2)	G14 2ケ (No compatible products)	※1 T10×31 2ケ (P143 ×2)	※2 T10×31 2ケ (P143 ×2)	－	－	－	－	※1 It is necessary to remove the metal plate inside the light fixture. ※2 Standard equipment on vehicles equipped with HID
	2001.1-2010.7	F50	G14 2ケ (No compatible products)	－	※1 T10×31 2ケ (P134 ×2)	G14 2ケ (No compatible products)	－	※1 T10×31 2ケ (P143 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	※1 It is necessary to remove the metal plate inside the light fixture.
	2003.10-2006.1		G14 2ケ (No compatible products)	－	※1 T10×31 2ケ (P134 ×2)	G14 2ケ (No compatible products)	－	※1 T10×31 2ケ (P143 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	※1 It is necessary to remove the metal plate inside the light fixture.
	2006.2-2010.8	F50	G14 2ケ (No compatible products)	－	※1 T10×31 2ケ (P134 ×2)	G14 2ケ (No compatible products)	－	※1 T10×31 2ケ (P143 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	※1 It is necessary to remove the metal plate inside the light fixture.
	2012.5-	HGY51	G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	－	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	－	T10 1ケ (P406/407 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》		room lamp	《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
juke	2010.6-2014.6	F15	T10 3ケ (P406/P407 ×3)	-	T8×29 1ケ (No compatible products)	※1 T10 3ケ (P145 ×2) (P141 ×2)	-	T8×29 1ケ (P143 ×1)	-	-	-	-	※1 Two sets are required, but the number used is three.
	2014.7-2020.6	F15	T10 3ケ (P406/P407 ×3)	-	T8×29 1ケ (No compatible products)	※1 T10 3ケ (P145 ×2) (P141 ×2)	-	T8×29 1ケ (P143 ×1)	-	-	-	-	※1 Two sets are required, but the number used is three.
			T10 3ケ (P406/P407 ×3)	-	T8×29 1ケ (No compatible products)	※1 T10 3ケ (P145 ×2) (P141 ×2)	-	T8×29 1ケ (P143 ×1)	-	-	-	-	※1 Two sets are required, but the number used is three.
silvia	1988.5-1993.9	S13	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	-	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	-	T10 1ケ (P406/P407 ×1)	-	-	-	
	1993.10-1998.12	S14	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	-	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	-	-	-	-	-	
	1999.1-2002.11	S15	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	-	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	-	-	-	-	-	
skyline ※Continue to next page	1993.8-1995.12 4door		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	-	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	-	-	-	-	-	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》		room lamp	《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
skyline ※Continue to next page	2door	R33	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1996.1-1998.4 4door		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2door		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1998.5-2000.7 4door	R34	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2door		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2000.8-2002.8 4door	R34	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》		room lamp	《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
skyline	2000.8-2002.8 2door	R34	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2001.6-2006.10 SEDAN	V35	T10×31 2ケ (P408/P409 ×2)	－	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P143 ×2)	－	T10×31 2ケ (P143 ×2)	－	－	－	－	
	2003.1-2005.10 coupe		T10×31 2ケ (P408/P409 ×2)	－	－	T10×31 2ケ (P143 ×2)	－	－	－	－	－	－	
	2005.11-2007.9 coupe		T10×31 2ケ (P408/P409 ×2)	－	－	T10×31 2ケ (P143 ×2)	－	－	－	－	－	－	
	2006.11- SEDAN	V36	T10 2ケ (P406/P407 ×2)	T10 2ケ (P406/P407 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	
	2007.10- coupe		T10 2ケ (P406/P407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	
	2014.2-2017.11	V37	※1 LED	T10 2ケ (P406/P407 ×2)	－	※1 LED	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	※1 Not applicable due to LED lamp
	2017.12-2019.8		※1 LED	T10 2ケ (P406/P407 ×2)	－	※1 LED	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	※1 Not applicable due to LED lamp
skyline crossover	2009.7-2016.6	J50	T10 2ケ (P406/P407 ×2)	T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
Skyline GT-R	1995.1-1998.12	R33	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※It is necessary to remove the metal plate inside the light fixture.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Skyline GT-R	1999.1-2002.8	R34	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	-	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	-	-	-	-	-	※1 It is necessary to remove the metal plate inside the light fixture.
	2000.10-2002.8		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	-	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	-	-	-	-	-	※1 It is necessary to remove the metal plate inside the light fixture.
GT-R	2007.12-2013.11	R35	T10 2ケ (P406/P407 ×2)	-	-	T10 2ケ (P145 ×1) (P141 ×1)	-	-	-	-	-	-	
	2013.12-2016.7		T10 2ケ (P406/P407 ×2)	-	-	T10 2ケ (P145 ×1) (P141 ×1)	-	-	-	-	-	-	
Stagea Continue to next page	1996.10-1998.7	C34	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	-	-	-	-	
	1998.8-2001.9		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	-	-	-	-	
	2001.10-2004.7	M35	T10×31 2ケ (P134 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	-	-	-	-	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Stagea	2004.8-2007.6	M35	T10×31 2ケ (P134 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
cedric	1991.6-1993.5	Y32	G14 2ケ (No compatible products)	※1 T10×31 2ケ (P408/P409 ×2)	－	G14 2ケ (No compatible products)	※1 T10×31 2ケ (P143 ×2)	－	－	－	－	－	※1 It is necessary to remove the metal plate inside the light fixture.
	1993.6-1995.5		G14 2ケ (No compatible products)	※1 T10×31 2ケ (P408/P409 ×2)	－	G14 2ケ (No compatible products)	※1 T10×31 2ケ (P143 ×2)	－	－	－	－	－	※1 It is necessary to remove the metal plate inside the light fixture.
	1995.6-1999.5	Y33	G14 2ケ (No compatible products)	※1 T10×31 2ケ (P408/P409 ×2)	－	G14 2ケ (No compatible products)	※1 T10×31 2ケ (P143 ×2)	－	－	－	－	－	※1 It is necessary to remove the metal plate inside the light fixture.
	1999.6-2004.10	Y34	G14 2ケ (No compatible products)	－	※ T10×31 2ケ (P408/P409 ×2)	G14 2ケ (No compatible products)	－	※1 T10×31 2ケ (P143 ×2)	－	－	－	－	※1 It is necessary to remove the metal plate inside the light fixture.
Cefiro ※Continue to next page	1994.8-1996.12	A32	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》		room lamp	《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Cefiro	1997.1-1998.1	A32	G14 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	-	G14 2ヶ (No compatible products)	T10×31 1ヶ (P143 ×1)	-	-	-	-	-	
	1998.12-2003.3	A33	G14 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	-	G14 2ヶ (No compatible products)	T10×31 1ヶ (P143 ×1)	-	-	-	-	-	
Cefiro Wagon	1997.6-2000.8	A32	G14 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P408/P409 ×1)	G14 2ヶ (No compatible products)	T10×31 1ヶ (P143 ×1)	T10×31 1ヶ (P143 ×1)	-	-	-	-	
Serena ※Continue to next page	1991.6-1996.12	C23	G14 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P408/P409 ×1)	G14 2ヶ (No compatible products)	T10×31 1ヶ (P143 ×1)	T10×31 1ヶ (P143 ×1)	-	-	-	-	
	1997.1-1997.12		G14 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P408/P409 ×1)	G14 2ヶ (No compatible products)	T10×31 1ヶ (P143 ×1)	T10×31 1ヶ (P143 ×1)	-	-	-	-	
	1998.1-1999.5		G14 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P408/P409 ×1)	G14 2ヶ (No compatible products)	T10×31 1ヶ (P143 ×1)	T10×31 1ヶ (P143 ×1)	-	-	-	-	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Serena	1999.6-2001.11	C24	G14 2ケ (No compatible products)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2001.12-2005.4		G14 2ケ (No compatible products)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2005.5-2010.11	C25	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2010.11-2013.11	C26 HC26.HFC26	T10 3ケ (P406/P407 ×3)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	※1 T10 3ケ (P145 ×2) (P141 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	※1 Two sets are required, but the number used is three.
	2013.12-2016.7		T10 3ケ (P406/P407 ×3)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	※1 T10 3ケ (P145 ×2) (P141 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	※1 Two sets are required, but the number used is three.
	2016.8-2019.7	C27.HC27	T13 2ケ (P406/P407 ×2)	T13 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	※1 T13 2ケ (P145 ×1) (P141 ×1)	※1 T13 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2019.8-2022.11	GC27.GFC27 HC27.HFC27	T13 2ケ (P406/P407 ×2)	T13 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	※1 T13 2ケ (P145 ×1) (P141 ×1)	※1 T13 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2022.12-	C28	※LED	※LED	※LED	※LED	※LED	※LED	－	－	－	－	※Not applicable as the interior is all LED.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
datsun pickup	1985.8-1996.12	D21	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
datsun pickup	1997.10-2002.8	D22	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
dayz	2013.6-2015.9	B21W	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
dayz	2015.10-H31.3	B21W	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
dayz	H31.3-	B4#	T10 3ケ (P406/P407 ×3)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 3ケ (P145 ×2) (P141 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 Two sets are required, but the number used is three.
dayz rooks	2014.2-2016.11	B21A	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
dayz rooks	2016.12-2020.2	B21A	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
Tiana	2003.2-2005.11	J31	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	－	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	－	－	－	－	－	
Tiana	2005.12-2008.5	J31	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	－	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	－	－	－	－	－	
Tiana	2008.6-2014.1	J32	T10 2ケ (P406/P407 ×2)	T10 2ケ (P406/P407 ×2)	－	※1 T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》		room lamp	《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Tiana	2014.2-2020.7	L32	※1 LED	T10 2ケ (P406/P407 ×2)	－	※1 LED	※1 T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	※1 Not applicable due to LED lamp
TIDA	2004.10-2007.12	C11	※1 T8×29 1ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	※1 T8×29 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	※1 LED lamp specifications available
	2008.1-2012.8		※1 T8×29 1ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	※1 T8×29 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	※1 LED lamp specifications available
TIDALatio	2004.10-	C11	※1 T8×29 1ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	※1 T8×29 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 LED lamp specifications available
Tino	1998.12-2003.5	V10	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/P407 ×1)	－	－	－	
Dualis	2007.5-	J10	T10 3ケ (P406/P407 ×3)	T10×31 2ケ (P408/P409 ×2)	－	※1 T10 3ケ (P145 ×2) (P141 ×2)	T10×31 2ケ (P143 ×2)	－	T10 1ケ (P406/P407 ×1)	－	－	－	
Terrano	1986.8-1995.8	WD21	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	1995.9-2002.8	R50	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》		room lamp	《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
terrano reglass	1996.8-2002.8	R50	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
notes	2005.1-2007.12	E11	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (適応品なし)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2008.1-2012.8		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (適応品なし)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2012.9-2016.10	E12	T10 1ケ (P406/P407 ×1)	T10 1ケ (P406/P407 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2016.11-2020.11	E12.HE12	T10 1ケ (P406/P407 ×1)	T10 1ケ (P406/P407 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10 1ケ (P406/P407 ×1)	－	－	－	Including e-POWER
	2020.12-	E13.SNE13	T13 2ケ (P406/P407 ×2)	T10 1ケ (P406/P407 ×1)	－	T13 2ケ (P145 ×2) (P141 ×2)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/P407 ×1)	－	－	－	Including e-POWER
Basara	1999.11-2003.6	U30	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P408/P409 ×2)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 2ケ (P143 ×2)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
banette van	1999.6-	SK#	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	-	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	-	-	-	-	-	
pulsar	1995.1-2000.8	N15	G14 1ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	-	G14 1ケ (No compatible products)	T10×31 1ケ (P143 ×1)	-	-	-	-	-	
Pulsar Serie (S-RV)	1996.5-2000.8	N15	G14 1ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	-	G14 1ケ (No compatible products)	T10×31 1ケ (P143 ×1)	-	-	-	-	-	
pino	2007.1-2010.2	HC24S	T10 1ケ (P406/P407 ×1)	-	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
fuga	2004.10-2009.10	Y50	G14 2ケ (No compatible products)	T10×31 2ケ (P408/P409 ×2)	-	G14 2ケ (No compatible products)	T10×31 2ケ (P143 ×2)	-	-	T10 2ケ (P406/407 ×2) (P145 ×1) (P141 ×1)	-	-	
	2009.11-2015.1	Y51	G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	-	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	-	-	T10 2ケ (P406/407 ×2) (P145 ×1) (P141 ×1)	-	-	
	2015.2-		G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	-	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	-	-	T10 2ケ (P406/407 ×2) (P145 ×1) (P141 ×1)	-	-	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》		room lamp	《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Fairlady Z	1989.7-1998.9	Z32	T5 2ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	－	T5 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	1 Cannot be installed due to limited space for the light fixture.
	1998.10-2000.8		T5 2ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	－	T5 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	1 Cannot be installed due to limited space for the light fixture.
	2002.7-2005.7	Z33	T10×31 2ケ (P408/P409 ×2)	－	－	T10×31 2ケ (P143 ×2)	－	－	T10side 1ケ (P404 ×1)	－	－	－	
	2005.8-2008.11		T10×31 2ケ (P408/P409 ×2)	－	－	T10×31 2ケ (P143 ×2)	－	－	T10side 1ケ (P404 ×1)	－	－	－	
	2008.12-2022.6	Z34	T10 2ケ (P406/P407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	
	2022.7-	RZ34	T10 2ケ (P406/P407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	T6.3×30 (No compatible products)	
Primera	1990.2-1995.8	P10	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1995.9-1998.8	P11	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Primera	1998.9-2000.12	P11	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Primera	2001.1-2005.12	P12	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Primera Camino	1995.9-1998.8	P11	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1998.9-2000.12		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
primera wagon	1997.9-2000.12	P11	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2001.1-2005.12	P12	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
bluebird	1991.9-1995.12	U13	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
bluebird	1996.1-2001.9	U14	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1997.9-2001.9	U14	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
bluebird sylphy	2000.8-2003.1	G10	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2003.2-2005.11		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2005.12-2009.4	G11	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2009.5-2012.12		T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
prairie liberty	1998.11-2001.4	M12	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
liberty	2001.5-2004.12	M12	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
Presage	1998.6-2001.8	U30	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P408/P409 ×2)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 2ケ (P143 ×2)	－	－	－	－	
	2001.8-2003.6		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P408/P409 ×2)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	T10×31 2ケ (P143 ×2)	－	－	－	－	
	2003.7-2009.8	U31	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
			T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	Vehicle equipped with large room lamp
president	1990.10-1998.11	G50	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1998.12-2003.9		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2003.10-2010.8	F50	G14 2ケ (No compatible products)	T10×31 2ケ (P408/P409 ×2)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》		room lamp	《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Presea	1995.1-1997.7	R11	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1997.8-2000.8		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
march	1992.1-1997.4	K11	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1997.5-1999.10	K11	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1999.11-2002.2		－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2002.3-2010.6	K12	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
	2010.7-2013.5	K13	T10 1ケ (P406/P407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
march	2013.6-	K13	T10 1ケ (P406/P407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Murano	2004.9-2008.8	Z50	T10×31 2ケ (P134 ×2)	T10×31 1ケ (P408/P409 ×1) T10×31 2ケ (P408/P409 ×2)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1) T10×31 2ケ (P143 ×2)	－	－	－	－	－	
	2008.9-2011.1	Z51	T10 2ケ (P406/P407 ×2)	T10 2ケ (P406/P407 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	
	2011.2-2015.4		T10 2ケ (P406/P407 ×2)	T10 2ケ (P406/P407 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	
Moco	2002.4～2006.1	MG21S	T10 1ケ (P406/P407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2006.2～2011.2	MG22S	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2011.2-2016.5	MG33S	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
			T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
Racine	1994.12～1996.12	NB14	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10 1ケ (P406/P407 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			room lamp Recommended《CSP plate type》			room lamp 《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Racine	1997.1-2000.8	NB14	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10 1ケ (P406/P407 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Lafesta	2004.12～2012.12	B30	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	
LaFesta Highway Star	2011.6～2018.3	CWE#WN	※1 T10 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 Plate type cannot be installed at the front of the room.
largo	1993.5～1996.9	W30	G14 2ケ (No compatible products) T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products) T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
			G14 2ケ (No compatible products) T10×31 1ケ (P408/P409 ×1)	※fluorescent lighting	－	G14 2ケ (No compatible products) T10×31 1ケ	※ fluorescent lighting	－	－	－	－	－	Car with panoramic view top ※Not applicable due to fluorescent lighting
	1996.10～1999.6	W30	G14 2ケ (No compatible products) T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products) T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	highway star touring
			G14 2ケ (No compatible products) T10×31 1ケ (P408/P409 ×1)	※fluorescent lighting	－	G14 2ケ (No compatible products) T10×31 1ケ (P143 ×1)	※ fluorescent lighting	－	－	－	－	－	highway star touring Car with panoramic view top ※Not applicable due to fluorescent lighting

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》		room lamp	《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
leaf	2010.12-2012.10	ZE0	T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
	2012.11-2017.9	AZE0	※1 LED	T10×31 1ケ (P408/P409 ×1)	－	※1 LED	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	※1 Not applicable due to LED lamp
	2017.10-	ZE1	T13 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/P407 ×1)	－	－	－	
rooks	2009.12-2013.3	ML21S	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2020.3-	B4#	※1 T10 3ケ (P406/P407 ×3)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 3ケ (P145 ×2) (P141 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 Two sets are required, but the number used is three.
Renessa	1997.10～2001.6	N30	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
leopard	1996.3～1999.6	Y33	G14 2ケ (No compatible products)	－	T10×31 1ケ (P408/P409 ×1)	G14 2ケ (No compatible products)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
laurel	1993.1～1993.12	C34	G14 2ケ (No compatible products)	－	G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	G14 2ケ (No compatible products)	－	－	－	－	
※Continue to next page	1994.1-1997.5		G14 2ケ (No compatible products)	－	G14 2ケ (No compatible products)	G14 2ケ (No compatible products)	－	G14 2ケ (No compatible products)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
laurel	1997.6～1999.7	C35	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
			G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1999.8～2003.1	C35	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
			G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
180SX	1989.4～1996.7	S13	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/P407 ×1)	－	－	－	
	1996.8-1998.12		G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/P407 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
acti	1999.5-2018.6	H1993.6	－	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
acti track	1999.5-2009.11	HA6.7	－	T10side 1ケ (P404 ×1)	T16 1ケ (No applicable products)	－	T10side 1ケ (P404 ×1)	T16 1ケ (No applicable products)	－	－	－	－	
	2009.12-2021.4	HA8.9	－	T10side 1ケ (P404 ×1)	T16 1ケ (No applicable products)	－	T10side 1ケ (P404 ×1)	T16 1ケ (No applicable products)	－	－	－	－	
accord	2008.12-2013.3	CU1.2	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
accord hybrid	2013.6～2016.4	CR6	T10 2ケ (P406/P407 ×2)	T10 1ケ (P406/P407 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2016.5～2020.1	CR7	※1 LED	※1 LED	－	※1 LED	※1 LED	－	T10side 1ケ (P404 ×1)	※1 LED	－	－	※1 Not applicable due to LED lamp
	2020.2～	CV3	※1 LED	※1 LED	－	※1 LED	※1 LED	－	T10side 1ケ (P404 ×1)	※1 LED	－	－	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA

Car model	model year	model	room lamp Recommended《CSP plate type》 front	room lamp center	room lamp rear	room lamp 《valve type》 front	room lamp center	room lamp rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
accord tourer	2008.12-	CW1.2	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	-	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	-	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	-	-	
insight	1999.11-2006.6	ZE1	T10 1ケ (P406/407 ×1) T10 2ケ (P406/407 ×2)	-	-	※1 T10 1ケ (P145 ×1) T10 2ケ (P145 ×2)	-	-	T8×29 1ケ (P143 ×1)	-	-	-	※1 Two sets are required, but the number used is three.
	2009.2-	ZE2.3	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	-	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	-	T10side 1ケ (P404/405 ×1)	-	-	-	
	2018.12-	ZE4	※1 LED	※1 LED	-	※1 LED	※1 LED	-	T10side 1ケ (P404/405 ×1)				※1 Not applicable due to LED lamp
inspire	2003.6-2005.10	UC1	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	-	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	-	-	-	-	-	
	2005.11-2007.11		T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	-	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	-	-	-	-	-	
	2007.12-	CP3	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	-	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	-	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	-	-	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Integra	1993.5-2001.6	DB6.7.8.9 DC1.2	T8×29 2ケ (No compatible products)	T8×29 1ケ (No compatible products)	－	T8×29 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
	2001.7-2004.8	DC5	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	2004.9-2007.2	DC5	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
Integra TYPE-R	1993.5-2001.6	DB6.7.8.9 DC1.2	T8×29 2ケ (No compatible products)	T8×29 1ケ (No compatible products)	－	T8×29 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
	2001.7-2004.8	DC5	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			room lamp Recommended《CSP plate type》			room lamp 《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Integra TYPE-R	2004.9-2007.2	DC5	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
vezel	2014.12-2018.1	RU1.2.3.4	※1 LED	※1 LED	－	※1 LED	※1 LED	－	T10side 1ケ (P404 ×1)	－	－	－	※1 Not applicable due to LED lamp
	2018.2-2021.4		※1 LED	※1 LED	－	※1 LED	※1 LED	－	T10side 1ケ (P404 ×1)	－	－	－	※1 Not applicable due to LED lamp
	2021.4-	RV3.4.5.6	※1 LED	※1 LED	－	※1 LED	※1 LED	－	※1 LED	－	－	ASSY (Not replaceable)	
S2000	1999.4-2009.9	AP1.2	T8×29 2ケ (No compatible products)	－	－	T8×29 2ケ (P143 ×2)	－	－	T10 1ケ (P406/P407 ×1)	－	－	－	
	2003.10-2009.9	AP1.2	T8×29 2ケ (No compatible products)	－	－	T8×29 2ケ (P143 ×2)	－	－	T10 1ケ (P406/P407 ×1)	－	－	－	
S600	2015.3-2019.12	JW5	T10side 1ケ (P404 ×1)	－	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2020.1-2021.12		T10side 1ケ (P404 ×1)	－	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
			※1 LED	－	－	※1 LED	－	－	－	－	－	－	※1 α、moduloX、Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA

Car model	model year	model	room lamp Recommended《CSP plate type》 front	room lamp center	room lamp rear	room lamp 《valve type》 front	room lamp center	room lamp rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
Edix	2004.7-2009.8	BE1.2.3.4	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
NSX	1990.9-2005.12	NA1.2	T8×29 2ケ (No compatible products)	－	－	T8×29 2ケ (P143 ×2)	－	－	－	－	－	－	
	2017.2-	NC1	※1 LED	－	－	※1 LED	－	－	※1 LED	－	－	－	※1 Not applicable due to LED lamp
N BOX	2011.12-2013.11	JF1.2	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2013.12-2017.7		T10 2ケ (P406/P407 ×2)	－	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2017.8-2023.9	JF3.4	T10 2ケ (P406/P407 ×2)	－	T10×31 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2023.10-	JF5.6	T10 2ケ (P406/P407 ×2)	T10 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	T10side 1ケ (P404/405 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
N BOX custom	2011.12-2013.11	JF1.2	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2013.12-2017.7		T10 2ケ (P406/P407 ×2)	－	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
			※1 LED 2ケ (P406/P407 ×2)	－	※1 LED 1ケ (P404 ×1)	※1 LED 2ケ (P145 ×1) (P141 ×1)	－	※1.2 LED 1ケ(P145 ×1) (P141 ×1)	－	－	－	－	※1LED bulb、replaceable ※2 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			room lamp Recommended《CSP plate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
N BOX custom	2017.8-2023.9	JF3.4	※1 LED	－	※1 LED	※1 LED	－	※1 LED	－	－	－	－	※1 Not applicable due to LED lamp
	2023.10-	JF5.6	T10 2ケ (P406/P407 ×2)	T10 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	T10side 1ケ (P404 ×1)				※1 It comes in 2 pieces, but only 1 piece is used.
N-BOX SLASH	2014.12-2020.2	JF1.2	T10 2ケ (P406/P407 ×2)	－	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
			※1 LED 2ケ (P406/P407 ×2)	－	※1 LED 1ケ (P404 ×1)	※1 LED 2ケ (P145 ×1) (P141 ×1)	－	※1.2 LED 1ケ(P145 ×1) (P141 ×1)	－	－	－	－	※1LED bulb、replaceable ※2 It comes in 2 pieces, but only 1 piece is used.
N-BOX +	2012.7-2013.11	JF1.2	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P408/P409 ×1)	－	－	－	
	2013.12-2018.3		T10 2ケ (P406/P407 ×2)	－	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	T10side 1ケ (P404 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
N-BOX + custom	2012.7-2013.11	JF1.2	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P408/P409 ×1)	－	－	－	
	2013.12-2018.3	JF1.2	※1 LED 2ケ (P406/P407 ×2)	－	※1 LED 1ケ (P404 ×1)	※1 LED 2ケ (P145 ×1) (P141 ×1)	－	※1.2 LED 1ケ(P145 ×1) (P141 ×1)	※1 LED 1ケ (P404 ×1)	－	－	－	※1LED bulb、replaceable ※2 It comes in 2 pieces, but only 1 piece is used.
N-VAN	2018.7-	JJ1.2	T10side 1ケ (P404 ×1)	－	T10side 1ケ (P404 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	T10side 1ケ (P404 ×1)	－	－	－	Ggrade ※1 It comes in 2 pieces, but only 1 piece is used.
			T10 2ケ (P406/P407 ×2)	※1 T10 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1.2 T10side 1ケ (P145 ×1) (P141 ×1)	※1.2 T10side 1ケ (P145 ×1) (P141 ×1)	T10side 1ケ (P404 ×1)	－	－	－	Lgrade ※1 passenger seat interior light ※2 It comes in 2 pieces, but only 1 piece is used.
			※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	－	－	－	+STYLE FUN.+STYLE COOL ※1LED bulb、replaceable(Lgrade参照)

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
N-WGN	2013.11-2019.7	J1989.2	T10side 1ケ (P404 ×1)	－	T10side 1ケ (P404 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2019.8-	J1991.4	T10side 1ケ (P404 ×1)	－	T10side 1ケ (P404 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
N-WGN custom	2013.11-2019.7	J1989.2	T10 1ケ (P406/P407 ×1)	－	T10 1ケ (P406/P407 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2019.8-	J1991.4	※1 LED	－	※1 LED	※1 LED	－	※1 LED	－	－	－	－	※1LED bulb、replaceable
N-ONE	2012.11-2020.10	JG1.2	T10side 1ケ (P404 ×1)	－	T10side 1ケ (P404 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2014.4-2020.10		※1 LED 1ケ (P404 ×1)	－	※1 LED 1ケ (P404 ×1)	※1.2 LED 1ケ (P145 ×1) (P141 ×1)	－	※1.2 LED 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	Premium ※1LED bulb、replaceable ※2 It comes in 2 pieces, but only 1 piece is used.
	2020.11-	JG3.4	T10side 1ケ (P404 ×1)	－	T10side 1ケ (P404 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
			※1 LED	－	※1 LED	※1 LED	－	※1 LED	－	－	－	－	Premium ※1 Not applicable due to LED lamp
Elysium	2004.5-2012.5	R2019.2.3.4	T10×31 2ケ (P408/P409 ×2)	T10 2ケ (P406/P407 ×2)	T10 2ケ (P406/P407 ×2)	T10×31 2ケ (P143 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 1ケ (P406/P407 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	
Elysion Prestige	2007.1-2013.10	R2019.2.5.6	T10×31 2ケ (P408/P409 ×2)	T10 2ケ (P406/P407 ×2)	T10 2ケ (P406/P407 ×2)	T10×31 2ケ (P143 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 1ケ (P406/P407 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
odyssey	2003.10-2006.3	RB1.2	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10side 1ケ (P404 ×1)	T10side 2ケ (P404 ×2)	－	－	
	2006.4-2008.9		T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10side 1ケ (P404 ×1)	T10side 2ケ (P404 ×2)	－	－	
	2008.9-2013.10	RB3.4	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
	2013.11-2020.10	RC1.2.4	T10 2ケ (P406/P407 ×2)	T10 2ケ (P406/P407 ×2)	T10 2ケ (P406/P407 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
			※1 LED	※2 LED 2ケ (P404 ×2)	※2 LED 2ケ (P404 ×2)	※1 LED	※2 LED 2ケ (P145 ×1) (P141 ×1)	※2 LED 2ケ (P145 ×1) (P141 ×1)	T10side 1ケ (P404 ×1)	－	－	－	※1 Not applicable due to LED lamp ※2LED bulb、replaceable(上段参照)
	2020.11-2022.9		※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	T10side 1ケ (P404 ×1)	－	－	－	※1 Not applicable due to LED lamp
	2023.12-	RC5	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	T10side 1ケ (P404 ×1)	－	－	－	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA

Car model	model year	model	room lamp Recommended《CSP plate type》 front	room lamp center	room lamp rear	room lamp 《valve type》 front	room lamp center	room lamp rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
That's	2002.2-	JD1.2	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
clarity	2016.3-2018.6	ZC4	※1 LED	※1 LED	－	※1 LED	※1 LED	－	－	－	－	－	※1 Not applicable due to LED lamp
clarityPHEV	2018.7-	ZC5	※1 LED	※1 LED	－	※1 LED	※1 LED	－	－	－	－	－	※1 Not applicable due to LED lamp
grace	2014.12-2017.6	GM4.5.6.7	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2017.7-2020.7		T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
CR-V	1995.10-2001.8	RD1.2	T8×29 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T8×29 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2001.9-2004.8	RD4.5	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			room lamp Recommended《CSP plate type》			room lamp 《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
CR-V	2004.9-2006.9	RD6.7	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2006.10-2011.12	RE3.4	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2011.12-2016.8	RM1.4	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P134 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
			T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 x1)	T10side 1ケ (P404 x1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 x1) (P141 x1)	※1 T10side 1ケ (P145 x1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2018.9-2020.5	RT5.6 RW1.2	※1 LED	※1 LED	－	※1 LED	※1 LED	－	T10 1ケ (P404 ×1)	－	－	－	※1 Not applicable due to LED lamp
	2020.6-		※1 LED	※1 LED	－	※1 LED	※1 LED	－	T10 1ケ (P404 ×1)	－	－	－	※1 Not applicable due to LED lamp
CR-Z	2010.2-2012.8	ZF1	T10×31 2ケ (P408/P409 ×2)	－	－	T10×31 2ケ (P143 ×2)	－	－	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	
	2012.9-2015.9	ZF2	T10×31 2ケ (P408/P409 ×2)	－	－	T10×31 2ケ (P143 ×2)	－	－	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
CR-Z	2015.10-2017.1	ZF2	※1 LED	－	－	※1 LED	－	－	T10side 1ケ (P404 ×1)	※1 LED	－	－	※1 Not applicable due to LED lamp
shuttle	2015.5-H31.4	GK8.9	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 x1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 x1) (P141 x1)	－	T10side 1ケ (P404 x1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2019.5-		※1 LED	※1 LED	－	※1 LED	※1 LED	－	※1 LED	－	－	－	※1 Not applicable due to LED lamp
shuttle hybrid	2015.5-H31.4	GP7.8	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 x1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 x1) (P141 x1)	－	T10side 1ケ (P404 x1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2019.5-		※1 LED	※1 LED	－	※1 LED	※1 LED	－	※1 LED	－	－	－	※1 Not applicable due to LED lamp
jade	2015.2-2018.4	F2022.5	※1 LED	T10side 1ケ (P404 x1)	T10side 1ケ (P404 x1)	※1 LED	※2 T10side 1ケ (P145 x1) (P141 x1)	－	T10side 1ケ (P404 x1)	－	－	－	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2018.5-		※1 LED	T10side 1ケ (P404 x1)	T10side 1ケ (P404 x1)	※1 LED	※2 T10side 1ケ (P145 x1) (P141 x1)	－	T10side 1ケ (P404 x1)	－	－	－	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
civic	2005.9-2010.12	FD1.2	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
civic hybrid	2005.9-2010.12	FD3	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 x1)	T10side 2ケ (P404 ×2)	－	－	
civic SEDAN	2017.7-2019.12	FC1	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 x1) (P141 x1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
civic SEDAN	2020.1-2021.9	FC1	※1 LED	※1 LED	－	※1 LED	※1 LED	－	－	－	－	－	※1 Not applicable due to LED lamp
civic hatchback	2017.7-2019.12	FK7	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 x1) (P141 x1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2020.1-2021.9		※1 LED	※1 LED	－	※1 LED	※1 LED	－	－	－	－	－	※1 Not applicable due to LED lamp
civic TYPE-R	2007.3-2010.12	FD2	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2015.10-2016.6	FK2	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 x1) (P141 x1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2017.7-	FK8	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 x1) (P141 x1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
civic TYPE-R EUR	2009.11-2012.6	FN2	T10 2ケ (P404 ×1)	T10×31 1ケ (P406/P407 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
step wagon ※Continue to next page	1996.5-1999.4	RF1.2	T8×29 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	T8×29 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
			T10 1ケ (P406/P407 ×1) T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	－	※1 T10 1ケ (P145 ×1) T10 2ケ (P145 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	Car with sunroof ※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
step wagon	1999.5-2001.3		T8×29 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	T8×29 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	
			T10 1ケ (P406/P407 ×1) T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	－	※1 T10 1ケ (P145 ×1) T10 2ケ (P145 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	Car with sunroof ※1 It comes in 2 pieces, but only 1 piece is used.
	2001.4-2005.4	RF3.4.5.6.7.8	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2005.5-2009.9	RG1.2.3.4	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	
			T10×31 2ケ (P408/P409 ×2)	T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	top light roof car

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			room lamp Recommended《CSP plate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
step wagon	2009.10-2015.3	RK1.2.5.6	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	
	2015.4-2017.8	RP1.2.3.4	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2017.9-2022.4		T10 2ケ (P406/P407 ×2)	T10 1ケ (P404 ×1)	T10 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
			※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	－	－	－	－	※1 Not applicable due to LED lamp
	2020.1-2022.4	RP5	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	－	－	－	－	hybrid ※1 Not applicable due to LED lamp
	2022.5-	RP6.7.8	※1 LED	T10 1ケ (P404 ×1)	T10 1ケ (P404 ×1)	※1 LED	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	T10 2ケ (P406/P407 ×2)	T6.3×31 (No applicable products)	※1 Not applicable due to LED lamp
stream	2000.10-2006.6	RN1.2.3.4.5	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	
	2006.7-2014.5	RN6.7.8.9	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	
zest	2006.3-2012.11	JE1.2	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			room lamp Recommended《CSP plate type》			room lamp《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
zest spark	2008.12-2012..	JE1.2	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
ZR-V	2022.4-	RZ3.4.5.6	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	－	－	－	－	※1 Not applicable due to LED lamp
Vamos	1999.6-2018.5	HM1.2	T8×29 2ケ (P408/P409 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T8×29 2ケ (P143 ×2)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Vamoshobio	2003.4-2018.5	HM3.4	T10×31 2ケ (P408/P409 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10×31 2ケ (P143 ×2)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
beat	1991.5-1995.10	PP1	－	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
fit ※Continue to next page	2001.6-2007.9	GD1.2.3.4	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
fit	2007.10-2013.8	GE6.7.8.9	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	2013.9-2017.5	GK3.4.5.6	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2017.6-2020.1	GK3.4.5.6	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2020.2-	G2019.2.5.7	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
			※1 LED	※1 LED	－	※1 LED	※1 LED	－	－	－	－	－	※1 Not applicable due to LED lamp
fit aria	2002.12-2009.1	GD6.7.8.9	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
fit hybrid	2010.10-2013.8	GP1	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	2013.9-2020.1	GP5.6	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2020.2-	G2021.4.6.8	T10 2ケ (P406/P407 ×2)	T10 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
			※1 LED	※1 LED	－	※1 LED	※1 LED	－	T10side 1ケ (P404 ×1)	－	－	－	※1 Not applicable due to LED lamp
fit shuttle	2011.6-	GG7.8	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T10side 1ケ (P404 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			room lamp Recommended《CSP plate type》			room lamp 《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
fit shuttle hybrid	2011.6-	GP2	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
freed	2008.5-2014.3	GB3.4	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
			T10×31 2ケ (P408/P409 ×2)	T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	Car with sunroof
	2014.4-2016.8		T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)					※1 It comes in 2 pieces, but only 1 piece is used.
	2016.9-	GB5.6	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)					※1 It comes in 2 pieces, but only 1 piece is used.
freed hybrid	2011.10-2014.3	GP3	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2014.4-2016.8		T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2016.9-	GB7.8	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
freed spike	2010.7-2014.3	GB3.4	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
			T10×31 2ケ (P408/P409 ×2)	T10 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	Car with sunroof
	2014.4-2016.8		T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
freed spike hybrid	2011.10-2014.3	GP3	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2014.4-2016.8	GP3	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
freed+	2016.9-	GB5.6	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
freed+ hybrid	2016.9-	GB7.8	T10 2ケ (P406/P407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Mobilio	2001.12-2003.12	GB1.2	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2004.1-2008.4	GB1.2	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
mobilio spike	2002.9-2005.11	GK1.2	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2005.12-2008.4		T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			room lamp Recommended《CSP plate type》			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
life	1997.4-1998.9	JA4	－	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
	1998.10-2001.4	JB1.2	－	T10side 1ケ (P404 ×1)	－	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2001.5-2004.9		－	T10side 1ケ (P404 ×1)	－	－	※1 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2004.10-2006.9	JB5.6.7.8	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2006.10-2008.10	JB5.6.7.8	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2008.11-	JC1.2	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			room lamp Recommended《CSP plate type》			room lamp 《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
lifeDIVA	2003.9-2008.10	JB5.6.7.8	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2008.11-2010.10	JC1.2	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	
	2010.11-2014.4	JC1.2	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	
life pastel	2008.11-2010.11	JC1.2	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	
legend	2004.10-2008.8	KB1	T10side 2ケ (P404 ×2)	－	※1 T10×31 2ケ (No compatible products)	T10side 2ケ (P145 ×1) (P141 ×2)	－	T10×31 2ケ (P143 ×2)	※2 T10side 2ケ (P404 ×2)	T10 2ケ (P141 ×1)	－	－	※1Cannot be installed due to limited space ※2 It is attached to 1 piece inside the trunk and 1 piece to the trunk lid.
	2008.9-2014.10	KB2	T10side 2ケ (P404 ×2)	－	※1 T10×31 2ケ (No compatible products)	T10side 2ケ (P145 ×1) (P141 ×2)	－	T10×31 2ケ (P143 ×2)	※2 T10side 2ケ (P404 ×2)	T10 2ケ (P141 ×1)	－	－	※1Cannot be installed due to limited space ※2 It is attached to 1 piece inside the trunk and 1 piece to the trunk lid.
	2014.11-2018.1	KC2	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	－	－	－	※1 Not applicable due to LED lamp
	2018.2-		※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	－	－	－	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MITSUBISHI

Car model	model year	model	room lamp Recommended《CSP plate type》 front	room lamp center	room lamp rear	room lamp《valve type》 front	room lamp center	room lamp rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
i	2006.1-2013.9	HA1W	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
i-MiEV	2009.7-2018.3	HA3W	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2018.4-	HD4	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
RVR	1991.2-1997.10	N1# N2#	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	1997.11-2002.8	N6# N7#	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/P409 ×1)	T8×29 2ケ (No compatible products)	※1 T10 3ケ (P141 ×2)	T10×31 1ケ (P143 ×1)	T8×29 2ケ (P143 ×2)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
			T10×31 1ケ (P408/409 ×1) T13 2ケ (P406/407 ×2)	T10×31 1ケ (P408/P409 ×1)	T8×29 2ケ (No compatible products)	T10×31 1ケ (P143 ×1) T13 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T8×29 2ケ (P143 ×2)	－	－	－	－	Car with sunroof
	2010.2-	GA3W.GA4W	※1 T10×31 2ケ (P408/P409 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	－	※2 T10×31 2ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	－	T10side 1ケ (P404 ×1)	－	－	－	※1 Depending on the individual vehicle, symptoms such as flashing or not turning off when the key is turned off may occur. ※2 Not applicable as it may cause symptoms such as flashing or not turning off when the key is turned off.
RVRsports gear	1997.11-2002.8	N6# N7#	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/P409 ×1)	T8×29 2ケ (No compatible products)	※1 T10 3ケ (P141 ×2)	T10×31 1ケ (P143 ×1)	T8×29 2ケ (P143 ×2)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
			T10×31 1ケ (P408/409 ×1) T13 2ケ (P406/407 ×2)	T10×31 1ケ (P408/P409 ×1)	T8×29 2ケ (No compatible products)	T10×31 1ケ (P143 ×1) T13 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T8×29 2ケ (P143 ×2)	－	－	－	－	Car with sunroof
outlander ※Continue to next page	2005.10-2012.9	CW4W.5W.6W	※1 T10×31 2ケ (P408/P409 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	※1 T10×31 1ケ (P408/P409 ×1)	※2 T10×31 2ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	－	－	－	－	※1 Depending on the individual vehicle, symptoms such as flashing or not turning off when the key is turned off may occur. ※2 Not applicable as it may cause symptoms such as flashing or not turning off when the key is turned off.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MITSUBISHI

Car model	model year	model	room lamp Recommended《CSP plate type》 front	room lamp center	room lamp rear	room lamp 《valve type》 front	room lamp center	room lamp rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
outlander	2012.10-2015.5	GF7W.8W	※1 T10×31 2ケ (P408/P409 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	※1 T10×31 1ケ (P408/P409 ×1)	※2 T10×31 2ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	－	－	－	－	※1 Depending on the individual vehicle, symptoms such as flashing or not turning off when the key is turned off may occur. ※2 Not applicable as it may cause symptoms such as flashing or not turning off when the key is turned off.
	2015.6-2020.12	GF7W.8W	※1 T10×31 2ケ (P408/P409 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	※1 T10×31 1ケ (P408/P409 ×1)	※2 T10×31 2ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	－	－	－	－	※1 Depending on the individual vehicle, symptoms such as flashing or not turning off when the key is turned off may occur. ※2 Not applicable as it may cause symptoms such as flashing or not turning off when the key is turned off.
outlanderPHEV	GG2W	2012.12-2015.6	※1 T10×31 2ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	※1 T10×31 2ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	－	－	－	－	※1 If you replace it with an LED product, it may not work properly, so it is not suitable.
		2015.7-2018.7	※1 T10×31 2ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	※1 T10×31 2ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	－	－	－	－	※1 If you replace it with an LED product, it may not work properly, so it is not suitable.
	GG3W	2018.8-2021.11	※1 T10×31 2ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	※1 T10×31 2ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	※1 T10×31 1ケ (No compatible products)	－	－	－	－	※1 If you replace it with an LED product, it may not work properly, so it is not suitable.
	GN0W	2021.12-	※1 T10 2ケ (No compatible products)	※1 T10 2ケ (No compatible products)	－	※1 T10 2ケ (No compatible products)	※1 T10 2ケ (No compatible products)	－	※1 T10 1ケ (No compatible products)	－	－	※1 T10 2ケ (No compatible products)	※1 If you replace it with an LED product, it may not work properly, so it is not suitable.
eKactive	2004.5-2006.9	H81W	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
ekcustom	2013.8-H31.2	B11W	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)					
eKClassy	2003.5-2005.12	H81W	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
ekcross	H31.3-	B34W.35W 37W.38W	T10 3ケ (P406/P407 ×3)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 3ケ (P145 ×2) (P141 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in a pack of 4, but only 3 are used.
ekcross space	2020.3-	B34A.35A 37A.38A	T10 3ケ (P406/P407 ×3)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 3ケ (P145 ×2) (P141 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in a pack of 4, but only 3 are used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

MITSUBISHI			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
ekspace (custom)	2014.2-2020.2	B11A	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	1 T10 2ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	include custom
	2020.3-	B34A.35A 37A.38A	T10 3ケ (P406/P407 ×3)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 3ケ (P145 ×2) (P141 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in a pack of 4, but only 3 are used.
eksports	2002.9-2006.8	H81W	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2006.9-2013.5	H82W	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
eKwagon	2001.10-2006.8	H81W	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2006.9-2013.6	H82W	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2013.7-H31.2	B11W	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	H31.3-	B33W.36W	T10 3ケ (P406/407 ×3)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 3ケ (P145 ×2) (P141 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in a pack of 4, but only 3 are used.
Airtrek	2001.6-2005.10	CU#W	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 3ケ (P141 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in a pack of 4, but only 3 are used.
airtrek sports gear	2003.1-2005.10	CU4W CU5W	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 3ケ (P141 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in a pack of 4, but only 3 are used.
eclipse	1989.9-1995.5	D22A D27A	T10×31 4ケ (P408/409 ×4)	－	－	T10×31 4ケ (P143 ×4)	－	－	－	－	－	－	
	1995.6-2000.9	D32A	T10×31 2ケ (P408/409 ×2)	－	－	T10×31 2ケ (P143 ×2)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	
eclipse spider	2004.10-2006.4	D53A	ヒューズ球 (No compatible products)	－	－	ヒューズ球 (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MITSUBISHI

Car model	model year	model	room lamp Recommended《CSP plate type》 front	room lamp Recommended《CSP plate type》 center	room lamp Recommended《CSP plate type》 rear	room lamp 《valve type》 front	room lamp 《valve type》 center	room lamp 《valve type》 rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
eclipse cross Including PHEV	2018.3-	GK1W.GL3W	※1 T13 2ケ (P406/P407 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	－	※2 T13 2ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	－	T10side 1ケ (P404 ×1)	－	－	－	※1 Depending on the individual vehicle, symptoms such as flashing or not turning off when the key is turned off may occur. ※2 Not applicable as it may cause symptoms such as flashing or not turning off when the key is turned off.
FTO	1994.10-2000.9	DE2A DE3A	ヒューズ球 (No compatible products)	－	－	ヒューズ球 (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	
Galant	1996.8-2005.11	EA# EC#	T10×31 2ケ (P408/409 ×2)	－	T10×31 2ケ (P408/409 ×2)	T10×31 2ケ (P143 ×2)	－	T10×31 2ケ (P143 ×2)	－	－	－	－	
			T10×31 1ケ (P408/409 ×1) T13 2ケ (P406/407 ×2)	－	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P143 ×1) T13 2ケ (P145 ×1) (P141 ×1)	－	T10×31 2ケ (P143 ×2)	－	－	－	－	Car with sunroof
galant fortis	2007.8-2015.3	CY4A	※1 T13 2ケ (P406/P407 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	－	※2 T13 2ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	－	－	－	－	－	※1 Depending on the individual vehicle, symptoms such as flashing or not turning off when the key is turned off may occur. ※2 Not applicable as it may cause symptoms such as flashing or not turning off when the key is turned off.
galant fortis sportsback	2008.12-2015.3	CX4A	※1 T13 2ケ (P406/P407 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	－	※2 T13 2ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	－	－	－	－	－	※1 Depending on the individual vehicle, symptoms such as flashing or not turning off when the key is turned off may occur. ※2 Not applicable as it may cause symptoms such as flashing or not turning off when the key is turned off.
Colt	2002.11-2012.10	Z2#A	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
colt ralliart version R	2006.5-2012.10	Z27AG	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
colt plus	2004.10-2012.10	Z2#W	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
GTO	1990.10-2000.9	Z15A Z16A	T10×31 2ケ (P408/409 ×2) T10×31 2ケ (P408/409 ×2)	－	－	T10×31 2ケ (P143 ×) T10×31 2ケ (P143 ×2)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MITSUBISHI

Car model	model year	model	room lamp Recommended《CSP plate type》 front	room lamp center	room lamp rear	room lamp《valve type》 front	room lamp center	room lamp rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
Chariot Grandis	1997.10-2003.4	N8#.9#	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/P409 ×1)	T8×29 2ケ (No compatible products)	※1 T13 1ケ (P141 ×1) ※1 T13 2ケ (P141 ×1)	T10×31 1ケ (P143 ×1)	T8×29 2ケ (P143 ×2)	－	－	－	－	※1 It comes in a pack of 4, but only 3 are used.
			T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/P409 ×1)	T8×29 2ケ (No compatible products)	※1 T13 1ケ (P141 ×1) ※1 T13 2ケ (P141 ×1)	T10×31 1ケ (P143 ×1)	T8×29 2ケ (P143 ×2)	－	－	－	－	Vehicles with HID ※1 It comes in a pack of 4, but only 3 are used.
Grandis	2003.5-2009.3	NA4W	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	－	－	－	－	
grandis sports gear	2005.6-2009.3	NA4W	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	－	－	－	－	
townBOX	1999.4-2011.11	U6#	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2014.2-2015.3	DS64W	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2015.3-	DS17W	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
town box wide	1999.6-2001.6	U6#	T10×31 2ケ (P408/P409 ×2)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
Diamante	1995.1-2005.12	F3#.4#	T10×31 1ケ (P408/409 ×1) T13 2ケ (P406/407 ×2)	－	T13 2ケ (P406/407 ×2)	T10×31 1ケ (P143 ×1) T13 2ケ (P145 ×1) (P141 ×1)	－	T13 2ケ (P145 ×1) (P141 ×1)	T8×29 2ケ (P143 ×2)	－	－	－	
diamante wagon	1997.10-2001.10	F36W	T10×31 1ケ (P408/409 ×1) T13 2ケ (P406/407 ×2)	T13 2ケ (P406/407 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1) T13 2ケ (P145 ×1) (P141 ×1)	T13 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
Dion	2000.1-2006.3	CR#W	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	※1 T13 1ケ (P141 ×1) ※1 T13 2ケ (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in a pack of 4, but only 3 are used.
Tignity	2012.7-2016.12		G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	－	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	
Delica star wagon	1990.8-1999.10	L03#.06# P01#.02#.03#.04#	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

MITSUBISHI

Car model	model year	model	room lamp Recommended《CSP plate type》 front	room lamp center	room lamp rear	room lamp 《valve type》 front	room lamp center	room lamp rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
delica van	1999.11-2011.9	SK#	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2011.10-2019.4	BVM20	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	
delica space gear	1994.5-2004.9	P##W	※1 T10×31 2ケ (P408/P409 ×2)	※2 T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	※1 T10×31 2ケ (P143 ×2)	※2 T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 There is one vehicle in the front of the room Map lamp is unconfirmed. ※2 Not applicable for vehicles with fluorescent lighting
			T10×31 1ケ (P408/P409 ×1) T13 2ケ (P406/407 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1) T13 2ケ (P145 ×1) (P141 ×1)	※1 T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	Car with sunroof ※1 Not applicable for vehicles with fluorescent lighting
	2004.10-2005.10	P##W	※1 T10×31 2ケ (P408/P409 ×2)	※2 T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	※1 T10×31 2ケ (P143 ×2)	※2 T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 There is one vehicle in the front of the room Map lamp is unconfirmed. ※2 Not applicable for vehicles with fluorescent lighting
			T10×31 1ケ (P408/P409 ×1) T13 2ケ (P406/407 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1) T13 2ケ (P145 ×1) (P141 ×1)	※1 T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	Car with sunroof ※1Not applicable for vehicles with fluorescent lighting
	2005.11-2006.12	P##W	※1 T10×31 2ケ (P408/P409 ×2)	※2 T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	※1 T10×31 2ケ (P143 ×2)	※2 T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 There is one vehicle in the front of the room Map lamp is unconfirmed. ※2 Not applicable for vehicles with fluorescent lighting
			T10×31 1ケ (P408/P409 ×1) T13 2ケ (P406/407 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1) T13 2ケ (P145 ×1) (P141 ×1)	※T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※1Not applicable for vehicles with fluorescent lighting
delicaD:2	2011.3-2015.11	MA15S	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2015.12-2020.11	MB36S	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2020.12-	MB37S	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
delicaD:3	2011.10-2019.4	BM20	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MITSUBISHI

Car model	model year	model	room lamp Recommended《CSP plate type》 front	room lamp Recommended《CSP plate type》 center	room lamp Recommended《CSP plate type》 rear	room lamp《valve type》 front	room lamp《valve type》 center	room lamp《valve type》 rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
delicaD:5	2007.1-	CV#W	※1 T10×31 2ケ (P408/P409 ×2)	※1 T10×31 2ケ (P408/P409 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	※2 T10×31 2ケ (No compatible products)	※2 T10×31 2ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	－	－	－	－	※1 Depending on the individual vehicle, symptoms such as flashing or not turning off when the key is turned off may occur. ※2 Not applicable as it may cause symptoms such as flashing or not turning off when the key is turned off.
	H31.2-	CV5W.2W	※1 T10×31 2ケ (P408/P409 ×2)	※1 T10×31 2ケ (P408/P409 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	※2 T10×31 2ケ (No compatible products)	※2 T10×31 2ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	－	－	－	－	※1 Depending on the individual vehicle, symptoms such as flashing or not turning off when the key is turned off may occur. ※2 Not applicable as it may cause symptoms such as flashing or not turning off when the key is turned off.
		CV1W	※1 T10×31 2ケ (P408/P409 ×2)	※1 T10×31 2ケ (P408/P409 ×2)	※1 T10×31 1ケ (P408/P409 ×1)	※2 T10×31 2ケ (No compatible products)	※2 T10×31 2ケ (No compatible products)	※2 T10×31 1ケ (No compatible products)	－	－	－	－	※1 Depending on the individual vehicle, symptoms such as flashing or not turning off when the key is turned off may occur. ※2 Not applicable as it may cause symptoms such as flashing or not turning off when the key is turned off.
triton	2006.9-2011.8	KB9T	T13 1ケ (Unconfirmed) T13 2ケ (Unconfirmed)	T10×31 1ケ (Unconfirmed)	－	T13 1ケ (Unconfirmed) T13 2ケ (Unconfirmed)	T10×31 1ケ (Unconfirmed)	－	－	－	－	－	
pajero	1999.9-2006.9	V6#.7#W	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	※1 T13 1ケ (P141 ×1) ※1 T13 2ケ (P141 ×1)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in a pack of 4, but only 3 are used.
	2006.10-2019.8	V8#.9#W	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	
pajeroJr.	1995.11-1998.6	H57A	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Pajeroio	1998.6-2007.8	H6#.7#W	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	－	T10×31 1ケ (P408/409 ×1)	※1 T13 1ケ (P141 ×1) ※1 T13 2ケ (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in a pack of 4, but only 3 are used.
pajero mini	1994.12-1998.9	H51A.56A	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1998.10-2013.8	H53A.58A	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Dignity	2012.7-2016.12	BHGY51	G14 2ケ (No compatible products)	T10 2ケ (P406/407 ×2)	－	G14 2ケ (No compatible products)	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MITSUBISHI			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
minika	1998.10-2011.7	H4#A	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
minika town bee	1998.10-2003.9	H4#A	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Toppo BJ	2001.2-2003.7	H4#A	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	－	T10×31 1ケ (P408/409 ×1)	※1 T13 1ケ (P141 ×1) ※1 T13 2ケ (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in a pack of 4, but only 3 are used.
Toppo	2008.9-2013.9	H82A	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	－	T10×31 1ケ (P408/P409 ×1)	※1 T13 1ケ (P141 ×1) ※1 T13 2ケ (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in a pack of 4, but only 3 are used.
minicab van	1999.1-2015.2	U6#V	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2015.3-	DS17V	T10 1ケ (P406/P407 ×1)	－	T10 1ケ (P406/P407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
minicab truck	1999.1-2014.1	U6#	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
	2014.2-	DS16T	T10 1ケ (P406/P407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
mirage	2012.8-	A05A.03A	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
lancer	2003.2-2010.5	CS#A	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/P409 ×1)	T8×29 1ケ (No compatible products)	※1 T13 1ケ (P141 ×1) T13 2ケ (P141 ×1)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
lancer cargo	2003.1-2008.11	CS2V	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2008.12-2019.4	Y12	G14 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	※G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
lancer cedia	2000.5-2003.1	CS#A	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/P409 ×1)	T8×29 1ケ (No compatible products)	※1 T13 1ケ (P141 ×1) T13 2ケ (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

MITSUBISHI

Car model	model year	model	room lamp Recommended《CSP plate type》 front	room lamp center	room lamp rear	room lamp 《valve type》 front	room lamp center	room lamp rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
Lancer Cedia Wagon	2000.11-2003.1	CS5W	T13 1ケ (No compatible products) T13 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	※1 T13 1ケ (P141 ×1) T13 2ケ (P141 ×1)	T10×31 1ケ (P401 ×1)	T10×31 1ケ (P401 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Lancer Evolution ※Continue to next page	1998.1- EVO.Ⅴ	CP9A	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P402 ×2)	T10×31 1ケ (P401 ×1)	－	－	－	－	－	
			T10×31 1ケ (P408/P409 ×1) T13 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P402 ×1) T13 2ケ (P403 ×2)	T10×31 1ケ (P401 ×1)	－	－	－	－	－	Car with sunroof
	1999.1- EVO.Ⅵ		T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P402 ×2)	T10×31 1ケ (P401 ×1)	－	－	－	－	－	
			T10×31 1ケ (P408/P409 ×1) T13 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P402 ×1) T13 2ケ (P403 ×2)	T10×31 1ケ (P401 ×1)	－	－	－	－	－	Car with sunroof
	2001.2- EVO.Ⅶ	CT9A	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/P409 ×1)	－	※1 T13 1ケ (P141 ×1) T13 2ケ (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Lancer Evolution	2003.1- EVO.Ⅷ	CT9A	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/P409 ×1)	－	※1 T13 1ケ (P141 ×1) T13 2ケ (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2005.3- EVO.Ⅸ		T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/P409 ×1)	－	※1 T13 1ケ (P141 ×1) T13 2ケ (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2007.10- EVO.Ⅹ	CZ4A	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Lancer Evolution WAGON	2005.9-2007.8	CT9A	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/P409 ×1)	－	※1 T13 1ケ (P141 ×1) T13 2ケ (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Lancer Wagon	2003.2-2010.5	CS5W	T13 1ケ (P404 ×1) T13 2ケ (P404 ×2)	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P408/P409 ×1)	※1 T13 1ケ (P141 ×1) T13 2ケ (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	front	slide(rear)		
RX-7	1991.12-1997.9	FD3S	T10 2ケ (P406/P407 ×1)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10×31 1ケ (P408/P409 ×1)	－	－	－	－	
	1997.10-2003.4		T10 2ケ (P406/P407 ×1)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10×31 1ケ (P408/P409 ×1)	－	－	－	－	
RX-8	2003.4-2008.2	SE3P	※1 T10 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	※2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 Plate type cannot be installed at the front of the room. ※2 It comes in 2 pieces, but only 1 piece is used.
	2008.3-2013.4		※1 T10 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	※2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 Plate type cannot be installed at the front of the room. ※2 It comes in 2 pieces, but only 1 piece is used.
Axela ※Continue to next page	2003.10-2009.5	BK#P	※1 T10 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	※2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 Plate type cannot be installed at the front of the room. ※2 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	front	slide(rear)		
Axela	2009.6-2013.10	BL#FP BLEAP	※1 T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	－	※1 For the front of the room, if you are installing the plate type, please remove the metal fittings inside the fixture or install the bulb at a slight angle. ハッチback
			※1 T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T5 1ケ (No compatible products)	－	－	－	－	※1 For the front of the room, if you are installing the plate type, please remove the metal fittings inside the fixture or install the bulb at a slight angle. SEDAN
	2013.11-H31.4	BM	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
Axela hybrid	2013.11-2019.5	BYEFP	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T5 1ケ (No compatible products)	－	－	－	－	
Axela sports	2003.10-2009.5	BK#P	※1 T10 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	－	F.Cgrade ※1 Plate type cannot be installed at the front of the room.
			※1 T10 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	－	Sgrade ※1 Plate type cannot be installed at the front of the room.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	front	slide(rear)		
Axela sports	2009.6-2013.10	BL#FW BLEAW	※1 T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	－	※1 For the front of the room, if you are installing the plate type, please remove the metal fittings inside the fixture or install the bulb at a slight angle.
	2013.11-2018.4	BM	T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－				
Mazdaspeed Axela ※Continue to next page	2003.10-2009.5	BK3P	※1 T10 2ケ (No compatible products)	T10×31 1ケ (P408/P409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	－	※1 Plate type cannot be installed at the front of the room.
Mazdaspeed Axela	2009.6-2012.6	BL3FW	※1 T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T8×29 1ケ (P143 ×1)	－	－	－	－	※1 For the front of the room, if you are installing the plate type, please remove the metal fittings inside the fixture or install the bulb at a slight angle.
Atenza SEDAN	2002.5-2007.12	GG#P	※1 T10 2ケ (No compatible products)	※1 T10 2ケ (No compatible products)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	－	T5 1ケ (No compatible products)	－	－	－	－	※1 Plate type cannot be installed on the front/center of the room
	2008.1-2012.10	GH#FP GH5AP	※1 T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T5 1ケ (No compatible products)	－	－	－	－	※1 For the front of the room, if you are installing the plate type, please remove the metal fittings inside the fixture or install the bulb at a slight angle.
	2012.11-2018.5	GJ	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T5 1ケ (No compatible products)	－	－	－	－	
	2018.6-2019.7		T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T5 1ケ (No compatible products)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	front	slide(rear)		
Atenza sports	2002.5-2007.12	GG#P	※ T10 2ケ (No compatible products)	※ T10 2ケ (No compatible products)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※Plate type cannot be installed on the front/center of the room
	2008.1-2012.10	GH#FP GH5AP	※1 T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	※1 For the front of the room, if you are installing the plate type, please remove the metal fittings inside the fixture or install the bulb at a slight angle.
Atenza sports wagon ※Continue to next page	2002.6-2007.12	GY#W	※1 T10 2ケ (No compatible products)	※1 T10 2ケ (No compatible products)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 2ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P408/P409 ×1)	－	－	－	－	※1 Plate type cannot be installed on the front/center of the room
	2008.1-2012.11	GH#FW GH5AW	※1 T10×31 2ケ (P408/P409 ×2)	T10×31 1ケ (P408/P409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P408/P409 ×1)	－	－	－	－	※1 For the front of the room, if you are installing the plate type, please remove the metal fittings inside the fixture or install the bulb at a slight angle.
	2012.11-2018.5	GJ	T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P408/P409 ×1)	－	－	－	－	
Atenza sports wagon	2018.6-2019.7	GJ	※1 LED	※1 LED	－	※1 LED	※1 LED	－	※2 LED or T10×31 1ケ (P408/P409 ×1)	－				※1 Not applicable due to LED lamp ※2 StandardNot applicable for LED lamps
AZ-Wagon	2003.10-2008.8	MJ21S.22S	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2008.9-2012.10	MJ23S	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
AZ-Wagon customstyle	2007.2-2008.8	MJ22S	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2008.9-2012.10	MJ23S	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
AZ-Wagon RR	2003.10-2008.8	MJ21S.22S	T10 1ケ (P406/P407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	front	slide(rear)		
AZ-Offroad	1998.10-2004.9	JM23W	T10 1ヶ (P406/P407 ×1)	－	－	※1 T10 1ヶ (P145 ×1) (P141 ×1)	－	－	※1 T10 1ヶ (P145 ×1) (P141 ×1)	－	－	－	－	※1 P1345/141 comes in a pack of two, so if you select P145/141 for the front, please use it for luggage.
	H116.10-2014.3		T10 1ヶ (P406/P407 ×1)	－	－	※1 T10 1ヶ (P145 ×1) (P141 ×1)	－	－	※1 T10 1ヶ (P145 ×1) (P141 ×1)	－	－	－	－	※1 P1345/141 comes in a pack of two, so if you select P145/141 for the front, please use it for luggage.
MPV	1999.6-2006.1	LW#W	※1 T10 2ヶ (No compatible products)	T10×31 2ヶ (P408/P409 ×2)	T10×31 1ヶ (P408/P409 ×1)	T10 2ヶ (P145 ×1) (P141 ×1)	T10×31 2ヶ (P143 ×2)	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	※1 Plate type cannot be installed at the front of the room.
	2006.2-2016.3	LY3P	※1 T10 2ヶ (No compatible products)	※1 T10 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	T10 2ヶ (P145 ×1) (P141 ×1)	T10 2ヶ (P145 ×1) (P141 ×1)	T10×31 1ヶ (P143 ×1)	T10×31 1ヶ (P408/P409 ×1)	－	－	－	－	※1 Plate type cannot be installed on the front/center of the room
MX-30	2020.10-	DREJ3P	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	－	－	－	－	※1 Not applicable due to LED lamp
MX-30 EV	2021.1-	DRH3P	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	－	－	－	－	※1 Not applicable due to LED lamp
Carol	2004.9-2006.11	HB24S	T10 1ヶ (P406/407 ×1)	－	－	※1 T10 1ヶ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2006.12-2009.11									－				
	2009.12-2014.12	HB25S	T10 1ヶ (P406/P407 ×1)	－	－	※1 T10 1ヶ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2015.1-2021.11	HB36S	T10 1ヶ (P406/P407 ×1)	－	－	※1 T10 1ヶ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2021.12-	HB37S HB97S	T10×31 1ヶ (P408/P409 ×1)	－	－	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			room lamp Recommended《CSP plate type》			《valve type》			luggage (trunk)	door	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	front	slide(rear)		
CX-8	2017.12-	KG2P	T10×31 2ヶ (P408/P409 ×2)	T10×31 2ヶ (P408/P409 ×2)	T10×31 1ヶ (P408/P409 ×1)	T10×31 2ヶ (P143 ×2)	T10×31 1ヶ (P143 ×1)	T10×31 1ヶ (P143 ×1)	T10×31 1ヶ (P408/P409 ×1)	－	－	－	－	
			※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	－	－	－	－	※1 Not applicable due to LED lamp
CX-7	2006.12-2009.8	ER3P	※1 T10 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P408/P409 ×1)	T10 2ヶ (P145 ×1) (P141 ×1)	T10×31 1ヶ (P143 ×1)	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	※Plate type cannot be installed at the front of the room.
	2009.9-2011.12	ER3P	※1 T10 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P408/P409 ×1)	T10 2ヶ (P145 ×1) (P141 ×1)	T10×31 1ヶ (P143 ×1)	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	※Plate type cannot be installed at the front of the room.
CX-5	2012.2-2014.12	KEE#W.KE2#W	T10×31 2ヶ (P408/P409 ×2)	T10×31 2ヶ (P408/P409 ×2)	－	T10×31 2ヶ (P143 ×2)	T10×31 2ヶ (P143 ×2)	－	T10×31 1ヶ (P408/P409 ×1)	－	－	－	－	
	2015.1-2017.1		T10×31 2ヶ (P408/P409 ×2)	T10×31 2ヶ (P408/P409 ×2)	－	T10×31 2ヶ (P143 ×2)	T10×31 2ヶ (P143 ×2)	－	T10×31 1ヶ (P408/P409 ×1)	－	－	－	－	
	2017.2-	KF	T10×31 2ヶ (P408/P409 ×2)	T10×31 2ヶ (P408/P409 ×2)	－	T10×31 2ヶ (P143 ×2)	T10×31 2ヶ (P143 ×2)	－	T10×31 1ヶ (P408/P409 ×1)	－	－	－	－	
			※1 LED	※1 LED	－	※1 LED	※1 LED	－	※1 LED	－	－	－	－	※1 Not applicable due to LED lamp
CX-3	2015.2-	DK	T10×31 2ヶ (P408/P409 ×2)	T10×31 1ヶ (P408/P409 ×1)	－	T10×31 2ヶ (P143 ×2)	T10×31 1ヶ (P143 ×1)	－	T10×31 1ヶ (P408/P409 ×1)	－	－	－	－	
			T10×31 2ヶ (P408/P409 ×2)	T10×31 1ヶ (P408/P409 ×1)	－	T10×31 2ヶ (P143 ×2)	T10×31 1ヶ (P143 ×1)	－	T10×31 1ヶ (P408/P409 ×1)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	front	slide(rear)		
CX-30	2019.10-	DMEP DMFP DM8P	※1 LED	※1 LED	-	※1 LED	※1 LED	-	※1 LED	-	-	-	-	※1 Not applicable due to LED lamp
Scrum Track	1999.1-2005.8	DG5#T DG6#T	T10 1ヶ (P406/407 ×1)	-	-	※1 T10 1ヶ (P145 ×1) (P141 ×1)	-	-	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
	2005.8-2013.8	DG63T	T10 1ヶ (P406/P407 ×1)	-	-	※1 T10 1ヶ (P145 ×1) (P141 ×1)	-	-	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
	2013.9-	DG16T	T10 1ヶ (P406/P407 ×1)	-	-	※1 T10 1ヶ (P145 ×1) (P141 ×1)	-	-	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
Scrum van	1999.1-2005.8	DG5#V DG6#V	T10 1ヶ (P406/P407 ×1)	-	-	※1 T10 1ヶ (P145 ×1) (P141 ×1)	-	-	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used. Front and rear can be used as one set (2 pieces).
	2005.9-2015.2	DG64V	T10 1ヶ (P406/P407 ×1)	-	-	※1 T10 1ヶ (P145 ×1) (P141 ×1)	-	-	T10 1ヶ (P406/407 ×1) ※1 (P145/141 ×1)	-	-	-	-	※1 P145/141 comes in a pack of two, so if you select P145/141 for the front, please use it for luggage.
	2015.3-	DG17V	T10 1ヶ (P406/407 ×1)	-	-	※1 T10 1ヶ (P145 ×1) (P141 ×1)	-	-	T10 1ヶ (P406/407 ×1) ※1 (P145/141 ×1)	-	-	-	-	※1 P1345/141 comes in a pack of two, so if you select P145/141 for the front, please use it for luggage.
Scrum Wagon	1999.1-2005.8	DG5#W DG6#W	T10 1ヶ (P406/P407 ×1)	-	T10 1ヶ (P406/P407 ×1)	※1 T10 1ヶ (P145 ×1) (P141 ×1)	-	※1 T10 1ヶ (P145 ×1) (P141 ×1)	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used. Front and rear can be used as one set (2 pieces).
	2005.9-2015.2	DG64W	T10 1ヶ (P406/P407 ×1)	T10×31 1ヶ (P408/409 ×1)	-	※1 T10 1ヶ (P145 ×1) (P141 ×1)	T10×31 1ヶ (P143 ×1)	-	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
	2015.3-	DG17W	T10 1ヶ (P406/407 ×1)	T10×31 1ヶ (P408/409 ×1)	-	※1 T10 1ヶ (P145 ×1) (P141 ×1)	T10×31 1ヶ (P143 ×1)	-	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
Spiano	2002.2-2004.2	HF21S	T10 1ヶ (P406/P407 ×1)	-	-	※1 T10 1ヶ (P145 ×1) (P141 ×1)	-	-	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
	2004.3-2006.3		T10 1ヶ (P406/P407 ×1)	-	-	※1 T10 1ヶ (P145 ×1) (P141 ×1)	-	-	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	front	slide(rear)		
Spiano	2006.4-2008.11	HF21S	T10 1ヶ (P406/P407 ×1)	－	－	※1 T10 1ヶ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Demio	1996.8-1999.11	DW3W DW5W	※T10 2ヶ (P406/407 ×1)	T10×31 1ヶ (P408/409 ×1)	－	※1 T10 1ヶ (P145 ×1) (P141 ×1)	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	1999.12-2002.7		※T10 2ヶ (P406/407 ×1)	T10×31 1ヶ (P408/409 ×1)	－	※1 T10 1ヶ (P145 ×1) (P141 ×1)	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Demio	2002.8 -2007.6	DY#W DY#R	T10×31 1ヶ (P408/P409 ×1)	－	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P143 ×1)	－	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	
			※1 T10 2ヶ (No compatible products)	－	T10×31 1ヶ (P134 ×1)	T10 2ヶ (P145 ×1) (P141 ×1)	－	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	Canvas top model ※1 Plate type cannot be installed at the front of the room.
	2007.7-2014.8	DE3#S DE5FS	T10×31 1ヶ (P408/P409 ×1)	－	－	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	front	slide(rear)		
Demio	2014.9-2019.8	DJ3#S DJ5#S	T10×31 2ヶ (P408/P409 ×2)	T10×31 1ヶ (P408/P409 ×1)	－	T10×31 2ヶ (P143 ×1)	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	－	
Demio Skyactive	2011.6-2014.8	DEJFS	T10×31 1ヶ (P408/P409 ×1)	－	－	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	－	－	
	2014.9-2019.8	DJ3 DJ5	T10×31 2ヶ (P408/P409 ×2)	T10×31 1ヶ (P408/P409 ×1)	－	T10×31 2ヶ (P143 ×1)	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	－	
Biante	2008.7-2018.2	CCE#W CC3FW	※1 T10 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P408/P409 ×1)	T10 2ヶ (P145 ×1) (P141 ×1)	T10×31 1ヶ (P143 ×1)	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	※1 Plate type cannot be installed at the front of the room.
Familia Van	1999.6-2002.8	Y11	G14 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	－	G14 2ヶ (No compatible products)	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	－	
	2002.9-2006.12		G14 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	－	G14 2ヶ (No compatible products)	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	－	
	2007.1-2018.5	Y12	G14 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	－	G14 2ヶ (No compatible products)	T10×31 1ヶ (P143 ×1)	－	※1 T10 1ヶ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2018.6-	NCP160M NCP165M	T10×31 1ヶ (P408/409 ×1)	－	T10×31 1ヶ (P408/409 ×1)	T10×31 1ヶ (P143 ×1)	－	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	
Flare	2012.10-2017.2	MJ34S	T10×31 1ヶ (P408/P409 ×1)	－	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P143 ×1)	－	T10×31 1ヶ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	front	slide(rear)		
Flare	2017.3-	MJ55S	T10×31 1ヶ (P408/P409 ×1)	-	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P143 ×1)	-	T10×31 1ヶ (P143 ×1)	-	-	-	-	-	
lair Crossover	2014.1-2020.2	MS31.41S	T10×31 1ヶ (P408/P409 ×1)	-	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P143 ×1)	-	T10×31 1ヶ (P143 ×1)	-	-	-	-	-	
	2020.2-	MS52S MS92S	T10×31 1ヶ (P408/P409 ×1)	-	T10 1ヶ (P406/P407 ×1)	T10×31 1ヶ (P143 ×1)	-	※1 T10 1ヶ (P145 ×1) (P141 ×1)	-	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
Flair Wagon	2012.6-2013.3	MM21S	T10×31 1ヶ (P408/P409 ×1)	-	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P143 ×1)	-	T10×31 1ヶ (P143 ×1)	-	-	-	-	-	
	2013.4-2018.1	MM32S.42S	T10×31 1ヶ (P408/P409 ×1)	-	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P143 ×1)	-	T10×31 1ヶ (P143 ×1)	T10side 1ヶ (P404 ×1)	-	-	-	-	include custom
	2018.2-	MM53S	T10×31 1ヶ (P408/P409 ×1)	-	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P143 ×1)	-	T10×31 1ヶ (P143 ×1)	T10side 1ヶ (P404 ×1)	-	-	-	-	include custom
Premacy	2005.2-2010.6	CR#W	※1 T10 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P408/P409 ×1)	T10 2ヶ (P145 ×1) (P141 ×1)	T10×31 1ヶ (P143 ×1)	T10×31 1ヶ (P143 ×1)	-	-	-	-	-	※1 Plate type cannot be installed at the front of the room.
	2010.7-2018.2	CWE#W	※1 T10 2ヶ (No compatible products)	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P408/P409 ×1)	T10 2ヶ (P145 ×1) (P141 ×1)	T10×31 1ヶ (P143 ×1)	T10×31 1ヶ (P143 ×1)	-	-	-	-	-	※1 Plate type cannot be installed at the front of the room.
Verisa	2004.6-2015.10	DC5#	T10×31 1ヶ (P408/P409 ×1)	-	T10×31 1ヶ (P408/P409 ×1)	T10×31 1ヶ (P143 ×1)	-	T10×31 1ヶ (P143 ×1)	-	-	-	-	-	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	front	slide(rear)		
Verisa	2006.8-2015.10	DC5#	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	－	
Bongo Truck	2020.7-	S403F S413F	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	－	
Bongo van	1999.6-2020.8	SK#	－	T10×31 1ケ (P408/P409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
			－	T10 2ケ (Unconfirmed)	－	－	T10 2ケ (Unconfirmed)	－	－	－	－	－		Vehicle equipped with large room lamp
	2020.9-	S403Z S413Z	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	－	
Bongo Brawny Van	2018.4-	TRH200M GDH206M	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	DX
			G14 2ケ (No compatible products)	T10×31 2ケ (P408/409×2)	T10×31 1ケ (P408/409 ×1)	G14 2ケ (No compatible products)	T10×31 2ケ (P143×2)	T10×31 1ケ (P143 ×1)	－		－	※1 T8×28 1ケ (P408/409 ×1)	－	GL Car with front map lamp and large room lamp ※1 T8×28 but P408/409 can be installed.
Mazda 2	2019.9-	DJL#S,DJ5#S	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
			T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－		－	－	－	
MAZDA 3 SEDAN	2019.5-	BP#P	※1 LED	※1 LED	－	※1 LED	※1 LED	－	－	－	－	－	－	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			Recommended《CSP plate type》 room lamp			《valve type》			luggage (trunk)	door	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	front	slide(rear)		
Marda 3 Fastback	2019.5-	BP#P	※1 LED	※1 LED	-	※1 LED	※1 LED	-	※1 LED	-	-	-	-	※1 Not applicable due to LED lamp
MAZDA 6 SEDAN	2019.8-	GJ#FP,GJ2#P	※1 LED	※1 LED	-	※1 LED	※1 LED	-	※1 LED	-	-	-	-	※1 Not applicable due to LED lamp
			T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	-	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	-	T5 (No compatible products)	-	-	-	-	
Mazda 6 Wagon	2019.8-	GJ#FW,GJ2#W	※1 LED	※1 LED	-	※1 LED	※1 LED	-	※1 LED	-	-	-	-	※1 Not applicable due to LED lamp
			T10×31 2ケ (P408/P409 ×2)	T10×31 2ケ (P408/P409 ×2)	-	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	-	-	-	-	-	-	
Roadster	1998.1-2000.6	NB6C NB8C	-	※1 T10×31 1ケ (No compatible products)	-	-	T10×31 1ケ (P143 ×1)	-	-	-	-	-	-	※1 Plate type cannot be installed at the front of the room.
	2000.7-2005.7			※1 T10×31 1ケ (No compatible products)	-	-	T10×31 1ケ (P143 ×1)	-	-	-	-	-	-	※1 Plate type cannot be installed at the front of the room.
	2005.8-2015.4	NCEC	-	※1 T10×31 1ケ (No compatible products)	-	-	T10×31 1ケ (P143 ×1)	-	T10×31 1ケ (P143 ×1)	-	-	-	-	※1 Plate type cannot be installed at the front of the room.
	2015.5-	ND5RC	-	※1 T10×31 1ケ (No compatible products)	-	-	T10×31 1ケ (P143 ×1)	-	T8×29 1ケ (P143 ×1)	-	-	-	-	※1 Plate type cannot be installed at the front of the room.
Roadster RF	2017.2-	NDE	-	※1 T10×31 1ケ (No compatible products)	-	-	T10×31 1ケ (P143 ×1)	-	T8×29 1ケ (P143 ×1)	-	-	-	-	※1 Plate type cannot be installed at the front of the room.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			Recommended《CSP plate type》		room lamp	《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
R1	2005.1-2010.3	RJ1.2	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
R2	2003.12-2010.3	RC1.2	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
AlcyoneSVX	1991.9-1996.12	CX#	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Impreza	1992.11-1997.8	GC#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1997.9-2000.7		T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2007.6-2011.11	GH#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
ImprezaSEDAN	2000.8-2005.5	GD#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2005.6-2007.5		T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Impreza Wagon	1992.11-2000.7	GF#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	1996.9-2000.7		T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
Impreza sports wagon	2000.8-2007.5	GG#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

SUBARU			Recommended《CSP plate type》 room lamp			《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
ImprezaXV	2010.6-2012.2	GH#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
Impreza Anesis	2008.10-2011.12	GE#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Impreza WRX STI	2007.10-2014.8	GR#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	2010.7-2014.8	GV# 4doorSEDAN	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
ImprezaG4	2011.12-2016.10	GJ#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2016.10-	GK#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	T6.3×30 (No compatible products)	※1 It comes in 2 pieces, but only 1 piece is used.
Imprezasports	2011.12-2016.10	GP#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2016.10-	GT#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	T6.3×30 (No compatible products)	
Vivio	1992.3-1998.9	KK3.4	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Exiga	2008.6-2015.3	YA#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
Exiga crossover 7	2015.4-2018.3	YAM	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			room lamp Recommended《CSP plate type》			room lamp《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
XV XV hybrid	2013.6-2017.4	GP#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	T6.3×30 (No compatible products)	
			T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	T6.3×30 (No compatible products)	hybrid
XV XV hybrid	2017.5-	GT#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	T6.3×30 (No compatible products)	
Sambar (Dias)	1990.3-1999.11	KV3.4	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	1999.2-2001.4	TV1.2 TW1.2	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2001.5-2002.8		T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2002.9-2012.3		T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
sambar truck ※Continue to next page	1990.3-1999.11	KS3.4	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
	1999.2-2001.4	TT1.2	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
	2001.5-2002.8		T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
	2002.9-2012.3		T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			Recommended《CSP plate type》 room lamp			《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
sambar truck	2014.9-2017.10	S500J S510J	T10 1ケ (P406/407 ×1)	－	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	
	2017.11-2021.12		T10 1ケ (P406/407 ×1)	－	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	※2 T10side 1ケ (P404 ×1)	－	－	－	halogen headlamp car ※1 It comes in 2 pieces, but only 1 piece is used. ※2 On the rear side of the driver's seat, not available depending on the grade.
sambar truck	2017.11-2021.12	S500J S510J	T10 1ケ (P406/407 ×1)	－	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	※2 T10side 1ケ (P404 ×1)	－	－	－	led headlamp car ※1 It comes in 2 pieces, but only 1 piece is used. ※2 On the rear side of the driver's seat, not available depending on the grade.
	2022.1-		T10 1ケ (P406/407 ×1)	－	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	halogen headlamp car ※1 It comes in 2 pieces, but only 1 piece is used.
			T10 1ケ (P406/407 ×1)	－	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	led headlamp car ※1 It comes in 2 pieces, but only 1 piece is used.
chiffon	2013.12-2019.7	LA600.610F	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	halogen headlamp car
			T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	led headlamp car
	2019.7-	LA650.660F	T10 2ケ (P406/407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Justy ※Continue to next page	2016.11-2020.8	M900.910F	T10 2ケ (P406/407 ×2)	T10 1ケ (P404 ×1)	T10 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10 1ケ (P404 ×1)	－	※2 T10 2ケ (P404 ×2)	－	※1 Since it comes in 2 pieces, please use one as a spare. ※2 The slide isDepending on the grade, it may or may not be set.
			CSPcomplete kit P18TC										※Same as Toyota Tank/Roomy Applicable areas: front, center, rear, luggage

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

SUBARU			Recommended《CSP plate type》 room lamp			《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Justy	2020.9-	M900.910F	T10 2ケ (P406/407 ×2)	T10 1ケ (P404 ×1)	T10 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10 1ケ (P404 ×1)	－	※2 T10 2ケ (P404 ×2)	－	※1 Since it comes in 2 pieces, please use one as a spare. ※2 The slide isDepending on the grade, it may or may not be set.
			CSPcomplete kit P18TC										※Same as Toyota Tank/Roomy Applicable areas: front, center, rear, luggage
Stella Stella custom	2006.6-2011.4	RN1.2	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2011.5-2014.12	LA100.110F	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	T10side 2ケ (P404 ×2)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	T10side 2ケ (P145 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
	2013.1-2014.12	LA100.110F	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	T10side 2ケ (P404 ×2)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	T10side 2ケ (P145 ×1)	T10side 1ケ (P404 ×1)	－	－	－	custom
	2014.12-	LA150.160F	T10 2ケ (P406/407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1)		T10side 1ケ (P404 ×1) ※1 (P145 ×1)	－	－	－	※1 If you select P145 as the center lamp, it can be used in luggage as it comes in 2 pieces.
			T10 2ケ (P406/407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1)		T10side 1ケ (P404 ×1) ※1 (P145 ×1)	－	－	－	custom ※1 If you select P145 as the center lamp, it can be used in luggage as it comes in 2 pieces.
WRX STI	2014.8-2020.4	VAB	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
WRX S4	2014.8-2021.3	VAG	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	2021.11-	VBH	※1 LED	※1 LED	－	※1 LED	※1 LED	－	T10side 1ケ (P404 ×1)	－	－	－	※1 Not applicable due to LED lamp
dias wagon	2009.9-2020.4	S321.331N	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			Recommended《CSP plate type》 room lamp			《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
DEX(dex)	2008.11-2012.11	M401F M411F	※1 T10 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10 1ケ (No compatible products)	※2 T10side 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 Plate type with narrow insertion opening is No applicable products. ※2 Contains 2 valves, so there is 1 left.
Domingo	1994.6-1999.2	FA7.8	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Travic	2001.8-1993.6	XM182.220	－	T10×41 1ケ (No compatible products)	－	－	T10×41 1ケ (No compatible products)	－	－	－	－	－	
	2003.7-2004.12		－	T10×41 1ケ (No compatible products)	－	－	T10×41 1ケ (No compatible products)	－	－	－	－	－	
Tresia	2010.11-2016.3	NSP.NCP12#	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
BRZ	2012.3-2016.6	ZC6	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	T10side 1ケ (P404 ×1)	※T10side 2ケ (P145 ×1) (P141 ×1)	－	T6.3×30 (No compatible products)	Early period ※Confirm the front door is installed on the vehicle side.
	2016.7-2021.3		T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	T10side 1ケ (P404 ×1)	※T10side 2ケ (P145 ×1) (P141 ×1)	－	T6.3×30 (No compatible products)	Late period ※Confirm the front door is installed on the vehicle side.
	2021.8-	ZD8	T10 2ケ (P406/407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10 1ケ (P406/407 ×1)	T10side 2ケ (P404 ×2) (P145 ×1)	－	T6.3×30 (No compatible products)	
forester ※Continue to next page	1997.2-1999.12	SF5.9	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2000.1-2002.1		T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2002.2-2007.11	SG5.9	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

SUBARU			Recommended《CSP plate type》 room lamp			《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
forester	2007.12-2012.11	S1993.9 SHJ	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10side 2ケ (P404 ×2) (P145 ×1)	－	T6.3×30 (No compatible products)	※1 It comes in 2 pieces, but only 1 piece is used.
	2012.11-2018.7	SJ5 SJG	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P404 ×1)	T10side 2ケ (P404 ×2) (P145 ×1)	－	T6.3×30 (No compatible products)	halogen headlamp car
			T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P404 ×1)	T10side 2ケ (P404 ×2) (P145 ×1)	－	T6.3×30 (No compatible products)	HID headlamp car
	2015.10-2018.7	SJ5 SJG	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P404 ×1)	T10side 2ケ (P404 ×2) (P145 ×1)	－	T6.3×30 (No compatible products)	halogen headlamp car
			T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	－	T10 1ケ (P404 ×1)	T10side 2ケ (P404 ×2) (P145 ×1)	－	T6.3×30 (No compatible products)	HID headlamp car
	2018.7-2021.8	SK5.9 SKE	※1 LED	※2 T10×31 1ケ (P408/409 ×1)	－	※1 LED	T10×31 1ケ (P143 ×1)	－	※3 T10 1ケ (P406/407 ×1)	T10side 2ケ (P404 ×2) (P145 ×1)	－	T6.3×30 (No compatible products)	※1 Not applicable due to LED lamp ※2 Since the front is genuine LED (warm color), we recommend P409, which has the same warm color for the center. ※3 Since the front is a genuine LED (warm color), we recommend P407, which has the same warm color as the luggage.
	2021.9-	SK5.SKE	※1 LED	※2 T10×31 1ケ (P408/409 ×1)	－	※1 LED	T10×31 1ケ (P143 ×1)	－	※3 T10 1ケ (P406/407 ×1)	T10side 2ケ (P404 ×2) (P145 ×1)	－	T6.3×30 (No compatible products)	※1 Not applicable due to LED lamp ※2 Since the front is genuine LED (warm color), we recommend P409, which has the same warm color for the center. ※3 Since the front is a genuine LED (warm color), we recommend P407, which has the same warm color as the luggage.
Pleo	1998.10-2000.9	RA1.2 RV1.2	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2000.10-2010.3		－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2010.4-2018.3	L275B.F L285B.F	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			room lamp Recommended《CSP plate type》			room lamp《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Pleo custom	2010.4-2013.2	L275.285F	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Pleo Plus	2012.12-2017.5	LA300.310F	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	
	2017.5-	LA350.360F	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	
Lukla	2010.4-2015.5	L455.465F	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
			T10 2ケ (P406/407 ×2)	T10 1ケ (P406/407 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	overhead console ※1 It comes in 2 pieces, but only 1 piece is used.
Lukla custom	2010.4-2015.5	L455.465F	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
			T10 2ケ (P406/407 ×2)	T10 1ケ (P406/407 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	overhead console ※1 It comes in 2 pieces, but only 1 piece is used.
Levorg	2014.10-2020.10	VM4.VMG	T10×31 2ケ (P408/409 ×2)	T10×31 2ケ (P408/409 ×2)	－	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	－	T10 1ケ (P406/407 ×1)			T6.3×30 (No compatible products)	
	2020.10-	VN5.VNH	※1 LED	※1 LED	－	※1 LED	※1 LED	－	T10 1ケ (P406/407 ×1)	－	－	T6.3×30 (No compatible products)	※1 Not applicable due to LED lamp
Levorg Ray back	2023.11-	VN5	※1 LED	※1 LED	－	※1 LED	※1 LED	－	T10 1ケ (P406/407 ×1)	－	－	T6.3×30 (No compatible products)	※1 Not applicable due to LED lamp
leone van	1999.6-2005.10	Y11	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

SUBARU			Recommended《CSP plate type》		room lamp	《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Legacy	1993.10-1998.11	BD#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	－	－	－	－	
Legacy B4	1998.12-2001.4	BE#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	－	－	－	－	
	1998.12-2001.4		T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	－	－	－	－	
	2001.5-2003.5		T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	－	－	－	－	
	2003.6-2009.4	BL#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	－	－	－	－	
	2009.5-2014.10	BM9 BMM.BMG	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	－	－	－	T6.3×30 (No compatible products)	
	2014.10-2020.8	BN9	T10×31 2ケ (P408/409 ×2)	T10×31 2ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143×1)	－	T10side 1ケ (P404 ×1)	T10side 2ケ (P404 ×2)	－	T6.3×30 (No compatible products)	
legacy touring wagon ※Continue to next page	1993.10-1998.5	BG#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	－	－	－	－	
	1998.6-2001.4	BH#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	2 headlamp car
			T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	4 headlamp car
	2001.5-2003.5		T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			Recommended《CSP plate type》 room lamp			《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
legacy touring wagon	2003.5-2009.4	BP#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	
	2009.5-2014.10	BR9 BRM.BRG	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	T10 1ケ (P406/407 ×1)	T10side 2ケ (P404 ×2)	－	T6.3×30 (No compatible products)	
legacy out back	2003.10-2009.5	BP#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	T10 1ケ (P406/407 ×1)	－	－	－	
	2009.5-2014.10	BR#	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143×1)	－	T10 1ケ (P406/407 ×1)	T10side 2ケ (P404 ×2)	－	T6.3×30 (No compatible products)	
	2014.10-2021.3	BS9	T10×31 2ケ (P408/409 ×2)	T10×31 2ケ (P408/409 ×1)	－	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143×1)	－	T10 1ケ (P406/407 ×1)	T10side 2ケ (P404 ×2)	－	T6.3×30 (No compatible products)	
legacy out back	2021.12-	BT5	※1 LED	※1 LED	－	※1 LED	※1 LED	－	－	T10side 2ケ (P404 ×2)	－	T6.3×30 (No compatible products)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			Recommended《CSP plate type》 room lamp			《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
alto Alto Works	1994.11-1997.3	HA.HB.HC11#	－	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
	1997.4-1998.9	HA11#.21#	－	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
		HA11#.21# ワークス	－	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
	1998.10-2004.8	HA12#.22#.23#	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
		HA12#.22#.23# クラシック	－	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
	2004.9-2009.11	HA24#	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2009.12-2014.12	HA25#	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	T6.3 2ケ (No compatible products)	※1 It comes in 2 pieces, but only 1 piece is used.
	2014.12-2021.12	HA36#	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	
	2021.12-	HA97S.37S	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	halogen headlamp car
			T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	led headlamp car

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			Recommended《CSP plate type》 room lamp			《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
alto eco	2011.12-2014.12	HA35S	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
alto lapin	2002.1-2003.12	HE21S	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2004.1-2008.10		T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2008.11-2015.6	HE22S	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2013.6-2015.5		T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2015.6-	HE33S	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	halogen headlamp car
			－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	led headlamp car
alto lapinSS	2002.1-2003.12	HE21S	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2004.1-2008.10		T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Ignis	2016.2-	FF21S	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			room lamp Recommended《CSP plate type》			room lamp《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
SX4	2006.7-2014.11	YA.YB#1S	T10 2ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
SX4SEDAN	2007.7-2014.11	YC11S	T10 2ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
Escudo	1988.5-1997.10	TA#1W TD#1W	T8×29 2ケ (No compatible products)	T8×29 1ケ (No compatible products)	－	T8×29 2ケ (P143 ×2)	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
	1997.11-2001.10	TA#2W.TL52W TD#2W	T10 2ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2001.11-2005.4		T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2005.5-2008.5	TD#4W TDA4W.B4W	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	2008.6-2017.4		T10 2ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2006.6-2017.4	TA74W	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	2015.10-	YD.YE#1S	T10 2ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	T6.3 2ケ (No compatible products)	
X90	1995.10-1997.12	LB11S	－	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	※1 T10side 1ケ (P137 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			room lamp Recommended《CSP plate type》			room lamp《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Every ※Continue to next page	1990.3-1998.12	DA.DB41#.51#	T8×29 1ケ (No compatible products)	T8×29 1ケ (No compatible products)	－	T8×29 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
	1999.1-2005.7	DA.DB52#.62#	T8×29 1ケ (No compatible products)	T8×29 1ケ (No compatible products)	－	T8×29 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
Every	2005.8-2015.1	DA64W	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
		DA64W ジョイン	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	T10 1ケ (P406/407 ×1) ※1 (P145/141 ×1)	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the luggage.
		DA64V	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	T10 1ケ (P406/407 ×1) ※1 (P145/141 ×1)	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the luggage.
	2015.2-	DA17W	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	halogen headlamp car ※1 It comes in 2 pieces, but only 1 piece is used.
			T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	led headlamp car ※1 It comes in 2 pieces, but only 1 piece is used.
		DA17V	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	T10 1ケ (P406/407 ×1) ※1 (P145/141 ×1)	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the luggage.
Every Plus	1999.6-2001.5	DA32W	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
every randy	2001.5-2005.7	DA32W	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			Recommended《CSP plate type》 room lamp			《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
MR wagon	2001.12-2005.12	MF21S	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2006.1-2010.12	MF22S	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2011.1-2016.3	MF33S	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	T6.3 2ケ (No compatible products)	
MR wagon sports	2002.6-2005.12	MF21S	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Elio	2001.1-2004.6	RB21S RD51S	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	T8×29 1ケ (No compatible products)	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2004.7-2006.5		T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	T8×29 1ケ (No compatible products)	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	T8×29 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Elio SEDAN	2001.11-2007.3	RA21S RC51S	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	T10 1ケ (P406/407 ×2)	T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the luggage.
cappuccino	1991.11-1997.12	EA11.21R	－	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
Cultus	1998.5-1999.8	GA11.31S	－	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
cultus crescent SEDAN	1995.1-1998.4	GC.GD21S	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Cultus SEDAN	1998.5-2001.11	GC.GD21S	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			Recommended《CSP plate type》 room lamp			《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
cultus crescent wagon	1996.2-1998.4	GC21.41W GD31W	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
cultus wagon	1998.5-2002.8	GC21.41W GD31W	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
character	1993.1-1995.12	PG6SS	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
carry	1999.1-2005.7	DA.DB52#.62#	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2005.8-2013.7	DA63.65T	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2013.8-	DA16T	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Kizashi	2009.10-2015.11	RE91S.RF91S	T10 3ケ (P406/407 ×3)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×2) (P141 ×2)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 3 pieces are used.
grand escudo	2000.12-2001.9	TX92W	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2001.10-2003.5		T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the luggage.
	2003.6-2005.4		－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			Recommended《CSP plate type》 room lamp			《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
cross bee	2017.12-	MN71S	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	-	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	-	T10side 1ケ (P404 ×1)	-	-	-	
Kei	1998.10-2009.10	HN11.12S HN21.22S	T10 1ケ (P406/407 ×1)	-	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	-	-	-	-	※1 It comes in 2 pieces, but only 3 pieces are used.
chevrolet cruze	2000.12-2003.10	HR51S.52#	T10×31 1ケ (P408/409 ×1)	-	-	T10×31 1ケ (P143 ×1)	-	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
	2003.11-2008.7		T10×31 1ケ (P408/409 ×1)	-	-	T10×31 1ケ (P143 ×1)	-	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.
chevrolet MV	2006.1-2010.12	ME34S	T10 1ケ (P406/407 ×1)	-	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	-	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the luggage.
jimny	1995.11-1998.9	JA12#.22#	-	T8×29 1ケ (No compatible products)	-	-	T8×29 1ケ (P143 ×1)	-	-	-	-	-	
	1998.10-2001.12	JB23W	T10 1ケ (P406/407 ×1)	-	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	-	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the luggage.
	2002.1-2005.9		T10 1ケ (P406/407 ×1)	-	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	-	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the luggage.
	2005.10-2018.7		T10 1ケ (P406/407 ×1)	-	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	※1 T10 1ケ (P145 ×1) (P141 ×1)	-	-	-	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the luggage.
	2018.7-	JB64W	T10×31 1ケ (P408/409 ×1)	-	T10 1ケ (P404 ×1)	T10×31 1ケ (P143 ×1)	-	※1 T10 1ケ (P137 ×1)	-	-	-	-	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			Recommended《CSP plate type》 room lamp			《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
jimny sierra	1993.5-1995.10	JB31W	－	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
	1995.11-1997.12	JB32W	－	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
	2002.1-2018.7	JB43W	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the luggage.
	2018.7-	JB74W	T10×31 1ケ (P408/409 ×1)	－	T10 1ケ (P404 ×1)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P137 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
jimny wide	1998.1-2001.12	JB33W	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
swift ※Continue to next page	2000.2-2003.5	HT51#.81#	T10 1ケ (P406/407 ×1)	－	T10 1ケ (P406/407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the rear.
	2003.6-2004.10		T10 1ケ (P406/407 ×1)	－	T10 1ケ (P406/407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the rear.
swift	2004.11-2010.8	ZC.ZD11#.21# 71#	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	2010.9-2017.1	ZC72.ZD72	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	halogen headlamp car
			T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	led headlamp car

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			Recommended《CSP plate type》 room lamp			《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
swift	2017.1-	ZC.ZD#3S	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	halogen headlamp car
			T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	led headlamp car
swift sports	2005.9-2010.9	ZC31S	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	2011.12-2016.12	ZC32S	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	halogen headlamp car
			T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	HID headlamp car
	2017.9-	ZC33S	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	
splash	2008.10-2012.4	XB32S	T10×31 1ケ (P408/409 ×1)	－	T10×41 (No compatible products)	T10×31 1ケ (P143 ×1)	－	T10×41 (No compatible products)	－	－	－	－	
spacia (custom、customZ、GEAR)	2013.3-2017.12	MK32.42S	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
	2017.12-2023.10	MK53S	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
spacia base	2022.8-	MK33S	ASSY (No compatible products)	ASSY (No compatible products)	ASSY (No compatible products)	ASSY (No compatible products)	ASSY (No compatible products)	ASSY (No compatible products)	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			room lamp Recommended《CSP plate type》			room lamp《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
spacia	2023.11-	MK94S	T10×31 1ケ (P408/409 ×1)	－	T10 1ケ (P404 ×1)		－	T10 1ケ (P404/405 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
	2023.11-	MK54S MK94S	※1 LEDT10形状 1ケ (P404 ×1)	－	T10 1ケ (P404 ×1)	※1 LEDT10形状 1ケ (P404/405 ×1)	－	T10 1ケ (P404/405 ×1)	T10side 1ケ (P404 ×1)	－	－	－	custom ※1 The genuine one is a T10 shaped LED bulb. replaceable.
Cervo	2006.11-2009.12	HG21S	－	T10×31 1ケ (P408/409 ×1)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
Cervo mode	1990.7-1995.9	CN#.CP#	－	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
	1995.10-1998.9		－	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	
Solio Solio vandit ※Continue to next page	2005.8-2011.1	MA34S	T10 1ケ (P406/407 ×1)	－	T10 1ケ (P406/407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the rear.
			T10 1ケ (P406/407 ×1)	－	T10 1ケ (P406/407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	halogen headlamp car round tail
			T10 1ケ (P406/407 ×1)	－	T10 1ケ (P406/407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	HID headlamp car round tail
	2011.1-2015.8	MA15S	T10 1ケ (P406/407 ×1)	－	T10×31 1ケ (P408/409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2013.11-2015.9		T10 1ケ (P406/407 ×1)	－	T10×31 1ケ (P408/409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
			T10 1ケ (P406/407 ×1)	－	T10×31 1ケ (P408/409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	van dit

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			room lamp Recommended《CSP plate type》			room lamp《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Solio Solio vandit	2015.8-2020.11	MA26.36.46S	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)		T10side 1ケ (P404 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2020.12-	MA27.37S	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)		T10side 1ケ (P404 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
twin	2003.1-2005.8	EC22S	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
hustler	2014.1-2019.12	MR31.41S	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	T6.3 2ケ (No compatible products)	halogen headlamp car
			T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	T6.3 2ケ (No compatible products)	HID headlamp car Jスタイル
	2020.1～	MR92.52S	T10×31 1ケ (P408/409 ×1)	－	T10side 1ケ (P404 ×1)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P137 ×1)	－	－	－	－	halogen headlamp car ※1 It comes in 2 pieces, but only 1 piece is used.
			T10×31 1ケ (P408/409 ×1)	－	T10side 1ケ (P404 ×1)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P137 ×1)	－	－	－	－	led headlamp car ※1 It comes in 2 pieces, but only 1 piece is used.
palette	2008.1-2013.2	MK21S	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
palette SW	2009.9-2013.2	MK21S	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
randy	2007.1-2010.12	SC25.SNC25	T10×31 2ケ (P408/409 ×2)	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	T10×31 2ケ (P143 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2010.12-2016.8	SC26.SNC26 SHC26	T10 3ケ (P406/407 ×3)	T10×31 2ケ (P408/409 ×2)	T10×31 1ケ (P408/409 ×1)	※1 T10 3ケ (P145 ×2) (P141 ×2)	T10×31 2ケ (P143 ×2)	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	※1 It comes in 2 pieces, but only 3 pieces are used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			room lamp Recommended《CSP plate type》			room lamp《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
randy	2016.12-	SC27.SGC27 SGNC27	※1 T13 2ケ (P406/P407 ×2)	※1 T13 2ケ (P406/P407 ×2)	T10×31 1ケ (P408/P409 ×1)	※1 T13 2ケ (P145 ×1) (P141 ×1)	※1 T13 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 T13だがT10 type装着可能
Wagon R ※Continue to next page	1993.9-1998.9	CT.CV#	T8×29 1ケ (No compatible products)	－	T10 1ケ (P406/407 ×1)	T8×29 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	1998.10-2001.10	MC#	T10 1ケ (P406/407 ×1)	－	T10 1ケ (P406/407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the rear.
	2001.11-2003.8	MC#	T10 1ケ (P406/407 ×1)	－	T10 1ケ (P406/407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the rear.
			T10 1ケ (P406/407 ×1)	－	T10 1ケ (P406/407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	4-lamp halogen/HID lamp vehicle ※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the rear.
	2003.9-2005.8	MH#1S.22S	T10 1ケ (P406/407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	halogen headlamp car ※1 It comes in 2 pieces, but only 1 piece is used.
			T10 1ケ (P406/407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	HID headlamp car ※1 It comes in 2 pieces, but only 1 piece is used.
	2005.9-2008.8		T10 1ケ (P406/407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
			T10 1ケ (P406/407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2008.9-2012.8	MH23S	T10 1ケ (P406/407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			room lamp Recommended《CSP plate type》			room lamp 《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Wagon R	2012.9-2017.1	MH34.44S	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2017.2-2019.12	MH35.55S	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	halogen headlamp car
			T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	led headlamp car
	2020.1-	MH85.95S	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
Wagon R Stingray	2007.2-2008.8	MH21S.22S	T10 1ケ (P406/407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2008.9-2012.8	MH23S	T10 1ケ (P406/407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2012.9-2017.1	MH34.44S	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2017.2-2019.12	MH35.55S	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2020.1-	MH55.95S	T10×31 1ケ (P408/P409 ×1)	－	T10×31 1ケ (P408/P409 ×1)	T10×31 1ケ (P143 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	
Wagon R Smile	2021.9-	MX81.91S	T10×31 1ケ (P408/P409 ×1)	－	T10side 1ケ (P404 ×1)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P137 ×1)	－	－	－	－	halogen headlamp car ※1 It comes in 2 pieces, but only 1 piece is used.
			T10×31 1ケ (P408/P409 ×1)	－	T10side 1ケ (P404 ×1)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P137 ×1)	－	－	－	－	led headlamp car ※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			Recommended《CSP plate type》 room lamp			《バルブ type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Wagon R RR	1998.10-2003.8	MC#	T10 1ケ (P406/407 ×1)	－	T10 1ケ (P406/407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the rear.
	2003.9-2008.8	MH21S.22S	T10 1ケ (P406/407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	halogen headlamp car ※1 It comes in 2 pieces, but only 1 piece is used.
			T10 1ケ (P406/407 ×1)	－	T10×31 1ケ (P408/P409 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10×31 1ケ (P143 ×1)	－	－	－	－	HID headlamp car ※1 It comes in 2 pieces, but only 1 piece is used.
Wagon R wide	1997.2-1999.4	MA.MB61S	T8×29 1ケ (No compatible products)	－	T10 1ケ (P406/407 ×1)	T8×29 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
wagon R plus	1999.5-2000.11	MA63S	T10×31 1ケ (P408/P409 ×1)	－	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Wagon R Solio	2000.12-2005.7	MA64S.MA34S	T10 1ケ (P406/407 ×1)	－	T10 1ケ (P406/407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the rear.
	2002.6-2005.7		T10 1ケ (P406/407 ×1)	－	T10 1ケ (P406/407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	HID headlamp car ※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the rear.
			T10 1ケ (P406/407 ×1)	－	T10 1ケ (P406/407 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	halogen headlamp car round tail ※1 P145/141 comes in 2 pieces, so if you select P145/141 for the front, please use it for the rear.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation

Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark

※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			room lamp Recommended《CSP plate type》			room lamp《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
atrai	1994.1-1998.12	S12#.13#	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	1999.1-2005.4	S22#.23#	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2001.1-2005.4		－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	
	2022.1-	S700.710V	※1 T10 1ケ (P406/407 ×1)	Unconfirmed	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	Unconfirmed	－	※1 T10side 1ケ (P404 ×1)	－	－	－	※1 Standard LED settings are also available. ※2 It comes in 2 pieces, but only 1 piece is used.
atrai wagon	2005.5-2007.8	S32#G.33#G	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2007.9-2017.10		T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2017.11-2021.12		T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Atrai 7 (Seven)	2000.7-2004.12	S22#.23#	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

DAIHATSU			room lamp Recommended《CSP plate type》			room lamp《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Applause	1989.7-1997.8	A10#.11#	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	1997.9-2000.3		T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Altis	2000.3-2001.8	SXV2#N	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	G14 2ケ (No compatible products)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2001.9-2004.6	ACV3#N	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2004.7-2005.12		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2006.1-2010.2	ACV4#N	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
	2012.5-2014.7	AVV50N	T10 2ケ (P406/407 ×2)	T10×31 2ケ (P408/409 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 2ケ (P143 ×2)	－	－	※1.2 T10side 2ケ (P145 ×1)	－	※1 T10side 2ケ (P404 ×2)	※1 For front door/vanity, check the vehicle side installation setting.
	2014.8-2017.6		T10 2ケ (P406/407 ×2)	T10×31 2ケ (P408/409 ×2)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 2ケ (P143 ×2)	－	－	※1.2 T10side 2ケ (P145 ×1)	－	※1 T10side 2ケ (P404 ×2)	※1 For front door/vanity, check the vehicle side installation setting.
	2017.7-	AXVH70.75N	※LED	※LED	－	※LED	※LED	－	T10side 1ケ (P404 ×1)	T10side 2ケ (P404 ×2)	－	T10side 2ケ (P404 ×2)	※Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

DAIHATSU

Car model	model year	model	room lamp Recommended《CSP plate type》 front	room lamp center	room lamp rear	room lamp《bulb type》 front	room lamp center	room lamp rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
wake	2014.11-2016.4	LA700.710S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	－	※1 T10side 1ケ (P404 ×1)	－	－	－	※1 If the back door lamp also has a light fixture, you can use the same one.
	2016.5-		※1 T10 2ケ (P406/407 ×2)	―	※1 T10side 1ケ (P404 ×1)	※1 T10 2ケ (P145 ×1) (P141 ×1)	－	※1.2 T10side 1ケ (P145 ×1)	※1.3 T10side 1ケ (P404 ×1) ※2 (P145 ×1)	－	－	－	※1 Vehicles with standard LED settings are No compatible products. ※2 It comes in 2 pieces, but only 1 piece is used.If you select rear P137, you can use the remaining 1 piece. ※3If the back door lamp also has a light fixture, you can use the same
esse	2005.12-2011.9	L23#.24#	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	
Opti	1992.1-1998.10	L30#.31#	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
	1996.5-1998.10	L30#.31# クラシック	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	
	1998.11-2002.8	L80#.81#	T10×31 1ケ (P408/409 ×1)	－	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2000.3-2002.8												
cast	2015.9-	LA250.260S	※1 T10 2ケ (P406/407 ×2)	T10side 1ケ (P404 ×1)	－	※1 T10 2ケ (P145 ×1) (P141 ×1)	※2 T10side 1ケ (P145 ×1)		T10side 1ケ (P404 ×1) ※2 (P145 ×1)	－	－	－	※1 Replaceable even on cars with standard LED settings. ※2 It comes in 2 pieces, but only 1 piece is used. If you select P137 for center lamp, 1 piece can be used for luggage.
Coo	2006.5-2013.1	M40#.41#	※1 T10 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	※1 CSP doctor's office and doctor's office.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

DAIHATSU			room lamp Recommended《CSP plate type》			room lamp《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Copen	2002.6-2012.9	L880K	※1 T10×31 1ケ (No compatible products)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	※1 CSP is not possible due to lens interference
	2014.6-	LA400K	※1 T10×31 1ケ (No compatible products)	－	－	T10×31 1ケ (P143 ×1)	－	－	－	－	－	－	※1 CSP is not possible due to lens interference
charade	1993.1-2000.5	G20#.21#	T10×31 1ケ (P408/409 ×1)	－	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
		G20#.21#	T10×31 1ケ (P408/409 ×1)	－	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P143 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used. 1.5L car
Storia	1998.2-2000.4	M10#.11#	T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	－	
	2000.5-2001.11		T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	－	
	2001.12-2004.6		T8×29 1ケ (No compatible products)	－	－	T8×29 1ケ (P143 ×1)	－	－	－	－	－	－	
Sonica	2006.6-2009.5	L40#.41#	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	
tuft	2020.6-	LA900.910S	T10 2ケ (P406/407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	
Tanto	2003.11-2005.5	L350.360S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
※Continue to next page		L350,360S サンルーフ付	T10 2ケ (P406/407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation

Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark

※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

DAIHATSU			room lamp Recommended《CSP plate type》			room lamp《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Tanto	2005.6-2007.11	L350.360S	T10 2ケ (P406/407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	
	2007.12-2013.10	L375.385S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	2013.10-2019.7	LA600,610S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	
	2019.7-2022.9	LA650,660S	T10 2ケ (P406/407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
	2022.10-	LA650,660S	T10 2ケ (P406/407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Tanto custom	2003.11-2005.5	L350.360S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
		L350,360S サンルーフ付	T10 2ケ (P406/407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	
	2005.6-2007.11	L350.360S	T10 2ケ (P406/407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	
	2007.12-2013.10	L375.385S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	2013.10-2019.7	LA600,610S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	
	2019.7-2022.9	LA650,660S	T10 2ケ (P406/407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

DAIHATSU

Car model	model year	model	room lamp Recommended《CSP plate type》 front	room lamp center	room lamp rear	room lamp《bulb type》 front	room lamp center	room lamp rear	luggage (trunk)	door front	door slide(rear)	vanity	remarks
Tanto custom	2022.10-	LA650,660S	T10 2ケ (P406/407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1)	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
Tanto Exe	2009.12-2011.12	L455,465S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
			T10 2ケ (P406/407 ×2)	T10 1ケ (P406/407 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	overhead console ※1 It comes in 2 pieces, but only 1 piece is used.
	2011.12-2014.10		T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
			T10 2ケ (P406/407 ×2)	T10 1ケ (P406/407 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	overhead console ※1 It comes in 2 pieces, but only 1 piece is used.
Tanto Exe custom	2009.12-2011.11	L455,465S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
			T10 2ケ (P406/407 ×2)	T10 1ケ (P406/407 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	overhead console ※1 It comes in 2 pieces, but only 1 piece is used.
	2011.12-2014.10		T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
			T10 2ケ (P406/407 ×2)	T10 1ケ (P406/407 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	T10side 1ケ (P404 ×1)	－	－	－	overhead console ※1 It comes in 2 pieces, but only 1 piece is used.
Terios	1997.4-2000.4	J100G	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
	2000.5-2006.1	J10#.12#G	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			room lamp Recommended《CSP plate type》			room lamp《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
terio kid ※Continue to next page	1998.10-2012.4	J11#.13#G	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
terio kid	2000.11-2012.4	J11#.13#G	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
terio kid custom	2006.8-2012.4	J11#.13#G	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
Teriosulkia	2002.1-2003.8	J11#.13#G	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
			T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	Vehicle with rear tires
delta wide wagon	1992.1-1998.10	CB.YB2#.3#G	G14 2ケ (No compatible products)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	G14 2ケ (No compatible products)	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	
delta wagon	1996.11-2001.5	CR.SR4#.5#	T10×31 2ケ (P408/409 ×2)	※1 T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 2ケ (P143×2)	※1 T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	※1 Some vehicles are equipped with fluorescent lighting, in which case Not applicable
delta van	1996.11-2001.5	CR.KR4#.5#	G14 2ケ (No compatible products)	※1 T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	G14 2ケ (No compatible products)	※1 T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	※1 Some vehicles are equipped with fluorescent lighting, in which case Not applicable
Thor	2016.11-2020.8	M900.910S	T10 2ケ (P406/407 ×2)	T10 1ケ (P404 ×1)	T10 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10 1ケ (P404 ×1)	－	※2 T10 2ケ (P404 ×2)	－	※1 Since it comes in 2 pieces, please use one as a spare. ※2 The slide isDepending on the grade, it may or may not be set.
			CSPcomplete kit P18TC										※Same as Toyota Tank/Roomy Applicable areas: front, center, rear, luggage

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

DAIHATSU			room lamp						luggage (trunk)	door		vanity	remarks
			Recommended《CSP plate type》			《bulb type》							
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Thor	2020.9-	M900.910S	T10 2ケ (P406/407 ×2)	T10 1ケ (P404 ×1)	T10 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10 1ケ (P404 ×1)	－	※2 T10 2ケ (P404 ×2)	－	※1 Since it comes in 2 pieces, please use one as a spare. ※2 The slide isDepending on the grade, it may or may not be set.
			CSPcomplete kit P18TC										※Same as Toyota Tank/Roomy Applicable areas: front, center, rear, luggage
naked	1999.11-2001.12	L750.760S	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
	2002.1-2003.11		T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
			T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
pizer	1996.8-1997.8	G30#.G31#	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
	1997.9-1998.6		T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
	1998.7-2002.8		T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
hijet van	1996.1-1998.12	S100.110V	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
highjet cargo	1999.1-2004.11	S200.210V	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
※Continue to next page	2004.12-2007.12	S320.330V	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10×37 1ケ (No compatible products)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

DAIHATSU			room lamp Recommended《CSP plate type》			room lamp《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
highjet cargo	2007.12-2017.11	S321,331V	T10 1ケ (P406/407 ×1)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10×37 1ケ (No compatible products)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
highjet cargo	2017.11-2021.12	S321,331V	T10 1ケ (P406/407 ×1)	－	－	※1 T10 1ケ (P145 ×1) (P141 ×1)	－	－	T10×37 1ケ (No compatible products)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
highjet cargo	2022.1-	S700.710V	※1 T10 1ケ (P406/407 ×1)	Unconfirmed	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	Unconfirmed	－	※1 T10side 1ケ (P404 ×1)	－	－	－	※1 Standard LED settings are also available. ※2 It comes in 2 pieces, but only 1 piece is used.
highjet cargo	2022.1-	S700.710W	※1 T10 1ケ (P406/407 ×1)	Unconfirmed	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	Unconfirmed	－	－	－	－	－	deck van ※1 Standard LED settings are also available. ※2 It comes in 2 pieces, but only 1 piece is used.
Hijet Pick	1996.1-1998.12	S10#.11#	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	
highjet truck ※Continue to next page	1999.1-2004.11	S200,210P	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	
highjet truck ※Continue to next page	2004.12-2014.8	S201,211P	T10 1ケ (P406/407 ×1)	－	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used.
highjet truck ※Continue to next page	2014.9-2017.10	S500,510P	T10 1ケ (P406/407 ×1)	－	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	※2 T10side 1ケ (P404 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used. ※2 Rear side of seat change, not available depending on grade.
highjet truck ※Continue to next page	2017.11-2018.4	S500,510P	T10 1ケ (P406/407 ×1)	－	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	※2 T10side 1ケ (P404 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used. ※2 Rear side of seat change, not available depending on grade.
highjet truck ※Continue to next page	2017.11-2018.4	S500,510P											

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation

Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark

※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

DAIHATSU			room lamp						luggage (trunk)	door		vanity	remarks
			Recommended《CSP plate type》			《bulb type》							
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
highjet truck	2018.5-2018.7	S500,510P	T10 1ケ (P406/407 ×1)	－	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	※2 T10side 1ケ (P404 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used. ※2 Rear side of seat change, not available depending on grade.
	2018.8-	S500,510P	T10 1ケ (P406/407 ×1)	－	－	※1.2 T10 1ケ (P145 ×1) (P141 ×1)	－	－	※2 T10side 1ケ (P404 ×1)	－	－	－	※1 It comes in 2 pieces, but only 1 piece is used. ※2 Rear side of seat change, not available depending on grade.
Bigo	2006.1-2016.3	J200.210G	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
Boon	2004.6-2010.1	M30#.31#S	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
	2010.2-2016.4	M60#.61#	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	－	T10side 1ケ (P404 ×1)	－	－	－	
	2016.4-	M700,710S	T10 2ケ (P406/407 ×2)	－	－	T10 2ケ (P145 ×1) (P141 ×1)	－	－	－	－	－	－	
Boon custom	2004.12-2010.1	M30#.31#S	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
boon luminous	2008.12-2012.3	M502.512G	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	T10side 1ケ (P404 ×1)	－	－	－	
MAX	2001.11-2005.11	L95#.96#S	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

DAIHATSU			room lamp Recommended《CSP plate type》			room lamp《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
midget Ⅱ	1996.4-2001.7	K100P	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143×1)	－	T10×31 1ケ (P143×1)	－	－	－	－	
Mira ※Continue to next page	1990.3-1994.8	L200.210S	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	
Mira	1994.9-1997.4	L50#.51#S	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	
	1997.5-1998.9		T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	
	1995.10-1997.4		T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	CR.TR.TR-XX.moderno
	1997.5-1998.9		T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	CR.TR.TR-XX.moderno
	1998.10-2000.9	L70#.71#S	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	
	2000.10-2002.11		T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	
	2002.12-2006.11	L25#.26#S	※1 T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	※1 Room front may not be set depending on the grade.
	2006.12-2018.3	L27#.28#S	※1 T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	※1 Room front may not be set depending on the grade.
miraavi	2002.12-2006.11	L25#.26#S	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

DAIHATSU			room lamp Recommended《CSP plate type》			room lamp《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
mira e:s	2011.9-2017.5	LA300S.310S	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	
	2017.5-	LA350S.360S	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	
mira custom	2006.12-2013.2	L27#.28#S	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
mira cocoa	2009.8-2014.7	L67#.68#S	－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	
	2012.4-2014.7		－	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	
	2014.8-2018.3		－	※1 T10×31 1ケ (P408/409 ×1)	－	－	※1 T10×31 1ケ (P143×1)	－	－	－	－	－	※1 Not applicable for standard LED settings
Miragino	1999.3-2004.10	L70#.71#S	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	
	2004.11-2005.12	L65#.66#S	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
	2005.12-2009.4		T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
Miragino1000	2002.8-2004.11	L70#.71#	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	
miratkot	2018.6-	LA550.560S	※1 T10 2ケ (P406/407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※2 T10side 1ケ (P145 ×1)	－	－	－	－	－	※1 Not applicable to cars with standard LED settings. ※2 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			room lamp Recommended《CSP plate type》			room lamp《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Move	1995.8-1997.4	L60#.61#	T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	
	1997.5-1998.9		T10×31 1ケ (P408/409 ×1)	－	－	T10×31 1ケ (P143×1)	－	－	－	－	－	－	
	1998.10-2000.9	L90#.91#	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2000.10-2002.9		T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2002.10-2006.9	L15#.16#S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	T10side 2ケ (P404 ×2)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	T10side 2ケ (P145 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
	2006.10-2010.11	L17#.18#S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	T10side 2ケ (P404 ×2)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	T10side 2ケ (P145 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
	2010.12-2014.12	LA100S.110S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	T10side 2ケ (P404 ×2)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	T10side 2ケ (P145 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
	2014.12-	LA150.160S	T10 2ケ (P406/407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1)		T10side 1ケ (P404 ×1) ※1 (P145 ×1)	－	－	－	※1 If you select P137 as the center lamp, it can be used in luggage as it comes in 2 pieces.
Move custom ※Continue to next page	1998.10-2000.9	L90#.91#S	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2000.10-2002.9		T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	T10×31 1ケ (P408/409 ×1) (P143 ×1)	－	－	－	
	2002.10-2006.9	L15#.16#S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	T10side 2ケ (P404 ×2)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	T10side 2ケ (P145 ×1)	T10side 1ケ (P404 ×1)	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			Recommended《CSP plate type》 room lamp			《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
Move custom	2006.10-2008.11	L17#.18#S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	T10side 2ケ (P404 ×2)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	T10side 2ケ (P145 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
	2008.12-2010.11		T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	T10side 2ケ (P404 ×2)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	T10side 2ケ (P145 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
	2010.12-2012.11	LA100S.110S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	T10side 2ケ (P404 ×2)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	T10side 2ケ (P145 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
	2012.12-2014.12		T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	－	T10side 2ケ (P404 ×2)	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	－	T10side 2ケ (P145 ×1)	T10side 1ケ (P404 ×1)	－	－	－	
	2014.12-	LA150.160S	T10 2ケ (P406/407 ×2)	T10side 1ケ (P404 ×1)	T10side 1ケ (P404 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1)	－	T10side 1ケ (P404 ×1) ※1 (P145 ×1)	－	－	－	※1 If you select P137 as the center lamp, it can be used in luggage as it comes in 2 pieces.
move canvas	2016.9-2022.6	LA800.810S	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
	2022.7-	LA850.860S	T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
Move Conte	2008.8-2017.3	L57#.58#S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
Move Conte custom	2008.8-2017.3	L57#.58#S	T10×31 1ケ (P408/409 ×1) T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143 ×1) T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	
move latte	2004.8-2009.4	L55#.56#S	※1 T10 2ケ (P406/407 ×2)	T10×31 1ケ (P408/409 ×1)	－	※1 T10 2ケ (P145 ×1) (P141 ×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	※1 Room front may not be set depending on the grade.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			room lamp Recommended《CSP plate type》			room lamp《bulb type》			luggage (trunk)	door		vanity	remarks
Car model	model year	model	front	center	rear	front	center	rear		front	slide(rear)		
rocky	2019.11-	A200.210S	T10 2ケ (P406/407 ×2)	T10side 1ケ (P404 ×1)	－	T10 2ケ (P145 ×1) (P141 ×1)	※1 T10side 1ケ (P145 ×1)	－	T10side 1ケ (P404 ×1) ※1 (P145 ×1)	－	－	－	※1 If you select P137 as the center lamp, it can be used in luggage as it comes in 2 pieces.
			CSPcomplete kit P27TC										※Same as for Toyota Rise Applicable location：front、center、luggage
YRV	2000.8-2005.7	M20#.21#	T10×31 1ケ (P408/409 ×1)	T10×31 1ケ (P408/409 ×1)	－	T10×31 1ケ (P143×1)	T10×31 1ケ (P143×1)	－	－	－	－	－	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
IQ	2008.11-2016.4	KGJ.NGK10	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable due to LED lamp
Isis	2004.9-2007.4	ANM.ZNM1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2007.5-2009.9		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2009.9-2012.6	ZGM1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2012.6-2015.5		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2015.5-2017.10		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
aqua including crossover	2011.12-2014.11	NHP10.10H	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 The stop is Not applicable due to LED lamp, and the tail is T10, but No applicable products.
	2014.12-2021.6		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable to LED lamp vehicles, some G's etc. have 2 T10 specifications. In that case, P145/P141 is recommended. ※2 Not applicable due to LED lamp
	2021.7-	MXPK1#	※1 LED	※1 T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	※2 LED	※2 LED	※1 Not applicable to Bi-Beam headlamp vehicles (standard for Zgrade, optional for G.X) because they are LED. ※2 Not applicable due to LED lamp
Avalon	1995.5-1997.9	MCX10	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1997.10-1999.6		Integrated with cornering (No applicable products)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
avensis	2003.10-2006.6	AZT25# AZT25#W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	Sedan: S25 single (No applicable products) wagon:※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2006.7-2008.8		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	Sedan: S25 single (No applicable products) wagon:※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2011.9-2015.9	ZRT272W	※1 LED	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2015.10-2018.4		※1 LED	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Arion	2001.12-2004.11	AZT24# NZT24# ZZT24#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−.
	2004.12-2007.5		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2007.6-2010.3	ZRT26# NZT26#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−.
	2010.4-2016.5		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2012.12-2021.3		※1 LED or T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp
Aristo	1997.8-2000.6	JZS16#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−.
	2000.7-2004.12		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
Altezza	1998.10-2005.7	GXE1# SXE1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
Altezza Gita	2001.7-2003.7	JCE1#W GXE1#W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2003.8-2005.7		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
Alphard	2002.5-2005.3	ANH1# MNH1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	MS,AS ※1 Not applicable because the polarity does not correspond
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double Stop: T20 single (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	MZ,MX,AX ※1 Tail stop is not applicable because the polarity is not compatible
	2005.4-2008.4		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double Stop: T20 single (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
Alphard Vellfire	2008.5-2013.12	ANH2# GGH2#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
	2013.12-2015.1		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
Alphard Vellfire ※Continue to next page	2015.1-2017.12	AGH.GGH3#	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
Alphard Vellfire	2018.1-R.5.6	AGH.GGH3#	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
	2023.7-	AAHH4#W AGH40W	※LED	※LED	※LED	※LED	※LED	※LED	※All outdoor lights are LED and cannot be replaced.
alphard hybrid	2003.7-2008.4	ATH1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※1 T20 double Stop: T20 single (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
alphard hybrid Vellfire hybrid ※Continue to next page	2011.11-2013.12	ATH20W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
	2013.12-2015.1		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
	2015.1-2017.12	AYH30	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
alphard hybrid Vellfire hybrid	2018.1-2023.6	AYH30	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
alex	2001.1-2002.8	NZE12# ZZE12#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2002.9-2004.3		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	HID specification car ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	halogen specification car ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2004.4-2006.9		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	HID specification car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	halogen specification car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
ist ※Continue to next page	2002.5-2005.4	NCP6#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	typeS ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 double 2ケ (No applicable products)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	typeF halogen specification car ※1 Tail stop is not applicable because the polarity is not compatible
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	typeF HID specification car ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
ist	2005.5-2006.12	NCP6#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2006.12-2007.7	NCP6#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2007.7-2016.5	NCP11# ZSP110	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
ipsum	2001.5-2009.12	ACM2#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double Stop: T20 single (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible The tail position is T10, but there is no applicable product.
vanguard	2007.8-2010.1	ACA33W GSA33W ACA38W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Vehicles with rear spare tire are not allowed.
	2010.1-2013.11	ACA3#W GSA33W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Vehicles with rear spare tire are not allowed.
WILL Cipher	2002.10-2005.7	NCP7#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
WILL Vi	2000.1-2001.12	NCP1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
WILL VS	2001.4-2004.4	NZE12# ZZE12#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
WISH	2003.1-2009.3	ANE1# ZNE1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
※Continue to next page	2009.4-2012.3	ZGE2#W ZGE2#G	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
WISH	2012.4-2017.10	ZGE2#W ZGE2#G	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Vitz	1999.1-2005.1	NCP1# SCP1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2001.12-2002.11		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	RS,グラヴィア ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2002.12-2005.1		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
	2005.2-2006.1	KSP9# NCP9# SCP9#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
	2005.2-2006.1		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	RS ※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
	2006.1-2007.7		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
	2006.1-2007.7		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	RS ※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
Vitz	2007.8-2010.12	KSP9# NCP9# SCP9#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
※Continue to next page	2007.8-2008.8		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	RS ※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
Vitz	2008.9-2010.12		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	RS ※1 Not applicable due to LED lamp
	2010.12-2014.3	NSP13# KSP130 NCP131 NHP130	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
	2014.4-2016.12		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
	2017.1-2020.3		※1 LED orT10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp
Verossa	2001.7-2004.4	GX110# JZX11#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +－ +－.
Voxy ※Continue to next page	2001.11-2007.5	AZR6#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2007.6-2014.1	ZRR70W,G ZRR75W,G	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
	2014.1-2022.1	ZRR8# ZWR8#	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
Voxy	2015.1-2022.1	ZRR8# ZWR8#	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2014.1-2022.1								
	2022.1-	ZWR90.95W MZRA90.95W	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
Volz	2002.8-2004.4	ZZE13#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
esquire	2014.1-2021.12	ZRR8# ZWR8#	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2015.1-2021.12		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2014.1-2021.12								
Estima	1990.5-1997.12	TCR1# TCR2#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1998.1-1999.12		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2000.1-2005.12	ACR.MCR3# ACR.MCR4#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2006.1-2016.5	ACR5# GSR5#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2016.6-2020.3 2019.10生産終了		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
Estima Hybrid	2001.6-2003.7	AHR10W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	※1 LED	※2 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Tail stop is not applicable because the polarity is not compatible
	2003.8-2006.5		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2006.6-2016.5	AHR20W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2016.6-2020.3 2019.10生産終了	AHR20W	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
FJ cruiser	2010.12-2018.1	GSJ15W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 double (No applicable products)	T16 2ケ (No applicable products)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
MR-S	1999.10-2002.7	ZZW3#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2002.8-2007.7		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
Auris	2006.10-2009.10	ZRE15#H NZE15#H	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	The tail position is T10, but there is no applicable product.
	2009.10-2012.5	ZRE15#H NZE15#H	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	The tail position is T10, but there is no applicable product.
	2012.6-2015.3	NEZ18# ZRE18#	※1 LED orT10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※2 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ※2 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2015.4-2018.3	NRE18# NEZ18# ZRE18# ZWE18#	※1 LED orT10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	S25シングル (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ﾃｰﾙﾎﾟｼﾞｼｮﾝはLEDの為、No applicable products

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
camry	2001.9-2004.6	ACV3#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
	2004.7-2005.12		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each) Stop: T20 single (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
	2006.1-2011.9	ACV4#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
	2011.9-2014.7	AVV50	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
	2014.8-2017.6		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2017.7-	AXVH70.75	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	WS.Ggrade ※1 Not applicable due to LED lamp
			※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	Xgrade ※1 Not applicable due to LED lamp
Caldina	2002.9-2007.5	AZT24# ST24# ZZT24#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
corolla corolla touring corolla sport	2019.9-2022.9 (sports 2018.6-)	NRE.ZWE. ZRE211(W/H)	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	※2 LED or T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Not applicable to Corolla Touring and Sports because they are LED.
	2022.10-		※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	※2 LED or T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Not applicable to Corolla Touring and Sports because they are LED.
corolla axio ※Continue to next page	2012.5-2017.9	NRE.NZE.NKE16 #	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
corolla axio	2017.10-	NRE.NZE.NKE16#	※1 LED orT10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps
corolla cross	2021.9-	ZVG11.15 ZSG10	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	Zgrade ※1 Not applicable due to LED lamp
			T20 2ケ (No applicable products)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	S.Ggrade
corolla fielder	2012.5-2015.2	ZRE162G NZE161G.164G	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ﾃｰﾙﾎﾟｼﾞｼｮﾝはLEDの為、No applicable products
	2015.3-	ZRE162G NZE161G.164G NKE16#	※1 LED orT10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED or ※2 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ※2 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
Corolla Lumion	2007.10-2015.11	ZRE15# NZE15#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
		ZRE15# NZE15#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
Gran Ace	GDH303W	2019.12-	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
crown athlete (including hybrid) ※Continue to next page	1999.9-2003.11	JZS17#	Integrated with cornering (No applicable products)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Stop and tail is not possible because the bulb burnout warning light is on and the resistor cannot be installed.
	2003.12-2008.1	GRS18#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable due to LED lamp
	2008.2-2012.12	GRS20# GWS20#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
crown athlete (including hybrid)	2012.12-2015.9	GRS21# GWS214 AWS21# ARS210	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2015.10-2018.5		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
crown royal saloon	1999.9-2001.7	GS17# JKS17# JZS17#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Stop and tail is not possible because the bulb burnout warning light is on and the resistor cannot be installed.
	2001.8-2003.11		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Stop and tail is not possible because the bulb burnout warning light is on and the resistor cannot be installed.
	2003.12-2008.1	GRS18#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable due to LED lamp
	2008.2-2012.12	GRS20# GWS20#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2012.12-2015.9	GRS21# GWS214 AWS21#	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2015.10-2018.5		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
crown	2018.6-	GWS.AWS22# AZSH2# ARS22#	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
crown estate (athlete)	1999.12-2007.5	JZS17#W	Integrated with cornering (No applicable products)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Stop and tail is not possible because the bulb burnout warning light is on and the resistor cannot be installed.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
crown estate (royal)	1999.12-2007.5	JZS17#W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Stop and tail is not possible because the bulb burnout warning light is on and the resistor cannot be installed.
crown sedan	1995.12-2001.7	GS15# JZS15# LS15#	Integrated with cornering (No applicable products)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Stop and tail is not possible because the bulb burnout warning light is on and the resistor cannot be installed.
	2001.8-2009.8	GBS1# GXS1# YXS1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (Not applicable)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Stop and tail is not possible because the bulb burnout warning light is on and the resistor cannot be installed.
crown majesta ※Continue to next page	1999.9-2001.7	JZS17# UZS17#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Stop and tail is not possible because the bulb burnout warning light is on and the resistor cannot be installed.
	2001.8-2004.6		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Stop and tail is not possible because the bulb burnout warning light is on and the resistor cannot be installed.
	2004.7-2009.2	UZS18#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2009.3-2013.4	URS206 UZS207	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable due to LED lamp
	2013.4-2013.8	URS206 UZS207	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable due to LED lamp
	2013.9-2018.4	GWS214 AWS215	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2015.6-2018.4		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
crown majesta	2015.10-2018.4	GWS214 AWS215	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
crown comfort	1995.12-	GXS10 YXS10	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (Not applicable)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Stop and tail is not possible because the bulb burnout warning light is on and the resistor cannot be installed.
comfort	1995.12-	LXS11 SXS11 YXS11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (Not applicable)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Stop and tail is not possible because the bulb burnout warning light is on and the resistor cannot be installed.
kruger	2000.11-2007.5	ACU2# MCU2#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-.
kruger hybrid	2005.3-2007.5	MHU28W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Cresta chaser	1992.10-1996.8	GX9# JZX9# LX9# SX9#	Integrated with cornering (No applicable products)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-.
	1996.9-2001.6	GX10# JZX10# LX10#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-.
Mark II	1992.10-1996.8	GX9# JZX9# LX9# SX9#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-.
	1996.9-2001.6	GX10# JZX10# LX10#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-.
	2000.10-2004.10	GX11# JZX11#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-.
Copen GR SPORTS	2019.10-	LA400A	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 バルブ使用は1ケ P137は2ケ入りなので、1ケ余ります。
Premio ※Continue to next page	2007.6-2016.5	ZRT26# NZT26#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED or ※2 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ※2 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
Premio	2016.6-2021.3	ZRT26# NZT26#	※1 LED orT10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp
SAI	2009.12-2013.7	AZK10	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2013.8-2017.11		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Succeed pro box	2002.7-2014.7	NCP58G NCP59G	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2014.8- (サクシード2020.5迄)	NHP.NSP160V	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
C-HR ※Continue to next page	2016.12-2019.9	NGX50 ZYX10	※1 LED	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2019.10-	NGX10.50 ZYX10.11	※1 LED	※1 LED or T20 2ケ (P621 ×1)	※1 LED or T20 2ケ (P621 ×1)	※1 LED	※1 LED T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
C-HR	2019.10-	NGX10.50 ZYX10.11							
Sienta	2003.9-2015.6	NCP81G NCP85G	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2015.6-2022.7	NCP175 NHP.NSP17#	※1 LED orT10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp
	2022.8-	MXPL10.15 MXPC10	※1 LED orT10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	※1 LED or T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp
spade	2012.7-2015.7	NCP.NSP14#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2015.7-2020.12		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
supra	1993.5-1996.4	JZA80	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1996.5-2002.7		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2019.5-	DB02.22.82	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
Celsior	2000.8-2003.7	UCF3#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2003.8-2006.5		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
century	2018.6-	UWG60	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
Soarer	1991.5-1993.12	JZZ3# UZZ3#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1994.1-2001.3		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	S25シングル (No applicable products)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
	2001.4-2005.6	UZZ4#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−.
tank Roomy	2016.11-2020.9 Tank up to 2020.9	M9#0A	※1 LED orT10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Roomy	2020.9-	M9#0A	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
town ace van ※Continue to next page	2008.2-2020.5	S402.412M	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
town ace van	2020.6-	S403.413M	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
town ace truck	2008.2-2020.5	S402.412U	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 1ケ (P623 ×1)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2020.6-	S403.413U	※1 LED	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 1ケ (P623 ×1)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Noah	2001.11-2007.5	AZR6#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2007.6-2014.1	ZRR70W,G ZRR75W,G	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp The tail position is T10, but there is no applicable product.
	2014.1-2022.1	ZRR8# ZWR8#	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2015.1-2022.1		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2014.1-2022.1								
	2022.1-	ZWR9#W MZRA9#W							
hiace（100 series） ※Continue to next page	1989.8-1993.7	KZH.LH.RZH10# ～18#	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1993.8-1996.7		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
hiace（100 series）	1996.8-1999.6	KZH.LH.RZH10#～18#	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1999.7-2004.7		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
hiace Regius Ace（200 series）	2004.8-	KDH.TRH.GDH2##	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
hilux surf	1989.5-1995.11	KZN13# LN13# YN13# VZN13#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	Back lamp integrated car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	Lighting vehicle with separate back lamp ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1995.12-2000.6	KDN18# KZN18# RZN18# VZN18#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2000.7-2002.10		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2002.11-2005.6	KDN.RZN.VZN.GRN.TRN21#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2005.7-2009.7		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
86	2012.4-2016.6	ZN6	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 1ケ (P623 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2016.7-2021.10		※1 LED	※1 LED	※1 LED	※1 LED	T16 1ケ (P623 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
GR86	2021.10-	ZN8	※1 LED	※1 LED	※1 LED	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
passo	2004.6-2010.1	KGC1# QNC1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-.
	2010.2-2016.3	NGC30 KGC30/35	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2016.4-	M700.710A	※1 LED orT10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp
Passosette	2008.12-2012.3	M502E M512E	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-.
harrier ※Continue to next page	1997.12-2003.1	ACU1# MCU1# SXU1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-.
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-.
	2003.2-2013.7	ACU.GSU3#W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2013.12-2015.3	ZSU6#W AVU65W	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
harrier	2015.4-2020.6	ASU.ZSU6#W AVU65W	※1 LED	※2 T20 2ケ (P621 ×1)	※2 T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp ※2 Vehicles equipped with AHS (Adaptive High Beam System) do not have turn signals applicable due to LED lamps.
	2020.6-	MXUA8#	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
harrier hybrid	2005.3-2013.7	MHU38W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
bB	2000.2-2003.3	NCP3#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2003.4-2005.11		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2005.12-2008.9	QNC20 QNC21 QNC25	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2008.10-2014.7		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2014.8-2016.7		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Tail stop is not applicable because the polarity is not compatible ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Pyxis Epoch	2012.5-2017.5	LA300A.310A	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2017.6-	LA350A.360A	※1 LED orT10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※2 LED	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
pixis joy	2015.9-	LA250.260S	※1 LED orT10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
pixis space	2011.9-2017.1	L57#.58#	T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ヶ (P623 ×2)	※2 T10 1ヶ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
pixis track	2011.12-2014.8	S201U.211U	T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ヶ (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 1ヶ (P625 ×1)	G18 1ヶ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2014.9-2018.4	S500U.510U	T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T16 2ヶ (No applicable products)	※1 T20 double (Not applicable)	S25 1ヶ (P625 ×1)	G18 1ヶ (P211 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2018.5-		T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ヶ (No applicable products)	※1 T20 double (Not applicable)	T16 1ヶ (P623 ×1)	※2 T10 1ヶ (P145 ×1) (P141 ×1)	halogen headlamp car ※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ヶ (P621 ×1)	T16 2ヶ (No applicable products)	※2 T20 double (Not applicable)	T16 1ヶ (P623 ×1)	※3 T10 1ヶ (P145 ×1) (P141 ×1)	led headlamp car ※1 Not applicable due to LED lamp ※2 Tail stop is not applicable because the polarity is not compatible ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
pixis van	2011.12-2017.11	S321M	T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ヶ (P623 ×2)	※2 T10 1ヶ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2017.12-2021.11	S3#1M	T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	※2 T10 1ヶ (P145 ×1)	halogen headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	※2 T10 1ヶ (P145 ×1)	led headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2021.12-	S700.710M	※1 LED or T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	※2 T10 1ヶ (P145 ×1)	※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
pixis mega ※Continue to next page	2015.7-2016.4	LA700A.710A	※1 LED	T20 2ヶ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ヶ (P623 ×2)	T10 2ヶ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
pixis mega	2016.5-	LA700A.710A	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	halogen headlamp car ※1 Not applicable due to LED lamp
			※1 LED	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	led headlamp car ※1 Not applicable due to LED lamp
fan cargo	1999.8-2005.9	NCP2#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
platz	1999.8-2003.7	NCP1# SCP1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2003.8-2005.11		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
prius ※Continue to next page	1997.12-2000.4	NHW1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2000.5-2003.8		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2003.9-2009.4	NHW2#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2009.5-2011.11	ZVW30	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable due to LED lamp
	2011.12-2013.6		※1 LED or T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp
	2013.6-2015.5		※1 LED or T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
prius	2015.5-2015.12	ZVW30	※1 LED or T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp
	2015.12-2018.11	ZVW5#	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable for LED lamps
	2018.12-		※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
prius α	2011.5-2013.6	ZVW40/41	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable due to LED lamp
	2013.6-2015.5		※1 LED or T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	Vehicles equipped with LED headlamps have standard LED lights. ※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp
	2015.5-2021.3	ZVW40/41	※1 LED or T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	Vehicles equipped with LED headlamps have standard LED lights. ※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp
priusPHV ※Continue to next page	2012.1-2013.6	ZVW35	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable due to LED lamp
	2013.6-2015.5		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable due to LED lamp
	2015.5-2016.5		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
priusPHV	2017.2-	ZVW52	※1 LED	※1 LED	※1 LED	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
blade	2006.12-2012.4	GRE156H AZE154.156H	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
brevis	2001.6-2007.5	JCG1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2005.12-2007.5		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20シングル (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 The tail position is T10, but there is no applicable product.
Premio	2012.12-2016.5	NZT.ZRT26#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED or T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible。純正LEDの場合Not applicable。
	2016.6-2021.3		※1 LED or T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp
Progre	1998.5-2007.5	JCG1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
Bertha	2005.11-2012.6	SCP92 KSP92 NCP96	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Porte	2004.7-2012.5	NNP10 NNP11 NNP15	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
※Continue to next page	2012.7-2015.7	NCP.NSP14#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
Porte	2015.7-2020.12	NCP.NSP14#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Mark X	2004.11-2009.9	GRX12#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2009.10-2012.7	GRX13#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2012.8-2013.2		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2013.3-2019.12		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
mark x geo	2007.9-2013.11	GGA1# ANA1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Mark Ⅱ brit	2002.1-2007.5	GX11# JZX11#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
Mirai	2014.12-2020.11	JPD10	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
	2020.12-	JPD20	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
yaris Yaris Cross	2020.2- 2020.8-	MXPH,MXPA1# KSP10 MXPB1,MXPJ1#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	※1 LED ※2 T16 2ケ (P623 2ケ)	T10 2ケ (P145 ×1) (P141 ×1)	halogen headlamp car ※1 Not applicable due to LED lamp ※2 Yaris Cross has T16 valve.
			※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	T10 2ケ (P145 ×1) (P141 ×1)	led headlamp car
									Applicable areas: center, rear luggage
									Zgrade Applicable areas: center, rear luggage、vanity
raise	2019.10-	A200.210A	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
light ace	1992.1-1996.9	CR.KR.TR.YR2# CR.KR.TR.YR3#	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
light ace van	2008.2-2020.5	S402.412M	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−.
	2020.6-	S403.413M	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
light ace truck	2008.2-2020.5	S402.412U	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 1ケ (P623 ×1)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2020.6-	S403.413U	※1 LED	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 1ケ (P623 ×1)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
light ace noah (Town Ace Noah) ※Continue to next page	1996.10-1998.11	CR.KR.SR4# CR.KR.SR5#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
light ace noah (Town Ace Noah)	1998.12-2001.10	CR.KR.SR4# CR.KR.SR5#	T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ヶ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ヶ (P624 ×2)	T10 2ヶ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
raum	1997.5-2003.4	EXZ1#	T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ヶ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ヶ (P624 ×2)	T10 2ヶ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2003.5-2006.11	NCZ20 NCZ25	T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED or T20 double (Not applicable)	T20 2ヶ (P624 ×2)	T10 2ヶ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible。純正LEDの場合 Not applicable。
	2006.12-2011.10		T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	T10 2ヶ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
RAV4 (hybrid/PHV)	2005.11-2015.5	ACA3#W	T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	※2 T10 2ヶ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Not applicable for vehicles equipped with a rear spare tire due to light distribution issues.
	2015.5-2016.7		T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	※2 T10 2ヶ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Not applicable for vehicles equipped with a rear spare tire due to light distribution issues.
	H31.3-	MXAA5# AXAH5# AXAP54	※1 LED	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
Ractis	2005.10-2010.10	NCP10# SCP10#	T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ヶ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ヶ (P623 ×2)	※2 T10 1ヶ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2007.12-2010.10		T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ヶ (P623 ×2)	※2 T10 1ヶ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2010.11-2014.4	NCP12# NSP12#	T10 2ヶ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED or T20 double (Not applicable)	T16 2ヶ (P623 ×2)	T10 2ヶ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible。純正LEDの場合 Not applicable。
	2014.5-2016.9		※1 LED	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	T10 2ヶ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
Rush	2006.1-2016.3	J210E J200E	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
land cruiser70	1987.8-2004.4	HZJ7#	Unconfirmed	Unconfirmed	Unconfirmed	Unconfirmed	Unconfirmed	T10 2ケ (P145 ×1) (P141 ×1)	
	2014.8-2015.7	GRJ76K	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (No applicable products)	S25 2ケ (P625 ×2)	G18 2ケ (P211 ×2)	van ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
		GRJ79K	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (No applicable products)	S25 2ケ (P625 ×2)	G18 2ケ (P211 ×2)	pickup ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2023.11-2024.9 2024.10-	GDJ76W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (No applicable products)	S25 2ケ (P625 ×2)	G18 2ケ (P211 ×2)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
land cruiser80	1989.10-1997.12	FJ.FZJ.HDJ. HZJ8#	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (No applicable products)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible。純正LEDの場合Not applicable。
land cruiser prado	1996.5-1999.5	KDJ.KZJ.RZJ. VZJ90#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (No applicable products)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible。純正LEDの場合Not applicable。
	1999.6-2002.9		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible。純正LEDの場合Not applicable。
	2002.10-2009.8	GRJ.KDJ.RZJ. TRJ.VZJ12#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible。純正LEDの場合Not applicable。
land cruiser prado	2009.9-2013.8	GRJ.TRJ15# GDJ15#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	gradeTX ※1 Not applicable due to LED lamp
	2013.8-	GRJ.TRJ15# GDJ15#	※1 LED or T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	gradeTX ※1 Not applicable for LED lamps

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
land cruiser prado	2009.9-2013.8	GRJ.TRJ15# GDJ15#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	gradeTZ-G,TX(Lpackage) ※1 Not applicable for LED lamps
	2013.8-		※1 LED or T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	gradeTZ-G,TX(Lpackage) ※1 Not applicable for LED lamps
land cruiser100	1998.1-2005.3	HDJ10# UZJ10#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible。純正LEDの場合 Not applicable。
	2005.4-2007.8		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
land cruiser200	2007.9-2011.10	URJ20# UZJ20#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	Early period ※1 Not applicable due to LED lamp
	2011.11-2013.7		※1 LED	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	middle period ※1 Not applicable due to LED lamp
	2013.8-2015.7		※1 LED	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	Late period ※1 Not applicable due to LED lamp
	2015.8-2021.8		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	Late period ※1 Not applicable due to LED lamp
land cruiser300	2021.8-	FJA300W VJA300W	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
land cruiser cygnus ※Continue to next page	1999.1-2002.7	UZJ10#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible。純正LEDの場合 Not applicable。

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified.
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

TOYOTA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	Model		front	rear				
land cruiser cygnus	2002.8-2007.8	UZJ10#	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible。純正LEDの場合Not applicable。

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

LEXUS			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
ES	2018.10-	AXZH10	※1 LED	※2 T20 2ケ (P621 ×1)	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp ※2 Trinocular full LED car is Not applicable due to LED lamp
HS	2009.7-2012.12	ANF10	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2013.1-2018.3		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
IS	2005.9-2010.7	GSE2#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
	2010.8-2013.4		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
	2013.5-2016.9	GSE.AVE3#	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
	2016.10-2020.10	GSE.AVE ASE3#	※1 LED	※2 T20 2ケ (P621 ×1)	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp ※2 Trinocular full LED car is Not applicable due to LED lamp
	2020.11-	GSE.AVEASE3#	※1 LED	※2 T20 2ケ (P621 ×1)	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp ※2 Trinocular full LED car is Not applicable due to LED lamp
IS F	2007.12-2014.5	USE20	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Some LED lamp specifications are available. Not applicable ※2 Not applicable due to LED lamp
ISconvertible	2009.5-	GSE2#	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Some LED lamp specifications are available. Not applicable ※2 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

LEXUS			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
RX	2009.1-2012.3	GGL1#W	T10 2ヶ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
	2009.4-2012.3	GYL1#W	T10 2ヶ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
	2012.4-2015.9	AGL.GGL GYL1#	※1 LED	T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
	2015.10-	GYL2#	※1 LED	※2 T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp ※2 Trinocular full LED car is Not applicable due to LED lamp
RC	2014.10-2018.9	CGC.AVC1#	※1 LED	※2 T20 2ヶ (P621 ×1)	T20 2ヶ (P621 ×1)	※1 LED	T16 2ヶ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp ※2 Trinocular full LED car is Not applicable due to LED lamp
	2018.11-	GSC.AVC,ASC1 #	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
LS	2006.9-2009.9	USF4#	T10 2ヶ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ヶ (P621 ×1)	T16 (No applicable products)	※1 LED	T16 2ヶ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
	2009.10-2017.9		※1 LED	※2 T20 2ヶ (P621 ×1)	※2 T20 (No applicable products)	※1 LED	※2 T16 2ヶ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp ※2 LEDランプ仕様あり。 Not applicable
	2017.10-	VXFA5#	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

LEXUS			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
LC	2017.3-	GWZ100	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
LFA	2010.10-2012.12	LFA10	※1 LED	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1 LED	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
LS hybrid	2007.5-2012.9	UVF4#	※1 LED	T20 2ケ (P621 ×1)	※2 T16 (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
SC	2005.8-2010.7	UZZ4#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	※1 LED	※1 Not applicable due to LED lamp
CT	2011.1-2017.7	ZWA10	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※1 T10 2ケ (P145 ×1) (P141 ×1)	※1 LED lamp specifications available. Not applicable ※2 Not applicable due to LED lamp
	2017.8-		※1 LED	※2 T20 2ケ (P621 ×1)	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp ※2 LED lamp specifications available. Not applicable
GS	2005.8-2011.12	GRS.UZS.URS 19#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
	2012.1-27.10	GRL1#	※1 LED	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
GS F	2015.11-2020.9	URL10	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

LEXUS			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
GS hybrid	2006.3-2011.12	GWS19#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
	2012.3-	GWL10	※1 LED	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
UX	2018.11-	MZAH1# MZAA1#	※1 LED	※2 T20 2ケ (P621 ×1)	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp ※2 Trinocular full LED car is Not applicable due to LED lamp
NX	2014.7-2017.8	AYZ/AGZ1#	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
	2017.9-		※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
avenir	1990.5-1998.7	W10	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1998.8-2005.10	W11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
infiniti q45	1989.11-1997.7	G50	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
wing road	1996.5-1999.4	Y10	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	1999.5-1997.9	Y11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2001.10-2005.10		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2005.11-2018.3	Y12	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	※1 T20 (No applicable products)	※2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 There are T20 amber vehicles depending on the grade. *2 Please check the polarity on the vehicle side. socket end Not applicable if child is not +, –, +, – *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
expert	1999.6-2005.10	W11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
AD Wagon	1990.10-1999.5	Y10	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
Advan	1990.10-1999.5	Y10	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1999.6-2001.9	Y11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	2001.10-2005.10		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
AD/AD Expert	2007.1-	Y12	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
NT100 clipper	2013.12-	DR16T	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 (No applicable products)	※1 S25 double 2ケ (P616＋P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side – ※2 It comes in 2 pieces, but only 1 piece
NV100 clipper	2013.12-2015.2	DR64V	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 S25 double 2ケ (P616＋P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side – ※2 It comes in 2 pieces, but only 1 piece

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
NV100 clipper	2015.3-	DR17V	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1 T20 double 2ケ (P615＋P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if child is not +, −, +, − ※2 It comes in 2 pieces, but only 1 piece is used.
NV100 Clipper Rio	2013.12-2015.2	DR64W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 T20 double 2ケ (P615＋P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if child is not +, −, +, − ※2 It comes in 2 pieces, but only 1 piece is used.
	2015.3-	DR17W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
x-trail ※Continue to next page	2000.11-2007.7	T30	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2007.8-2010.6	T31	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	※1 T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2010.7-2015.2		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2013.12-2017.6	T32 NT32	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20single (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2015.4-2017.6	HT32.NHT32 hybrid	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20single (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
x-trail	2017.6-2022.6	T32.NT32 HT32.NHT32	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20single (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2022.7-	T33.SNT33	※1 LED	※1 LED or T20 2ケ (P621 ×1)	※1 LED or T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 ASSY (交換不可)	※1 Not applicable due to LED lamp ※2 Cannot be replaced due to light assembly
NV200 Vanette	2009.5-	M20	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 1ケ (P625 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
e-NVvan	2014.6-	VME0	※1 LED	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 LED	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
e-NV wagon	2014.6-	ME0	※1 LED	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 LED	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
NV350 character van ※Continue to next page	2012.6-2017.6	E26	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
			※1 LED	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
NV350 character van	2017.7-	E26	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
elgrand	1997.5-2000.7	E50	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2000.8-2002.4	E50	Integrated with cornering (No applicable products)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2002.5-2010.7	E51	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2010.8-2013.12	E52	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2014.1-		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp, HID headlight vehicle, T10 2 piece specification. In that case, P145/P141 is recommended. ※2 Not applicable due to LED lamp
aura	FE13.FSNE13	2021.6-	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	T10 2ケ (P145 ×1) (P141 ×1)	※1 LED headlight vehicle Not applicable due to LED lamp
Otti	2005.6-2006.9	H91W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double 2ケ (P615＋P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※ Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − ※2 It comes in 2 pieces, but only 1 piece is used.
	2006.10-	H92W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
kicks	2008.10-2012.6	H59A	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 S25 double 2ケ (P616＋P613 1 each)	S25 2ケ (P625 ×2)	※2 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side –e ※2 Not applicable due to light distribution issues
	2020.7-	P15	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	T10 2ケ (P145 ×1) (P141 ×1)	
caravan Homie	1986.9-1997.4	E24	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	G18 (No applicable products)	※1Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1997.5-2001.4		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	G18 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
caravan	2001.5-2005.11	E25	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
	2005.12-2012.5	E25	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 2ケ (P622 ×1)	T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 2ケ (P622 ×1)	T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 2ケ (P622 ×1)	T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
cube	1998.2-2002.9	Z10	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 (適応品なし)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2002.10-2005.4	Z11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2005.5-2006.12	Z11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2007.1-2008.10		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2008.11-2020.3	Z12	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
cube cubic	2002.10-2005.4	Z11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2005.5-2006.12		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2007.1-2008.10		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
clipper van	2003.10-	U71V U72V	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T16 (No applicable products)	T20single (No applicable products)	T16 2ケ (P623 ×2)	※1 T10 (No applicable products)	※1 Not applicable due to light distribution issues
clipper rio	2007.6-2011.11	U71W U72W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T16 (No applicable products)	T20single (No applicable products)	T16 2ケ (P623 ×2)	※1 T10 (No applicable products)	※1 Not applicable due to light distribution issues
crew	1993.7-2002.6	K30	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	G18 (No applicable products)	※1Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
Gloria	1991.6-1993.5	Y32	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	1993.6-1995.5		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	1995.6-1999.5	Y33	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	T20single (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
	1999.6-2004.10	Y34	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
sunny	1994.1-1998.9	B14	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
sunny	1998.10-2004.10	B15	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※1 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
Luchino (coupe)	1994.5-1999.4	B14	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
Luchino (hatch back)	1995.1-1999.9	N15	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
Luchino S-RV	1996.5-2000.8	N15	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
safari ※Continue to next page	1997.10-H114.10	Y61	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2002.11-2004.7		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
safari	2004.8-2007.6		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
Sakura	2022.5-	B6AW	※LED	※LED	※LED	※LED	※LED	※LED	※室外は全てLEDの為Not applicable
CIMA	1991.8-1996.5	Y32	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not if the child is not +, –, +, – applicable *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	1996.6-2000.12	Y33	Integrated with cornering (No applicable products)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not if the child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2001.1-2010.7	F50	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not if the child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2003.10-2006.1		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not if the child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2006.2-2010.8	F50	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2012.5-	HGY51	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
juke	2010.6-2014.6	F15	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 (No applicable products)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
	2014.7-2020.6	F15	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
silvia	1988.5-1993.9	S13	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	G18 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1993.10-1998.12	S14	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	1999.1-2002.11	S15	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
skyline ※Continue to next page	1993.8-1995.12 4door		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
skyline ※Continue to next page	2door	R33	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	1996.1-1998.4 4door		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
	2door		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T16 (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1998.5-2000.7 4door	R34	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2door		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
	2000.8-2002.8 4door	R34	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
skyline	2000.8-2002.8 2door	R34	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
	2001.6-2006.10 SEDAN	V35	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2003.1-2005.10 coupe		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (適応品なし)	T20 (適応品なし)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2005.11-2007.9 coupe		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2006.11- SEDAN	V36	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2007.10- coupe		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2014.2-2017.11	V37	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	※1 LED	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2017.12-2019.8		※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
skyline crossover	2009.7-2016.6	J50	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 2ケ (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Skyline GT-R	1995.1-1998.12	R33	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T16 (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	※3 T10 (適応品なし)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Skyline GT-R	1999.1-2002.8	R34	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
	2000.10-2002.8		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 (No applicable products)	※1Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
GT-R	2007.12-2013.11	R35	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2013.12-2016.7		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Stagea Continue to next page	1996.10-1998.7	C34	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	1998.8-2001.9		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 parallel pin (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2001.10-2004.7	M35	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Stagea	2004.8-2007.6	M35	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
cedric	1991.6-1993.5	Y32	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	1993.6-1995.5		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	1995.6-1999.5	Y33	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	1999.6-2004.10	Y34	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
Cefiro ※Continue to next page	1994.8-1996.12	A32	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	S25 2ケ (P625 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Cefiro	1997.1-1998.1	A32	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
	1998.12-2003.3	A33	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
Cefiro Wagon	1997.6-2000.8	A32	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 (No applicable products)	※1Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
Serena ※Continue to next page	1991.6-1996.12	C23	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	S25 2ケ (P625 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1997.1-1997.12		Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
	1998.1-1999.5		Integrated with cornering (No applicable products)	T16 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Serena	1999.6-2001.11	C24	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	※1 T20 (No applicable products)	※2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※4 T10 (No applicable products)	※1 The high roof vehicle has two S25 specifications. P622 recommended ※2 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※4 Not applicable due to light distribution issues
	2001.12-2005.4		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
	2005.5-2010.11	C25	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
	2010.11-2013.11	C26 HC26.HFC26	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Hybrid cars have LED lamps Not
	2013.12-2016.7		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp Halogen lamp vehicles have two T10 units. the spot If so, P145/P141 is recommended. ※2 Not applicable due to LED lamp
	2016.8-2019.7	C27.HC27	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	T16 2ケ (P623 ×2)	ランプ一体 (No applicable products)	※1 Not applicable due to LED lamp Halogen lamp vehicles have two T10 units. the spot If so, P145/P141 is recommended.
	2019.8-2022.11	GC27.GFC27 HC27.HFC27	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	ランプ一体 (No applicable products)	※1 Not applicable due to LED lamp Halogen lamp vehicles have two T10 units. the spot If so, P145/P141 is recommended. ※2 Not applicable due to LED lamp
	2022.12-	C28	※LED	※LED	※LED	※LED	※LED	※LED	※Not applicable as all outdoor areas are LED.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
datsun pickup	1985.8-1996.12	D21	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1997.10-2002.8	D22	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
dayz	2013.6-2015.9	B21W	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2015.10-H31.3		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	H31.3-	B4#	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
dayz rooks	2014.2-2016.11	B21A	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (No applicable products)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Highway Star is equipped with LED lamps Not applicable for cars ※2 It comes in 2 pieces, but only 1 piece is used.
	2016.12-2020.2		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
Tiana	2003.2-2005.11	J31	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2005.12-2008.5		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2008.6-2014.1	J32	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Tiana	2014.2-2020.7	L32	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
TIDA	2004.10-2007.12	C11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 S25 double 2ケ (P616＋P613 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side –
	2008.1-2012.8		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 S25 double 2ケ (P616＋P613 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side –
TIDALatio	2004.10-	C11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 S25 double 2ケ (P616＋P613 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side –
Tino	1998.12-2003.5	V10	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T16 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 (No applicable products)	*1 Please check the polarity on the vehicle side. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
Dualis	2007.5-	J10	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
Terrano	1986.8-1995.8	WD21	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1995.9-2002.8	R50	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
terrano reglass	1996.8-2002.8	R50	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
notes	2005.1-2007.12	E11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T16 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2008.1-2012.8		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2012.9-2016.10	E12	※1 T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 (No applicable products)	※2 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 LED headlight car side light is Not applicable due to LED lamp ※2 Not applicable due to LED lamp
	2016.11-2020.11	E12.HE12	※1 T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 (No applicable products)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 LED headlight car side light is Not applicable due to LED lamp ※2 Not applicable due to LED lamp
	2020.12-	E13.SNE13	※1 T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 LED headlight car side light is Not applicable due to LED lamp ※2 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
Basara	1999.11-2003.6	U30	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
banette van	1999.6-	SK#	Integrated with cornering (No applicable products)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
pulsar	1995.1-2000.8	N15	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
Pulsar Serie (S-RV)	1996.5-2000.8	N15	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
pino	2007.1-2010.2	HC24S	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 S25 double 2ケ (P616＋P613 ×1)	T16 2ケ (P623 ×2)	※2 T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side ※2 It comes in 2 pieces, but only 1 piece is used.
fuga	2004.10-2009.10	Y50	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2009.11-2015.1	Y51	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Vehicles equipped with HID use LED lamps.Not ※2 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2015.2-		※1 LED	※1 LED	T20 (No applicable products)	※1 LED	※1 LED	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Fairlady Z	1989.7-1998.9	Z32	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1998.10-2000.8		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	2002.7-2005.7	Z33	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2005.8-2008.11		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2008.12-2022.6	Z34	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2022.7-	RZ34	※LED	※LED	※LED	※LED	※LED	※LED	※Not applicable as all outdoor areas are LED.
Primera	1990.2-1995.8	P10	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2.3 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	1995.9-1998.8	P11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T16 (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Primera	1998.9-2000.12	P11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
Primera	2001.1-2005.12	P12	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
Primera Camino	1995.9-1998.8	P11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T16 (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1998.9-2000.12		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
primera wagon	1997.9-2000.12	P11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2001.1-2005.12	P12	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
bluebird	1991.9-1995.12	U13	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
bluebird	1996.1-2001.9	U14	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	1997.9-2001.9	U14	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
bluebird sylphy	2000.8-2003.1	G10	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2003.2-2005.11		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2005.12-2009.4	G11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2009.5-2012.12		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
prairie liberty	1998.11-2001.4	M12	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN

Car model	model year	model	side light	blinker front	blinker rear	stop & tail	back	license	remarks
liberty	2001.5-2004.12	M12	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
Presage	1998.6-2001.8	U30	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 2ケ (P622 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
	2001.8-2003.6		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
	2003.7-2009.8	U31	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
president	1990.10-1998.11	G50	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1998.12-2003.9		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	2003.10-2010.8	F50	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Presea	1995.1-1997.7	R11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1997.8-2000.8		Integrated with cornering (No applicable products)	T20 (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, –, +, – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
march	1992.1-1997.4	K11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	G18 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1997.5-1999.10	K11	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	G18 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1999.11-2002.2		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	G18 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	2002.3-2010.6	K12	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	※1 T20 (No applicable products)	S25 2ケ (P622 ×1)	※2 S25 double 2ケ (P616＋P613 ×1)	S25 2ケ (P625 ×2)	※3 T10 (No applicable products)	※1 Some have T20 amber specifications. In that case, P621 is recommended. ※2 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – ※3 Not applicable due to light distribution
	2010.7-2013.5	K13	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side – *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
march	2013.6-	K13	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
Murano	2004.9-2008.8	Z50	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	2008.9-2011.1	Z51	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2011.2-2015.4		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Moco	2002.4～2006.1	MG21S	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double 2ケ (P615+P613 ×1)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − ※2 It comes in 2 pieces, but only 1 piece is used.
	2006.2～2011.2	MG22S	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double 2ケ (P615+P613 ×1)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − ※2 It comes in 2 pieces, but only 1 piece is used.
	2011.2-2016.5	MG33S	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double 2ケ (P615+P613 ×1)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − ※2 It comes in 2 pieces, but only 1 piece is used.
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 HIDヘッドライト車は、LEDランプの為 Not applicable ※2 It comes in 2 pieces, but only 1 piece is used.
Racine	1994.12～1996.12	NB14	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Racine	1997.1-2000.8	NB14	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
Lafesta	2004.12～2012.12	B30	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
LaFesta Highway Star	2011.6～2018.3	CWE#WN	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
largo	1993.5～1996.9	W30	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
			Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning
	1996.10～1999.6	W30	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T16 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
leaf	2010.12-2012.10	ZE0	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2012.11-2017.9	AZE0	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2017.10-	ZE1	※1 T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 LED headlight car side light is Not applicable due to LED lamp ※2 Not applicable due to LED lamp
rooks	2009.12-2013.3	ML21S	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	S25 double (No applicable products)	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2020.3-	B4#	※1 T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 LED headlight car side light is Not applicable due to LED lamp ※2 Not applicable due to LED lamp
Renessa	1997.10～2001.6	N30	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
leopard	1996.3～1999.6	Y33	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T16 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
laurel ※Continue to next page	1993.1～1993.12	C34	Integrated with cornering (No applicable products)	T20 (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1994.1-1997.5		Integrated with cornering (No applicable products)	T16 (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specifie
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

NISSAN			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
laurel	1997.6～1999.7	C35	Integrated with cornering (No applicable products)	S25 2ケ (P622 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	HID headlamp car ※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
			Integrated with cornering (No applicable products)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	halogen headlamp car ※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
	1999.8～2003.1	C35	Integrated with cornering (No applicable products)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	Club S, 4-halogen headlamp vehicle ※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
			T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	medalist ※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)
180SX	1989.4～1996.7	S13	T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	G18 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613
	1996.8-1998.12		T10 2ケ (P144 ×1) (P145 ×1) (P141 ×1) (P142 ×1)	T16 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	S25 2ケ (P625 ×2)	G18 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop)

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
acti	1999.5-2018.6	H1993.6	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
acti track	1999.5-2009.11	HA6.7	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	*1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	2009.12-2021.4	HA8.9	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
accord	2008.12-2013.3	CU1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
accord hybrid	2013.6～2016.4	CR6	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2016.5～2020.1	CR7	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
	2020.2～	CV3	※1 LED	※1 LED	S25 2ケ (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
accord tourer	2008.12-	CW1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 (No applicable products)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
insight	1999.11-2006.6	ZE1	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2009.2-	ZE2.3	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2018.12-	ZE4	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
inspire	2003.6-2005.10	UC1	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2005.11-2007.11		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2007.12-	CP3	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Integra	1993.5-2001.6	DB6.7.8.9 DC1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※2.3 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T13 (No applicable products)	※1 Some have S25 amber specifications. In that case, P622 is recommended. ※2 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2001.7-2004.8	DC5	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	2004.9-2007.2	DC5	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
Integra TYPE-R	1993.5-2001.6	DB6.7.8.9 DC1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※2.3 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T13 (No applicable products)	※1 Some have S25 amber specifications. In that case, P622 is recommended. ※2 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2001.7-2004.8	DC5	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Integra TYPE-R	2004.9-2007.2	DC5	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
vezel	2014.12-2018.1	RU1.2.3.4	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1 Not applicable due to LED lamp halogen headlamp car has 2 T10 specification. In that case, P145/P141 is recommended. ※2 Not applicable due to LED lamp
	2018.2-2021.4		※1 LED	※2 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp ※2 Not applicable due to LED lamp halogen headlamp car is T20 amber specification. In that case, P621 is recommended.
	2021.4-	RV3.4.5.6	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
S2000	1999.4-2009.9	AP1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	2003.10-2009.9	AP1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1 LED	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
S600	2015.3-2019.12	JW5	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2020.1-2021.12		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	α、moduloX ※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Edix	2004.7-2009.8	BE1.2.3.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20single (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
NSX	1990.9-2005.12	NA1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 (No applicable products)	※1.2.3 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T13 (No applicable products)	※1 Some have S25 parallel pin specifications. No applicable products ※2 *1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side - *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2017.2-	NC1	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
N BOX	2011.12-2013.11	JF1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2013.12-2017.7		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2017.8-2023.9	JF3.4	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2023.10-	JF5.6	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※2 LED or T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.標準LED車の場合No applicable products。
N BOX custom	2011.12-2013.11	JF1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2013.12-2017.7		※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Turbo cars are not applicable due to LED lamp ※2 Not applicable due to LED lamp ※3 It comes in 2 pieces, but only 1 piece is used.
			※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Turbo cars are not applicable due to LED lamp ※2 Not applicable due to LED lamp ※3 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
N BOX custom	2017.8-2023.9	JF3.4	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1It comes in 2 pieces, but only 1 piece is used.
	2023.10-	JF5.6	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※2 LED or T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.標準LED車の場合No applicable products。
N-BOX SLASH	2014.12-2020.2	JF1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
N-BOX +	2012.7-2013.11	JF1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2013.12-2018.3		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
N-BOX + custom	2012.7-2013.11	JF1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2013.12-2018.3	JF1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
N-VAN	2018.7-	JJ1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
			※1 LED	T20 (No applicable products)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
N-WGN	2013.11-2019.7	J1989.2	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 HID headlamp cars are not applicable due to LED lamp ※2 Not applicable due to LED lamp ※3 It comes in 2 pieces, but only 1 piece is used.
	2019.8-	J1991.4	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※3 T10 2ケ (P145 ×1) (P141 ×1)	※1 led headlamp carは、Not applicable due to LED lamp ※2 Not applicable due to LED lamp ※3 It comes in 2 pieces, but only 1 piece is used.
N-WGN custom	2013.11-2019.7	J1989.2	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2019.8-	J1991.4	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
N-ONE	2012.11-2020.10	JG1.2	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2014.4-2020.10		※1 LED	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2020.11-	JG3.4	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
			※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
Elysium	2004.5-2012.5	R2019.2.3.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Elysion Prestige	2007.1-2013.10	R2019.2.5.6	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
odyssey	2003.10-2006.3	RB1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※2.3 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※4 T10 (No applicable products)	※1 Vehicles equipped with AFS are T20 amber specification. In that case, P621 is recommended. ※2 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※4 Not applicable due to light distribution issues
	2006.4-2008.9		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※2 LED	T20 2ケ (P624 ×2)	※3 T10 (No applicable products)	※1Vehicles equipped with AFS are T20 amber specification. In that case, P621 is recommended. ※2 Not applicable due to LED lamp ※3 Not applicable due to light distribution issues
	2008.9-2013.10	RB3.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 一部、LED lamp specifications available。In that case, Not applicable
	2013.11-2020.10	RC1.2.4	※1 LED	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
			※1 LED	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
	2020.11-2022.9		※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
	2023.12-	RC5	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
That's	2002.2-	JD1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
clarity	2016.3-2018.6	ZC4	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
clarityPHEV	2018.7-	ZC5	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
grace	2014.12-2017.6	GM4.5.6.7	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2.3 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	※1 T10 2ケ (P145 ×1) (P141 ×1)	※1 For hybrid cars, Not applicable due to LED lamp ※2 Check the vehicle side polarity. socket end Not applicable if the child is not + or side − *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2017.7-2020.7		※1 LED	T20 2ケ (P621 ×1)	※2 T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp ※2 Gasoline cars are T20single, so not applicable.
CR-V	1995.10-2001.8	RD1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	2001.9-2004.8	RD4.5	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
CR-V	2004.9-2006.9	RD6.7	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	2006.10-2011.12	RE3.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	2011.12-2016.8	RM1.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2018.9-2020.5	RT5.6 RW1.2	※1 LED	※1 LED	※1 LED	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
	2020.6-		※1 LED	※1 LED	※1 LED	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
CR-Z	2010.2-2012.8	ZF1	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
	2012.9-2015.9	ZF2	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
CR-Z	2015.10-2017.1	ZF2	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
shuttle	2015.5-H31.4	GK8.9	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1 led headlamp carは、Not applicable due to LED lamp ※2 For LED lamps. Not
	2019.5-		※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1led headlamp carは、Not applicable due to LED lamp ※2 For LED lamps. Not
shuttle hybrid	2015.5-H31.4	GP7.8	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1led headlamp carは、Not applicable due to LED lamp ※2 For LED lamps. Not
	2019.5-		※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1led headlamp carは、Not applicable due to LED lamp ※2 For LED lamps. Not
jade	2015.2-2018.4	F2022.5	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 For LED lamps. Not
	2018.5-		※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1 For high beam LED cars, For LED lamps. ※2 Not applicable due to LED lamp
civic	2005.9-2010.12	FD1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
civic hybrid	2005.9-2010.12	FD3	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
civic SEDAN	2017.7-2019.12	FC1	※1 LED	※1 LED	T20 2ケ (P621 ×1)	T20single (No applicable products)	T16 2ケ (P623 ×2)	※1 LED	※1 For LED lamps. Not

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
civic SEDAN	2020.1-2021.9	FC1	※1 LED	※1 LED	T20 2ケ (P621 ×1)	T20single (No applicable products)	T16 2ケ (P623 ×2)	※1 LED	※1 For LED lamps. Not
civic hatchback	2017.7-2019.12	FK7	※1 LED	※1 LED	T20 2ケ (P621 ×1)	T20single (No applicable products)	T16 2ケ (P623 ×2)	※1 LED	※1 For LED lamps. Not
	2020.1-2021.9		※1 LED	※1 LED	T20 2ケ (P621 ×1)	T20single (No applicable products)	T16 2ケ (P623 ×2)	※1 LED	※1 For LED lamps. Not
civic TYPE-R	2007.3-2010.12	FD2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2015.10-2016.6	FK2	※1 LED	S25 2ケ (P622 ×1)	T16 (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 For LED lamps. Not
	2017.7-	FK8	※1 LED	※1 LED	T20 2ケ (P621 ×1)	T20single (No applicable products)	T16 2ケ (P623 ×2)	※1 LED	※1 For LED lamps. Not
civic TYPE-R EUR	2009.11-2012.6	FN2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
step wagon ※Continue to next page	1996.5-1999.4	RF1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T16 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T16 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
step wagon	1999.5-2001.3		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 (No applicable products)	T16 (No applicable products)	※2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※4 T10 2ケ (No applicable products)	※1 Some have T20 amber specifications. In that case, P621 is recommended. ※2 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※4 Not applicable due to light distribution issues
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 (No applicable products)	T16 (No applicable products)	※2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※4 T10 2ケ (No applicable products)	※1 Some have T20 amber specifications. In that case, P621 is recommended. ※2 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※4 Not applicable due to light distribution issues
	2001.4-2005.4	RF3.4.5.6.7.8	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2005.5-2009.9	RG1.2.3.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	※3 T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Some models have T16 2-piece specifications. In that case, P623 is
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	※3 T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Some models have T16 2-piece specifications. In that case, P623 is

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
step wagon	2009.10-2015.3	RK1.2.5.6	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 HIDヘッドランプ車は、Not applicable due to LED lamp ※2 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2015.4-2017.8	RP1.2.3.4	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 SPADA、led headlamp carは、Not applicable due to LED lamp ※2 For LED lamps. Not
	2017.9-2022.4		※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T20 2ケ (P624 ×2)	※2 LED	※1 SPADA、SPADA HYBRUD、led headlamp carは、Not applicable due to LED lamp ※2 For LED lamps. Not
			※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T20 2ケ (P624 ×2)	※2 LED	※1 SPADA、SPADA HYBRUD、led headlamp carは、Not applicable due to LED lamp ※2 For LED lamps. Not
	2020.1-2022.4	RP5	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T20 2ケ (P624 ×2)	※2 LED	※1 SPADA、SPADA HYBRUD、led headlamp carは、Not applicable due to LED lamp ※2 For LED lamps. Not
	2022.5-	RP6.7.8	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 For LED lamps. Not
stream	2000.10-2006.6	RN1.2.3.4.5	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 (No applicable products)	T20 (No applicable products)	T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some T20 amber specifications are available. In that case, P621 is recommended.
	2006.7-2014.5	RN6.7.8.9	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
zest	2006.3-2012.11	JE1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
zest spark	2008.12-2012..	JE1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
ZR-V	2022.4-	RZ3.4.5.6	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
Vamos	1999.6-2018.5	HM1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 (No applicable products)	※1 T16 (No applicable products)	※2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※4 T10 1ケ (P145 ×1) (P141 ×1)	※1 Some T20 amber specifications are available. In that case, P621 is recommended. ※2 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※4 It comes in 2 pieces, but only 1 piece is used.
Vamoshobio	2003.4-2018.5	HM3.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
beat	1991.5-1995.10	PP1	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T13 (No applicable products)	※1 *1 Please check the polarity on the vehicle side. socket end Not applicable if the child is not + or side − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
fit ※Continue to next page	2001.6-2007.9	GD1.2.3.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2.3 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※1 LED	※1 Some LED lamp specifications are available. Not applicable ※2 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
fit	2007.10-2013.8	GE6.7.8.9	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double 2ケ (P615 ×1)	※2 T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some LED lamp specifications are available.Not applicable ※2 Some T16 2-piece specifications are available. In that case, P623 is recommended.
	2013.9-2017.5	GK3.4.5.6	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1led headlamp carは、Not applicable due to LED lamp ※2 Not applicable due to LED lamp
	2017.6-2020.1	GK3.4.5.6	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	※3 T16 2ケ (P623 ×2)	※2 LED	※1led headlamp carは、Not applicable due to LED lamp ※2 Not applicable due to LED lamp ※3 ome models have 2 T20 specifications. In that case, P624 is recommended.
	2020.2-	G2019.2.5.7	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1 led headlamp carは、Not applicable due to LED lamp ※2 For LED lamps. Not
			※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1 led headlamp carは、Not applicable due to LED lamp ※2 For LED lamps. Not
fit aria	2002.12-2009.1	GD6.7.8.9	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
fit hybrid	2010.10-2013.8	GP1	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2013.9-2020.1	GP5.6	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	※3 T16 2ケ (P623 ×2)	※2 LED	※1 led headlamp car led lamp Therefore, Not applicable ※2 Not applicable due to LED lamp ※3 ome models have 2 T20 specifications. In that case, P624 is recommended.
	2020.2-	G2021.4.6.8	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1 led headlamp car led lamp Therefore, Not applicable ※2 Not applicable due to LED lamp
			※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1 led headlamp car led lamp Therefore, Not applicable ※2 Not applicable due to LED lamp
fit shuttle	2011.6-	GG7.8	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
fit shuttle hybrid	2011.6-	GP2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
freed	2008.5-2014.3	GB3.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (No applicable products)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Some LED lamp specifications available. Not ※2 It comes in 2 pieces, but only 1 piece is used.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (No applicable products)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Some LED lamp specifications available. Not ※2 It comes in 2 pieces, but only 1 piece is used.
	2014.4-2016.8		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2016.9-	GB5.6	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 led headlamp car led lamp Therefore, Not applicable ※2 Not applicable due to LED lamp
freed hybrid	2011.10-2014.3	GP3	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (No applicable products)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 led headlamp car led lamp Therefore, Not applicable ※2 It comes in 2 pieces, but only 1 piece is used.
	2014.4-2016.8		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2016.9-	GB7.8	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 led headlamp car led lamp Therefore, Not applicable
freed spike	2010.7-2014.3	GB3.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	Car with sunroof
	2014.4-2016.8		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
freed spike hybrid	2011.10-2014.3	GP3	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2014.4-2016.8	GP3	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
freed+	2016.9-	GB5.6	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1led headlamp car led lamp Therefore, Not applicable ※2 Not applicable due to LED lamp
freed+ hybrid	2016.9-	GB7.8	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 led headlamp car led lamp Therefore, Not applicable ※2 Not applicable due to LED lamp
Mobilio	2001.12-2003.12	GB1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2004.1-2008.4	GB1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
mobilio spike	2002.9-2005.11	GK1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	2005.12-2008.4		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
life	1997.4-1998.9	JA4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	1998.10-2001.4	JB1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	2001.5-2004.9		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	2004.10-2006.9	JB5.6.7.8	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2006.10-2008.10	JB5.6.7.8	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2008.11-	JC1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

HONDA			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
lifeDIVA	2003.9-2008.10	JB5.6.7.8	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2008.11-2010.10	JC1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	2010.11-2014.4	JC1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
life pastel	2008.11-2010.11	JC1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
legend	2004.10-2008.8	KB1	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2008.9-2014.10	KB2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2014.11-2018.1	KC2	※1 LED or T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※2 LED	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 LED	※1 For LED lamps, No applicable products. ※2 Not applicable due to LED lamp
	2018.2-		※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
i	2006.1-2013.9	HA1W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	T20 double (No applicable products)	T20 (No applicable products)	T10 (No applicable products)	
i-MiEV	2009.7-2018.3	HA3W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
	2018.4-	HD4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
RVR	1991.2-1997.10	N1# N2#	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	1997.11-2002.8	N6# N7#	BA9s (No applicable products)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2010.2-	GA3W.GA4W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1 LED	T20 (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
RVRsports Gear	1997.11-2002.8	N6# N7#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 (No applicable products)	T20 (No applicable products)	※2.3 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some S25 parallel pin specifications available. Not applicable ※2 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
Outlander	2005.10-2012.9	CW4W.5W.6W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 LED	T20 (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
	2012.10-2015.5	GF7W.8W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	S25 double (適用員なし)	T20 (No applicable products)	T10 (No applicable products)	
	2015.6-2020.12		※1 LED	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 LED	T16 2ケ (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
OutlanderPHEV	GG2W	2012.12-2015.6	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 LED	T20 (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
		2015.7-2018.7	※1 LED	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
	GG3W	2018.8-2021.11	※1 LED	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
	GN0W	2021.12-	※1 LED	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
eKactive	2004.5-2006.9	H81W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
ekcustom	2013.8-H31.2	B11W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T16 2ケ (No applicable products)	T10 (No applicable products)	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
eKClassy	2003.5-2005.12	H81W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
ekcross	H31.3-	B34W.35W 37W.38W	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
ekCross Space	2020.3-	B34A.35A 37A.38A	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
ekspace (custom)	2014.2-2020.2	B11A	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T16 2ケ (No applicable products)	T10 (No applicable products)	※1 Some LED lamp specifications are available. Not applicable due to LED lamp
	2020.3-	B34A.35A 37A.38A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
eksports	2002.9-2006.8	H81W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	2006.9-2013.5	H82W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
eKwagon	2001.10-2006.8	H81W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
eKwagon	2006.9-2013.6	H82W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
	2013.7-H31.2	B11W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T16 2ケ (No applicable products)	T10 (No applicable products)	
	H31.3-	B33W.36W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (No applicable products)	T10 (No applicable products)	※1 Not applicable due to LED lamp
Airtrek	2001.6-2005.10	CU#W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Airtrek sports gear	2003.1-2005.10	CU4W CU5W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Eclipse	1989.9-1995.5	D22A D27A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	1995.6-2000.9	D32A	BA9s (No applicable products)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
Eclipse Spider	2004.10-2006.4	D53A	ウィンカートと一体 (No applicable products)	S25 2ケ (P622 ×1)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece is used.
Eclipse Cross Including PHEV	2018.3-	GK1W.GL3W	※1 LED	※1 S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (No applicable products)	T10 (No applicable products)	※1 Some LED lamp specifications are available. Not applicable due to LED lamp
FTO	1994.10-2000.9	DE2A DE3A	T13 (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
Galant	1996.8-2005.11	EA# EC#	BA9s (No applicable products)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Galant Fortis	2007.8-2015.3	CY4A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	T20 double (No applicable products)	T20 (No applicable products)	T10 (No applicable products)	
Galant Fortis sportsback	2008.12-2015.3	CX4A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T20 (No applicable products)	T10 (No applicable products)	
Colt	2002.11-2012.10	Z2#A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	T20 (No applicable products)	T20 (No applicable products)	T10 (No applicable products)	
Colt Ralliart Version R	2006.5-2012.10	Z27AG	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	T20 (No applicable products)	T20 (No applicable products)	T10 (No applicable products)	
Colt Plus	2004.10-2012.10	Z2#W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T16 (No applicable products)	T20 (No applicable products)	T20 (No applicable products)	T10 (No applicable products)	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
Colt Plus	1990.10-2000.9	Z15A Z16A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	1993.6-2001.8		ウィンカーと一体 (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
Chariot Grandis	1997.10-2003.4	N8#.9#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
			Integrated with cornering (No applicable products)	T20 double (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Grandis	2003.5-2009.3	NA4W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Grandis Sports Gear	2005.6-2009.3	NA4W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Town Box	1999.4-2011.11	U6#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	※1 T16 (No applicable products)	T20 (No applicable products)	T16 2ケ (P623 ×2)	※2 T10 (No applicable products)	※1 Some are available in T20 amber. In that case, P621 is recommended. ※2 Not applicable due to light distribution issues
	2014.2-2015.3	DS64W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 T20 double 2ケ (P615＋P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※ Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. ※2 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
Town Box	2015.3-	DS17W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Town Box Wide	1999.6-2001.6	U6#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	※1 T16 (No applicable products)	T20 (No applicable products)	T16 2ケ (P623 ×2)	※2 T10 (No applicable products)	※1 Some are available in T20 amber. In that case, P621 is recommended. ※2 Not applicable due to light distribution issues
Diamante	1995.1-2005.12	F3#.4#	BA9s (No applicable products)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P187 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Diamante Wagon	1997.10-2001.10	F36W	BA9s (No applicable products)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P187 ×1) (P141 ×1)	※1Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Dion	2000.1-2006.3	CR#W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Delica Star Wagon	1990.8-1999.10	L03#.06# P01#.02#.03#.04 #	ウィンカートと一体 (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	G18 (No applicable products)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Delica van	1999.11-2011.9	SK#	Integrated with cornering (No applicable products)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2011.10-2019.4	BVM20	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
Delica Space Gear	1994.5-2004.9	P##W	ウィンカートと一体 (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	G18 (No applicable products)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2004.10-2005.10		ウィンカートと一体 (No applicable products)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	G18 (No applicable products)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2005.11-2006.12	P##W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	G18 (No applicable products)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
DelicaD:2	2011.3-2015.11	MA15S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 T20 double 2ケ (P615＋P613 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable.
	2015.12-2020.11	MB36S	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some LED lamp specifications are available. Not applicable due to LED lamp ※2 Not applicable due to LED lamp
	2020.12-	MB37S	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some LED lamp specifications are available. Not applicable due to LED lamp ※2 Not applicable due to LED lamp
DelicaD:3	2011.10-2019.4	BM20	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
DelicaD:5	2007.1-	CV#W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T20 (No applicable products)	T10 (No applicable products)	
	H31.2-	CV5W.2W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T20 (No applicable products)	T10 (No applicable products)	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
DelicaD:5	H31.2-	CV1W	※1 LED	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	T20 (No applicable products)	T20 (No applicable products)	T10 (No applicable products)	
Triton	2006.9-2011.8	KB9T	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T16 (No applicable products)	S25 double (No applicable products)	T16 (No applicable products)	T13 (No applicable products)	
Pajero	1999.9-2006.9	V6#.7#W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 (No applicable products)	※1 T20 (No applicable products)	※2.3 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※4 T10 (No applicable products)	※1 Some are available in T20 amber. In that case, P621 is recommended. ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※4 Not applicable due to light distribution issues
	2006.10-2019.8	V8#.9#W	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T20 (No applicable products)	T10 (No applicable products)	※1 Some LED lamp specifications available. Not
PajeroJr.	1995.11-1998.6	H57A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
Pajero IO	1998.6-2007.8	H6#.7#W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※2.3 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some are available in S25 amber. In that case, P622 is recommended. ※2 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
pajero mini	1994.12-1998.9	H51A.56A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
pajero mini	1998.10-2002.8	H53A.58A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2002.9-2005.11		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2005.12-2008.8		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2008.9-2013.8		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Dignity	2012.7-2016.12	BHGY51	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Minica	1998.10-2011.7	H4#A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※2.3 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some are available in S25 amber. In that case, P622 is recommended. ※2 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
Minica Town B	1998.10-2003.9	H4#A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
Toppo BJ	2001.2-2003.7	H4#A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	※3 T10 (No applicable products)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
Toppo	2008.9-2013.9	H82A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	T20 2ケ (P624 ×2)	※3 T10 (No applicable products)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 Not applicable due to light distribution
Minicab van	1999.1-2015.2	U6#V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	S25 (No applicable products)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Some S25 parallel pin specifications. Not applicable ※2 It comes in 2 pieces, but only 1 piece is used.
	2011.12-2015.2		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 S25 double 2ケ (P616＋P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. ※2 It comes in 2 pieces, but only 1 piece is used.
	2015.3-	DS17V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1 T20 double 2ケ (P615＋P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※ Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. ※2 It comes in 2 pieces, but only 1 piece is used.
Minicab Truck	1999.1-2014.1	U6＃	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	※1 T16 (No applicable products)	※2 S25 double 2ケ (P616＋P613 1 each)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Some are available in T20 amber. In that case, P621 is recommended. ※2 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. ※3 It comes in 2 pieces, but only 1 piece is used.
	2014.2-	DS16T	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 (No applicable products)	※1 S25 double 2ケ (P616＋P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. ※2 It comes in 2 pieces, but only 1 piece is used.
Mirage	2012.8-	A05A.03A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 parallel pin (No applicable products)	S25 double (No applicable products)	S25 (No applicable products)	T10 (No applicable products)	
			※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※2 LED	T16 (No applicable products)	T10 (No applicable products)	※1 Some LED lamp specifications available. Not

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
Lancer	2003.2-2010.5	CS#A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T16 (No applicable products)	T10 (No applicable products)	
Lancer Cargo	2003.1-2008.11	CS2V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2008.12-2017.1		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2017.1-	Y12	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Lancer Cedia	2000.5-2003.1	CS#A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Lancer Cedia Wagon	2000.11-2003.1	CS5W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Lancer Evolution	1998.1- EVO.Ⅴ	CP9A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

★The manufacturer does not recommend installing LEDs on high model year Mitsubishi vehicles as problems have occurred when these are installed.

MITSUBISHI			side light	blinker		ストップ&テール	back	license	remarks
Car model	model year	model		front	rear				
Lancer Evolution	1999.1- EVO.Ⅵ	CP9A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2001.2- EVO.Ⅶ	CT9A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 (No applicable products)	T20 2ケ (P621 ×1)	※2.3 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some are available in T20 amber. In that case, P621 is recommended. ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2003.1- EVO.Ⅷ		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	T20 (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
	2005.3- EVO.Ⅸ		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	T20 (No applicable products)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2007.10- EVO.Ⅹ	CZ4A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 (No applicable products)	T20 double (No applicable products)	T20 (No applicable products)	T10 (No applicable products)	
Lancer Evolution WAGON	2005.9-2007.8	CT9A	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Lancer Wagon	2003.2-2010.5	CS5W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
RX-7	1991.12-1997.9	FD3S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	1997.10-2003.4		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 parallel pin (No applicable products)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
RX-8	2003.4-2008.2	SE3P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	2008.3-2013.4		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
Axela ※Continue to next page	2003.10-2009.5	BK#P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
Axela	2009.6-2013.10	BL#FP BLEAP	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2.3 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some are available with LED specifications. Not applicable due to LED lamp ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2.3 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some are available with LED specifications. Not applicable due to LED lamp ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2013.11-H31.4	BM	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2) T20	T10 2ケ (P145 ×1) (P141 ×1)	※1 HID、led headlamp carは、LED仕様。Not applicable due to LED lamp ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
Axela hybrid	2013.11-2019.5	BYEFP	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 HID、led headlamp carは、LED仕様。Not applicable due to LED lamp ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
Axela sports	2003.10-2009.5	BK#P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece is used.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Axela sports	2009.6-2013.10	BL#FW BLEAW	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2.3 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some are available with LED specifications. Not applicable due to LED lamp ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2013.11-2018.4	BM	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2.3 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 HID, led headlamp car, LED specification. Not applicable due to LED lamp ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
Mazdaspeed Axela ※Continue to next page	2003.10-2009.5	BK3P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Mazdaspeed Axela	2009.6-2012.6	BL3FW	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Atenza SEDAN	2002.5-2007.12	GG#P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
Atenza SEDAN	2008.1-2012.10	GH#FP GH5AP	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2012.11-2018.5	GJ	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 HID headlamp vehicles are LED Not applicable due to LED lamp ※2 Not applicable due to LED lamp
	2018.6-2019.7		※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
Atenza sports	2002.5-2007.12	GG#P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2008.1-2012.10	GH#FP GH5AP	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
Atenza sports wagon ※Continue to next page	2002.6-2007.12	GY#W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2008.1-2012.11	GH#FW GH5AW	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2012.11-2018.5	GJ	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 HID headlamp vehicles are LED Not applicable due to LED lamp ※2 Not applicable due to LED lamp
Atenza sports wagon	2018.6-2019.7	GJ	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	※1 LED	※1 Not applicable due to LED lamp
AZ-Wagon	2003.10-2008.8	MJ21S.22S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Some S25 parallel pin specifications available.No applicable products ※2 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
AZ-Wagon	2008.9-2012.10	MJ23S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	S25 double (No applicable products)	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
AZ-Wagon customstyle	2007.2-2008.8	MJ22S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	S25 double (No applicable products)	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2008.9-2012.10	MJ23S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	S25 double (No applicable products)	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
AZ-Wagon RR	2003.10-2008.8	MJ21S.22S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
AZ-Offroad	1998.10-2004.9	JM23W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double 2ケ (P615＋P613 ×1)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. ※2 It comes in 2 pieces, but only 1 piece is used.
	H116.10-2014.3		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double 2ケ (P615＋P613 ×1)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. ※2 It comes in 2 pieces, but only 1 piece is used.
MPV	1999.6-2006.1	LW#W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※4 T10 (No applicable products)	※1 Some S25 parallel pin specifications available.No applicable products ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※4 Not applicable due to light distribution issues
	2006.2-2016.3	LY3P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
MX-30	2020.10-	DREJ3P	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
MX-30 EV	2021.1-	DRH3P	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
Carol	2004.9-2006.11	HB24S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	S25 double 2ケ (P616＋P613 ×1)	S25 2ケ (P625 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2006.12-2009.11		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	S25 double 2ケ (P616＋P613 ×1)	S25 2ケ (P625 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2009.12-2014.12	HB25S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	S25 double 2ケ (P616＋P613 ×1)	S25 2ケ (P625 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2015.1-2021.11	HB36S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	T20 double 2ケ (P615＋P613 ×1)	T20 2ケ (P624 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2021.12-	HB37S HB97S	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double 2ケ (P615＋P613 ×1)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 led headlamp carは、LED使用。Not applicable ※2 It comes in 2 pieces, but only 1 piece is used.
CX-8	2017.12-	KG2P	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 2ケ (P145 ×1) (P141 ×1)	※1 LED lamp specifications available。Not applicable due to LED lamp ※2 2018.11以降の車両は、Not applicable due to LED lamp
			※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 2ケ (P145 ×1) (P141 ×1)	Vehicles with LED interior ※1 LED lamp specifications available。Not applicable due to LED lamp ※2 Vehicles after November 2018: Not applicable due to LED lamp
CX-7	2006.12-2009.8	ER3P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2009.9-2011.12	ER3P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
CX-5	2012.2-2014.12	KEE#W.KE2#W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
CX-5	2015.1-2017.1	KEE#W.KE2#W	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2017.2-	KF	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	※1 LED	※2 T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 2Vehicles after 2020.1: Not applicable due to LED lamp
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	※1 LED	※2 T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Vehicles after 2020.1: Not applicable due to LED lamp
CX-3	2015.2-	DK	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
			※1 LED	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	※2 T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	led headlamp car ※1 Not applicable due to LED lamp ※2 LED specifications available. Not applicable due to LED lamp
CX-30	2019.10-	DMEP DMFP DM8P	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
Scrum Track	1999.1-2005.8	DG5#T DG6#T	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 parallel pin (No applicable products)	S25 double 2ケ (P616＋P613 ×1)	T13 (No applicable products)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2005.8-2013.8	DG63T	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T16 (No applicable products)	S25 double 2ケ (P616＋P613 ×1)	T16 1ケ (P623 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2013.9-	DG16T	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T16 (No applicable products)	S25 double 2ケ (P616＋P613 ×1)	T16 1ケ (P623 ×1)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
Scrum van	1999.1-2005.8	DG5#V DG6#V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T16 (No applicable products)	S25 double 2ケ (P616＋P613 ×1)	S25 2ケ (P625 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2005.9-2015.2	DG64V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	T20 double 2ケ (P615＋P613 ×1)	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
Scrum van	2015.3-	DG17V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	T20 double 2ケ (P615＋P613 ×1)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 For vehicles with HID headlamps, S25 amber specification. In that case, P622 is recommended. ※2 It comes in 2 pieces, but only 1 piece is used.
Scrum Wagon	1999.1-2005.8	DG5#W DG6#W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	※1 S25 2ケ (P622 ×1)	S25 double 2ケ (P616＋P613 ×1)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Some are S25 parallel pin specifications. No applicable products ※2 It comes in 2 pieces, but only 1 piece is used.
	2005.9-2015.2	DG64W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	S25 double 2ケ (P616＋P613 ×1)	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2015.3-	DG17W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 For vehicles with HID headlamps, S25 amber specification. In that case, P622 is recommended. ※2 Not applicable due to LED lamp ※3 It comes in 2 pieces, but only 1 piece is used.
Spiano	2002.2-2004.2	HF21S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	T20 double 2ケ (P615＋P613 ×1)	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2004.3-2006.3		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	T20 double 2ケ (P615＋P613 ×1)	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
Spiano	2006.4-2008.11	HF21S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	T20 double 2ケ (P615＋P613 ×1)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 For vehicles with HID headlamps, S25 amber specification. In that case, P622 is recommended. ※2 It comes in 2 pieces, but only 1 piece is used.
Demio	1996.8-1999.11	DW3W DW5W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 S25 double 2ケ (P616 ×1)	S25 2ケ (P625 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminal is not + and the side is not −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece
	1999.12-2002.7		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※3 It comes in 2 pieces, but only 1 piece

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
Demio	2002.8 -2007.6	DY#W DY#R	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※2.3 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some are available in T20 amber. In that case, P621 is recommended. ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	※1 T20 (P621 ×1)	※2.3 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 一部Some are available in T20 amber. In that case, P621 is recommended. ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2007.7-2014.8	DE3#S DE5FS	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	※4 T10 1ケ (P145 ×1) (P141 ×1)	※1 LED lamp specifications available。 Not applicable due to LED lamp ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth. ※4 It comes in 2 pieces, but only 1 piece is used.
Demio	2014.9-2019.8	DJ3#S DJ5#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Demio Skyactive	2011.6-2014.8	DEJFS	※1 LED	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2014.9-2019.8	DJ3 DJ5	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 led headlamp carは、LED 仕様。Not applicable due to LED lamp ※2 Not applicable due to LED lamp
Biante	2008.7-2018.2	CCE#W CC3FW	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
Familia Van	1999.6-2002.8	Y11	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	S25 double 2ケ (P616＋P613 ×1)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2002.9-2006.12		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 1ケ (P623 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2007.1-2018.5	Y12	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	※1 T20 2ケ (P621 ×1)	※2.3 T20 double 2ケ (P615 ×1)	T16 1ケ (P623 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some are available in T20 specifications.Not applicable ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2018.6-	NCP160M NCP165M	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Flare	2012.10-2017.2	MJ34S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
Flare	2017.3-	MJ55S	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	※2 T10 2ケ (P145 ×1) (P141 ×1)	※1 LED lamp specifications available。Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
lair Crossover	2014.1-2020.2	MS31.41S	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 It comes in 2 pieces, but only 1 piece is used.
	2020.2-	MS52S MS92S	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 led headlamp carは、LED仕様。Not applicable due to LED lamp ※2 Not applicable due to LED lamp ※3 It comes in 2 pieces, but only 1 piece is used.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
Flair Wagon	2012.6-2013.3	MM21S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	S25 double 2ケ (P616＋P613 ×1)	T16 2ケ (P623 ×2)	※1 T10 1ケ (P145 ×1) (P141 ×1)	※1 It comes in 2 pieces, but only 1 piece is used.
	2013.4-2018.1	MM32S.42S	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Some are available with LED specifications. Not applicable due to LED lamp ※2 Not applicable due to LED lamp ※3 It comes in 2 pieces, but only 1 piece is used.
	2018.2-	MM53S	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※2 T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Some are available with LED specifications. Not applicable due to LED lamp ※2 Tough style is T20 specification. No applicable products ※3 It comes in 2 pieces, but only 1 piece is used.
Premacy	2005.2-2010.6	CR#W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2.3 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some LED lamp specifications are available. Not applicable due to LED lamp ※2 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *3 Symptoms such as an out-of-bulb warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to earth.
	2010.7-2018.2	CWE#W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Verisa	2004.6-2015.10	DC5#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Verisa	2006.8-2015.10	DC5#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Bongo Truck	2020.7-	S403F S413F	※1 LED	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1 LED	T16 1ケ (P623 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
Bongo van	1999.6-2020.8	SK#	Integrated with cornering (No applicable products)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2020.9-	S403Z S413Z	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Bongo Brawny Van	2018.4-	TRH200M GDH206M	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
Mazda 2	2019.9-	DJL#S,DJ5#S	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	※2 LED	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some are available with LED specifications. Not applicable due to LED lamp ※2 Not applicable due to LED lamp
			※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	※2 LED	T10 2ケ (P145 ×1) (P141 ×1)	※1 Some are available with LED specifications. Not applicable due to LED lamp ※2 Not applicable due to LED lamp
MAZDA 3 SEDAN	2019.5-	BP#P	※1 T20 double (No applicable products)	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 led headlamp carはLEDの為、Not applicable
Marda 3 Fastback	2019.5-	BP#P	※1 T20 double (No applicable products)	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

MAZDA			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
MAZDA 6 SEDAN	2019.8-	GJ#FP,GJ2#P	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
			※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
Mazda 6 Wagon	2019.8-	GJ#FW,GJ2#W	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	※1 LED	※1 Not applicable due to LED lamp
			※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	※1 LED	※1 Not applicable due to LED lamp
Roadster	1998.1-2000.6	NB6C NB8C	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2000.7-2005.7		※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2005.8-2015.4	NCEC	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20 double (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the polarity on the vehicle side. If the socket terminals are not +, −, +, −, then it is Not applicable. *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to
	2015.5-	ND5RC	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
Roadster RF	2017.2-	NDE	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
R1	2005.1-2010.3	RJ1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
R2	2003.12-2010.3	RC1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
AlcyoneSVX	1991.9-1996.12	CX#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Impreza	1992.11-1997.8	GC#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1997.9-2000.7		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2007.6-2011.11	GH#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps
ImprezaSEDAN	2000.8-2005.5	GD#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (Not applicable) Stop: T20 single (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2005.6-2007.5		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
Impreza Wagon	1992.11-2000.7	GF#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1996.9-2000.7		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Impreza sports wagon	2000.8-2007.5	GG#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	Unconfirmed	Unconfirmed	Unconfirmed	Unconfirmed	T10 2ケ (P145 ×1) (P141 ×1)	

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
ImprezaXV	2010.6-2012.2	GH#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps
Impreza Anesis	2008.10-2011.12	GE#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
Impreza WRX STI	2007.10-2014.8	GR#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps
	2010.7-2014.8	GV# 4doorSEDAN	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
ImprezaG4	2011.12-2016.10	GJ#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2016.10-	GK#	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible The tail position is T10 (No applicable products) and the stop is LED, so no applicable products.
Imprezasports	2011.12-2016.10	GP#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2016.10-	GT#	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible The tail position is T10 (No applicable products) and the stop is LED, so no applicable products.
Vivio	1992.3-1998.9	KK3.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Exiga	2008.6-2015.3	YA#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
Exiga crossover 7	2015.4-2018.3	YAM	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
XV XV hybrid	2013.6-2017.4	GP#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	hybrid ※1 Not applicable for LED lamps The tail position is T10 (No applicable products) and the stop is LED, so no applicable products.
XV XV hybrid	2017.5-	GT#	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10 (No applicable products) and the stop is LED, so no applicable products.
Sambar (Dias)	1990.3-1999.11	KV3.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1999.2-2001.4	TV1.2 TW1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2001.5-2002.8		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2002.9-2012.3		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
sambar truck ※Continue to next page	1990.3-1999.11	KS3.4	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1999.2-2001.4	TT1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2001.5-2002.8		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2002.9-2012.3		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
sambar truck	2014.9-2017.10	S500J S510J	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※1 T20 double (P615+P613 1 each)	S25 1ケ (P625 ×1)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2017.11-2021.12		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	G18 1ケ (P211 ×1)	halogen headlamp car ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
sambar truck	2017.11-2021.12	S500J S510J	※1 LED	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※2 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	G18 1ケ (P211 ×1)	led headlamp car ※1 Not applicable for LED lamps ※2 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2022.1-		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	halogen headlamp car ※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	led headlamp carは ※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
chiffon	2013.12-2019.7	LA600.610F	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	halogen headlamp car ※1 Not applicable for LED lamps
			※1 LED	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	led headlamp carは ※1 Not applicable for LED lamps
	2019.7-	LA650.660F	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps
Justy ※Continue to next page	2016.11-2020.8	M900.910F	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
Justy	2020.9-	M900.910F	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Stella Stella custom	2006.6-2011.4	RN1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2011.5-2014.12	LA100.110F	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2013.1-2014.12	LA100.110F	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	custom ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2014.12-	LA150.160F	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	custom ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
WRX STI	2014.8-2020.4	VAB	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
WRX S4	2014.8-2021.3	VAG	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2021.11-	VBH	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp
dias wagon	2009.9-2020.4	S321.331N	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1)	※1 Not applicable as led headlamp car is LED. ※2 Tail stop is not applicable because the polarity is not compatible ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
DEX（dex）	2008.11-2012.11	M401F M411F	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Domingo	1994.6-1999.2	FA7.8	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Travic	2001.8-1993.6	XM182.220	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10×37 (No applicable products)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2003.7-2004.12		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10×37 (No applicable products)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Tresia	2010.11-2016.3	NSP.NCP12#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
BRZ	2012.3-2016.6	ZC6	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 1ケ (P623 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2016.7-2021.3		※1 LED	※1 LED	※1 LED	※1 LED	T16 1ケ (P623 ×1)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2021.8-	ZD8	※1 LED	※1 LED	※1 LED	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp
forester ※Continue to next page	1997.2-1999.12	SF5.9	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2000.1-2002.1		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2002.2-2007.11	SG5.9	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
forester	2007.12-2012.11	S1993.9 SHJ	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2012.11-2018.7	SJ5 SJG	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	halogen headlamp car ※1 Tail stop is not applicable because the polarity is not compatible
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	HID headlamp car ※1 Tail stop is not applicable because the polarity is not compatible
	2015.10-2018.7	SJ5 SJG	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	halogen headlamp car ※1 Not applicable due to LED lamp
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	HID headlamp car ※1 Not applicable due to LED lamp
	2018.7-2021.8	SK5.9 SKE	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable as led headlamp car is LED.
	2021.9-	SK5.SKE	※1 LED	※1 LED	※2 T20 2ケ (Not applicable)	※1 LED	T16 2ケ (P623 ×2)	※1 LED	※1 Not applicable due to LED lamp ※2 Not applicable to cars equipped with EyeSight X as it may cause malfunction or breakdown.
Pleo	1998.10-2000.9	RA1.2 RV1.2	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2000.10-2010.3		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2010.4-2018.3	L275B.F L285B.F	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
Pleo custom	2010.4-2013.2	L275.285F	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Pleo Plus	2012.12-2017.5	LA300.310F	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2017.5-	LA350.360F	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable as led headlamp car is LED. ※2 Not applicable due to LED lamp
Lukla	2010.4-2015.5	L455.465F	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
Lukla custom	2010.4-2015.5	L455.465F	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
Levorg	2014.10-2020.10	VM4.VMG	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable as led headlamp car is LED. ※2 Not applicable due to LED lamp
	2020.10-	VN5.VNH	※1 LED	※1 LED	※2 T20 2ケ (※Not applicable)	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp ※2 Not applicable to cars equipped with EyeSight X as it may cause malfunction or breakdown.
Levorg Ray back	2023.11-	VN5	※1 LED	※1 LED	※2 T20 2ケ (※Not applicable)	※1 LED	※1 LED	※1 LED	※1 Not applicable due to LED lamp ※2 Not applicable to cars equipped with EyeSight X as it may cause malfunction or breakdown.
leone van	1999.6-2005.10	Y11	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1.2 T20 double 2ケ (P615 ×1)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. socket end Not applicable if child is not +, −, +, − *2 Symptoms such as a burnout warning light on the meter panel or an abnormal light on the high mount may be observed. In such cases, connect the P613 resistance unit to the main harness (stop) and to

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

SUBARU			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
Legacy	1993.10-1998.11	BD#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Legacy B4	1998.12-2001.4	BE#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	2 headlamp car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1998.12-2001.4		Integrated with cornering (No applicable products)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	4 headlamp car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2001.5-2003.5		Integrated with cornering (No applicable products)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2003.6-2009.4	BL#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2009.5-2014.10	BM9 BMM.BMG	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2014.10-2020.8	BN9	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
legacy touring wagon ※Continue to next page	1993.10-1998.5	BG#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1998.6-2001.4	BH#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	2 headlamp car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
			Integrated with cornering (No applicable products)	S25 2ケ (P622 ×1)	S25 2ケ (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	4 headlamp car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2001.5-2003.5		Integrated with cornering (No applicable products)	T20 2ケ (P621 ×1)	S25 2ケ (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUBARU			side light	blinker		Stop and Tail	back	license	remarks
Car model	model year	model		front	rear				
legacy touring wagon	2003.5-2009.4	BP#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2009.5-2014.10	BR9 BRM.BRG	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20single (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
legacy out back	2003.10-2009.5	BP#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2009.5-2014.10	BR#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	T20single (No applicable products)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
legacy out back	2014.10-2021.3	BS9	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2021.12-	BT5	※1 LED	※1 LED	※2 T20 2ケ (Not applicable)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Not applicable to cars equipped with EyeSight X as it may cause malfunction or breakdown.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
alto Alto Works	1994.11-1997.3	HA.HB.HC11#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T16 2ケ (No applicable products)	T16 2ケ (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T13 (No compatible products)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1997.4-1998.9	HA11#.21#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
		HA11#.21# ワークス	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T16 2ケ (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	1998.10-2004.8	HA12#.22#.23#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
		HA12#.22#.23# クラシック	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2004.9-2009.11	HA24#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2009.12-2014.12	HA25#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2014.12-2021.12	HA36#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2021.12-	HA97S.37S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1)	led headlamp car ※1 Not applicable due to LED lamp ※2 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
alto eco	2011.12-2014.12	HA35S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
alto lapin	2002.1-2003.12	HE21S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2004.1-2008.10		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2008.11-2015.6	HE22S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2013.6-2015.5		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	chocolate ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2015.6-	HE33S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	HID headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
alto lapinSS	2002.1-2003.12	HE21S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	SS ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2004.1-2008.10		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	SS ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +-+-. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Ignis	2016.2-	FF21S	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
SX4	2006.7-2014.11	YA.YB#1S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
SX4SEDAN	2007.7-2014.11	YC11S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
Escudo	1988.5-1997.10	TA#1W TD#1W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1997.11-2001.10	TA#2W.TL52W TD#2W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2001.11-2005.4		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2005.5-2008.5	TD#4W TDA4W.B4W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2008.6-2017.4		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2006.6-2017.4	TA74W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2015.10-	YD.YE#1S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
X90	1995.10-1997.12	LB11S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Every ※Continue to next page	1990.3-1998.12	DA.DB41#.51#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1999.1-2005.7	DA.DB52#.62#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 pin angle difference (P622 ×1)	※2 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not compatible with vehicles equipped with S25single, only applicable products with different pin angles. ※2 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Every	2005.8-2015.1	DA64W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 T20 double (P615+P613 1 each)	S25 2ケ (P625 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
		DA64W ジョイン	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
		DA64V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 T20 double (P615+P613 1 each) GAはS25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2015.2-	DA17W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.Please check as it is set as a standard equipped vehicle with LED. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	HID headlamp car ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.Please check as it is set as a standard equipped vehicle with LED. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
		DA17V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Every Plus	1999.6-2001.5	DA32W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
every randy	2001.5-2005.7	DA32W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
MR wagon	2001.12-2005.12	MF21S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2006.1-2010.12	MF22S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2011.1-2016.3	MF33S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
MR wagon sports	2002.6-2005.12	MF21S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Elio	2001.1-2004.6	RB21S RD51S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2004.7-2006.5		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Elio SEDAN	2001.11-2007.3	RA21S RC51S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
cappuccino	1991.11-1997.12	EA11.21R	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T13 (No compatible products)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Cultus	1998.5-1999.8	GA11.31S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	S25single (No applicable products)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	
cultus crescent SEDAN	1995.1-1998.4	GC.GD21S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each) テール:S25single (No applicable products)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Cultus SEDAN	1998.5-2001.11	GC.GD21S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each) テール:S25single (No applicable products)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
cultus crescent wagon	1996.2-1998.4	GC21.41W GD31W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
cultus wagon	1998.5-2002.8	GC21.41W GD31W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
character	1993.1-1995.12	PG6SS	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
carry	1999.1-2005.7	DA.DB52#.62#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	※2 T10 1ケ (No applicable products)	※3 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2The back valve is T10 (8W) so no applicable products ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2005.8-2013.7	DA63.65T	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 S25 double (P616+P613 1 each)	※2 T10 1ケ (No applicable products)	※3 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2The back valve is T10 (8W) so no applicable products ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2013.8-	DA16T	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 1ケ (P623 ×1)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Kizashi	2009.10-2015.11	RE91S.RF91S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10×37 (No compatible products)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
grand escudo	2000.12-2001.9	TX92W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−.
	2001.10-2003.5		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−.
	2003.6-2005.4		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
cross bee	2017.12-	MN71S	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Kei	1998.10-2009.10	HN11.12S HN21.22S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
chevrolet cruze	2000.12-2003.10	HR51S.52#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2003.11-2008.7		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
chevrolet MV	2006.1-2010.12	ME34S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	Unconfirmed	Unconfirmed	Unconfirmed	Unconfirmed	※1 T10 (No compatible products)	※1 Unsuitable due to light distribution issues
jimny	1995.11-1998.9	JA12#.22#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1998.10-2001.12	JB23W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2002.1-2005.9		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T13 2ケ (No applicable products)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2005.10-2018.7		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2018.7-	JB64W	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
jimny sierra	1993.5-1995.10	JB31W	G18 2ケ (P211 ×2)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1995.11-1997.12	JB32W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2002.1-2018.7	JB43W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2018.7-	JB74W	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
jimny wide	1998.1-2001.12	JB33W	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
swift ※Continue to next page	2000.2-2003.5	HT51#.81#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2003.6-2004.10		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
swift	2004.11-2010.8	ZC.ZD11#.21# 71#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2010.9-2017.1	ZC72.ZD72	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2) ※2 T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	halogen headlamp car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 RSgrade is T16 type
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2) ※2 T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	HID headlamp car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 RSgrade is T16 type

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
swift	2017.1-	ZC.ZD#3S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	halogen headlamp car ※1 Not applicable due to LED lamp
			※1 LED	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	led headlamp car ※1 Not applicable due to LED lamp
swift sports	2005.9-2010.9	ZC31S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2011.12-2016.12	ZC32S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	halogen headlamp car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	HID headlamp car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2017.9-	ZC33S	※1 LED	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	led headlamp car ※1 Not applicable due to LED lamp
splash	2008.10-2012.4	XB32S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
spacia (custom、customZ、GEAR)	2013.3-2017.12	MK32.42S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2017.12-2023.10	MK53S	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
spacia base	2022.8-	MK33S	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
spacia	2023.11-	MK94S	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2023.11-	MK54S MK94S	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	custom ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Cervo	2006.11-2009.12	HG21S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Cervo mode	1990.7-1995.9	CN#.CP#	T8.5 2ケ (No applicable products)	T16 2ケ (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T13 2ケ (No applicable products)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1995.10-1998.9		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T16 2ケ (No applicable products)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T13 2ケ (No applicable products)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Solio Solio vandit ※Continue to next page	2005.8-2011.1	MA34S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 (No compatible products)	halogen headlamp car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Unsuitable due to light distribution issues
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 (No compatible products)	halogen headlamp car round tail ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−. ※2 Unsuitable due to light distribution issues
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 (No compatible products)	HID headlamp car round tail ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−. ※2 Unsuitable due to light distribution issues
	2011.1-2015.8	MA15S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2013.11-2015.9		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	van dit ※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences, cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Solio Solio vandit	2015.8-2020.11	MA26.36.46S	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2020.12-	MA27.37S	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
twin	2003.1-2005.8	EC22S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
hustler	2014.1-2019.12	MR31.41S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car ※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	HID headlamp car、Jスタイル ※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2020.1～	MR92.52S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car ※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	led headlamp car ※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
palette	2008.1-2013.2	MK21S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
palette SW	2009.9-2013.2	MK21S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
randy	2007.1-2010.12	SC25.SNC25	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	2010.12-2016.8	SC26.SNC26 SHC26	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
randy	2016.12-	SC27.SGC27 SGNC27	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	ASSY (Not replaceable)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp
Wagon R ※Continue to next page	1993.9-1998.9	CT.CV#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T16 2ケ (No applicable products)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T13 2ケ (No applicable products)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−.
	1998.10-2001.10	MC#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2001.11-2003.8	MC#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	4-lamp halogen/HID lamp vehicle ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2003.9-2005.8	MH#1S.22S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	HID headlamp car ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2005.9-2008.8		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2008.9-2012.8	MH23S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Wagon R	2012.9-2017.1	MH34.44S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2017.2-2019.12	MH35.55S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	led headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2020.1-	MH85.95S	※1 T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 LED headlamp car uses blue light bulbs. ※2 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Wagon R Stingray	2007.2-2008.8	MH21S.22S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2008.9-2012.8	MH23S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2012.9-2017.1	MH34.44S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2017.2-2019.12	MH35.55S	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2020.1-	MH55.95S	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Wagon R Smile	2021.9-	MX81.91S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	led headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

SUZUKI			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Wagon R RR	1998.10-2003.8	MC#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2003.9-2008.8	MH21S.22S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 S25 double (P616+P613 1 each) ※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car ※1 Check the vehicle side polarity. For S25 double, Not applicable if the bottom terminal of the socket is not + and the side terminal is not −. For T20 double, Not applicable if the terminal polarity is not +− +−. ※2 Only 1 valve is used. It comes in 2
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 2ケ (P621 ×1)	※1 S25 double (P616+P613 1 each) ※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	HID headlamp car ※1 Check the vehicle side polarity. For S25 double, Not applicable if the bottom terminal of the socket is not + and the side terminal is not −. For T20 double, Not applicable if the terminal polarity is not +− +−. ※2 Only 1 valve is used. It comes in 2
Wagon R wide	1997.2-1999.4	MA.MB61S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
wagon R plus	1999.5-2000.11	MA63S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Wagon R Solio	2000.12-2005.7	MA64S.MA34S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2002.6-2005.7		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1)	HID headlamp car ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car round tail ※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +− +−. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
atrai	1994.1-1998.12	S12#.13#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1999.1-2005.4	S22#.23#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2001.1-2005.4		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2022.1-	S700.710V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	led headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
atrai wagon	2005.5-2007.8	S32#G.33#G	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2007.9-2017.10		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2017.11-2021.12		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	halogen headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	led headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Atrai 7 (Seven)	2000.7-2004.12	S22#.23#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU

Car model	model year	model	side light	blinker front	blinker rear	stop & tail	back	license	remarks
Applause	1989.7-1997.8	A10#.11#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1997.9-2000.3		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Altis	2000.3-2001.8	SXV2#N	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
	2001.9-2004.6	ACV3#N	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
	2004.7-2005.12		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each) Stop: T20 single (No applicable products)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
	2006.1-2010.2	ACV4#N	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
	2012.5-2014.7	AVV50N	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (P615+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the terminal polarity is not +−+−. The tail position is T10, but there is no applicable product.
	2014.8-2017.6		※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2017.7-	AXVH70.75N	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	※1 LED	Ggrade ※1 Not applicable due to LED lamp

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

DAIHATSU			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
wake	2014.11-2016.4	LA700.710S	※1 LED	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2016.5-		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	halogen headlamp car ※1 Not applicable due to LED lamp
			※1 LED	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	led headlamp car ※1 Not applicable due to LED lamp
esse	2005.12-2011.9	L23#.24#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Opti	1992.1-1998.10	L30#.31#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1996.5-1998.10	L30#.31# クラシック	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1998.11-2002.8	L80#.81#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2000.3-2002.8		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
cast	2015.9-	LA250.260S	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps
Coo	2006.5-2013.1	M40#.41#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－: Indicates that there is no vehicle setting and our product is not applicable.
×: This indicates that our product is not compatible.

DAIHATSU			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Copen	2002.6-2012.9	L880K	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 S25 double (P616+P613 1 each)	T20 2ケ (P624 ×2)	T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2014.6-	LA400K	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T20 2ケ (P624 ×2)	T10 1ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
charade	1993.1-2000.5	G20#.21#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
		G20#.21#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	1.5L car ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Storia	1998.2-2000.4	M10#.11#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2000.5-2001.11		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2001.12-2004.6		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
Sonica	2006.6-2009.5	L40#.41#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
tuft	2020.6-	LA900.910S	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 1ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Tanto ※Continue to next page	2003.11-2005.5	L350.360S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
		L350,360S サンルーフ付	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Tanto	2005.6-2007.11	L350.360S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2007.12-2013.10	L375.385S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2013.10-2019.7	LA600,610S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps
	2019.7-2022.9	LA650,660S	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps
	2022.10-	LA650,660S	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Tanto custom	2003.11-2005.5	L350.360S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
		L350,360S サンルーフ付	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2005.6-2007.11	L350.360S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2007.12-2013.10	L375.385S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2013.10-2019.7	LA600,610S	※1 LED	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps
	2019.7-2022.9	LA650,660S	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Tanto custom	2022.10-	LA650,660S	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Tanto Exe	2009.12-2011.12	L455,465S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	overhead console ※1 Tail stop is not applicable because the polarity is not compatible
	2011.12-2014.10		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	overhead console ※1 Not applicable for LED lamps
Tanto Exe custom	2009.12-2011.11	L455,465S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	overhead console ※1 Tail stop is not applicable because the polarity is not compatible
	2011.12-2014.10		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	※1 Not applicable for LED lamps
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1)	overhead console ※1 Not applicable for LED lamps
Terios	1997.4-2000.4	J100G	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2000.5-2006.1	J10#.12#G	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU

Car model	model year	model	side light	blinker front	blinker rear	stop & tail	back	license	remarks
terio kid ※Continue to next page	1998.10-2012.4	J11#.13#G	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
terio kid	2000.11-2012.4	J11#.13#G	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
terio kid custom	2006.8-2012.4	J11#.13#G	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Teriosulkia	2002.1-2003.8	J11#.13#G	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	G18 1ケ (P211 ×1)	Vehicle with rear tires ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
delta wide wagon	1992.1-1998.10	CB.YB2#.3#G	Integrated with cornering (No applicable products)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
delta wagon	1996.11-2001.5	CR.SR4#.5#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
delta van	1996.11-2001.5	CR.KR4#.5#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
Thor	2016.11-2020.8	M900.910S	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1)	※1 Not applicable for LED lamps ※2 Not applicable due to LED lamp ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Thor	2020.9-	M900.910S	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 led headlamp carはNot applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
naked	1999.11-2001.12	L750.760S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2002.1-2003.11		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
			T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	F.turboG ※1 Tail stop is not applicable because the polarity is not compatible
pizer	1996.8-1997.8	G30#.G31#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is -.
	1997.9-1998.6		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is -.
	1998.7-2002.8		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is -.
hijet van	1996.1-1998.12	S100.110V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is -.
highjet cargo	1999.1-2004.11	S200.210V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is -.
※Continue to next page	2004.12-2007.12	S320.330V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU

Car model	model year	model	side light	blinker front	blinker rear	stop & tail	back	license	remarks
highjet cargo	2007.12-2017.11	S321,331V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
highjet cargo	2017.11-2021.12	S321,331V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
highjet cargo	2022.1-	S700.710V	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
highjet cargo	2022.1-	S700.710W	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	led headlamp car ※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Hijet Pick	1996.1-1998.12	S10#.11#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
highjet truck ※Continue to next page	1999.1-2004.11	S200,210P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
highjet truck ※Continue to next page	2004.12-2014.8	S201,211P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
highjet truck ※Continue to next page	2014.9-2017.10	S500,510P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※1 T20 double (Not applicable)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
highjet truck ※Continue to next page	2017.11-2018.4	S500,510P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	G18 1ケ (P211 ×1)	halogen headlamp car ※1 Tail stop is not applicable because the polarity is not compatible
highjet truck ※Continue to next page	2017.11-2018.4	S500,510P	※1 LED	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※2 T20 double (Not applicable)	T16 2ケ (P623 ×2)	G18 1ケ (P211 ×1)	led headlamp car ※1 Not applicable due to LED lamp ※2 Tail stop is not applicable because the polarity is not compatible

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
highjet truck	2018.5-2018.7	S500,510P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	G18 1ケ (P211 ×1)	halogen headlamp car ※1 Tail stop is not applicable because the polarity is not compatible
			※1 LED	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※2 T20 double (Not applicable)	T16 2ケ (P623 ×2)	G18 1ケ (P211 ×1)	led headlamp car ※1 Not applicable due to LED lamp ※2 Tail stop is not applicable because the polarity is not compatible
	2018.8-	S500,510P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T16 2ケ (No applicable products)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	halogen headlamp car ※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
			※1 LED	T20 2ケ (P621 ×1)	T16 2ケ (No applicable products)	※2 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1)	led headlamp car,jumbo ※1 Not applicable due to LED lamp ※2 Tail stop is not applicable because the polarity is not compatible ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Bigo	2006.1-2016.3	J200.210G	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Boon	2004.6-2010.1	M30#.31#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2010.2-2016.4	M60#.61#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp
	2016.4-	M700,710S	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable as led headlamp car is LED. ※2 Not applicable due to LED lamp
Boon custom	2004.12-2010.1	M30#.31#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
boon luminous	2008.12-2012.3	M502.512G	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
MAX	2001.11-2005.11	L95#.96#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
midget Ⅱ	1996.4-2001.7	K100P	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Mira ※Continue to next page	1990.3-1994.8	L200.210S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
Mira	1994.9-1997.4	L50#.51#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 parallel pin (No applicable products)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1997.5-1998.9		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1995.10-1997.4		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	CR.TR.TR-XX.moderno ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1997.5-1998.9		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	CR.TR.TR-XX.moderno ※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1998.10-2000.9	L70#.71#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2000.10-2002.11		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2002.12-2006.11	L25#.26#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2006.12-2018.3	L27#.28#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
miraavi	2002.12-2006.11	L25#.26#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
mira e:s	2011.9-2017.5	LA300S.310S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2017.5-	LA350S.360S	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※2 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable as led headlamp car is LED. ※2 Not applicable due to LED lamp
mira custom	2006.12-2013.2	L27#.28#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
mira cocoa	2009.8-2014.7	L67#.68#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2012.4-2014.7		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2014.8-2018.3		※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※2 LED	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1)	※1 Not applicable as led headlamp car is LED. ※2 Not applicable due to LED lamp ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Miragino	1999.3-2004.10	L70#.71#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2004.11-2005.12	L65#.66#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2005.12-2009.4		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
Miragino1000	2002.8-2004.11	L70#.71#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
miratkot	2018.6-	LA550.560S	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
Move	1995.8-1997.4	L60#.61#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1997.5-1998.9		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	G18 1ケ (P211 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	1998.10-2000.9	L90#.91#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 parallel pin (No applicable products)	※1 S25 double (P616+P613 1 each)	S25 2ケ (P625 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2000.10-2002.9		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2002.10-2006.9	L15#.16#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2006.10-2010.11	L17#.18#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2010.12-2014.12	LA100S.110S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2014.12-	LA150.160S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Move custom ※Continue to next page	1998.10-2000.9	L90#.91#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T20 2ケ (P624 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −.
	2000.10-2002.9		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible
	2002.10-2006.9	L15#.16#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU

Car model	model year	model	side light	blinker front	blinker rear	stop & tail	back	license	remarks
Move custom	2006.10-2008.11	L17#.18#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2008.12-2010.11		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2010.12-2012.11	LA100S.110S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2012.12-2014.12		T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
	2014.12-	LA150.160S	※1 LED	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
move canvas	2016.9-2022.6	LA800.810S	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※2 LED	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Not applicable as led headlamp car is LED. ※2 Not applicable due to LED lamp
	2022.7-	LA850.860S	※1 LED orT10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	※1 LED or T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※2 LED	T16 2ケ (P623 ×2)	※3 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable as led headlamp car is LED. ※2 Not applicable due to LED lamp ※3 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Move Conte	2008.8-2017.3	L57#.58#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
Move Conte custom	2008.8-2017.3	L57#.58#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	S25 pin angle difference (P622 ×1)	※1 S25 double (P616+P613 1 each)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Check the vehicle side polarity. Not applicable if the lower terminal of the socket is not + and the side terminal is −. ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
move latte	2004.8-2009.4	L55#.56#S	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	T20 2ケ (P621 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1)	※1 Tail stop is not applicable because the polarity is not compatible ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.

●The information listed in the application table of this book is the bulb specifications of genuine lighting equipment, and cannot be installed on aftermarket lighting equipment.
●Even the vehicle models listed in the application table may not necessarily be compatible due to individual vehicle differences,
cold region specifications, grade, model year, manufacturer specification changes (unannounced improvements), etc. Please be sure to check the actual vehicle.
●It cannot be installed on vehicle models not listed
in the application table or in locations other than those specified
●It cannot be installed on imported cars.

■How to read each applicable notation
Upper row: Displays the genuine valve shape and number of installed pieces.
Lower tier: Displays our recommended product number and required number of sets.
※If there are multiple recommended products, they will be displayed in two columns.

■Application table How to read each mark
※: Indicates that there is a note in the notes column.
－ : Indicates that there is no vehicle setting and our product is not applicable.
× : This indicates that our product is not compatible.

DAIHATSU			side light	blinker		stop & tail	back	license	remarks
Car model	model year	model		front	rear				
rocky	2019.11-	A200.210S	※1 LED	※1 LED	T20 2ケ (P621 ×1)	※1 LED	T16 2ケ (P623 ×2)	※2 T10 1ケ (P145 ×1) (P141 ×1)	※1 Not applicable due to LED lamp ※2 Only 1 valve is used. It comes in 2 pieces, so you have 1 left.
YRV	2000.8-2005.7	M20#.21#	T10 2ケ (P145 ×1) (P144 ×1) (P141 ×1) (P142 ×1)	S25 pin angle difference (P622 ×1)	T20 2ケ (P621 ×1)	※1 T20 double (Not applicable)	T16 2ケ (P623 ×2)	T10 2ケ (P145 ×1) (P141 ×1)	※1 Tail stop is not applicable because the polarity is not compatible